

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

163

James W. Byron, Co. Surveyor  
John M. Powell & Crew  
February, 1969  
C. S. File No. 54/79 M 37 - 20

Prorated  $\frac{1}{4}$  Corner to Sec. 19, T29-5 and Sec. 24, T29-6W.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1969  
R T 29 S R  
6  $\frac{1}{4}$  #189 5  
W S 24 S 19 W

New BT's: 10" D. Fir S. 87° W. 21.3 ft. mkd:  $\frac{1}{4}$  S24 CS BT.

7" Oak N. 82° E. 16.1 ft. mkd:  $\frac{1}{4}$  S19 CS BT.

Note - North-South Fence line bears East 13.0 ft.

Corner 119.0 ft. south of Boomer Hill Road.

164

$\frac{1}{4}$  Corner to Sec. 30, T29-5W. and Sec. 25, T29-6W.

Pro-rated  $\frac{1}{4}$  Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1969  
R T 29 S R  
6  $\frac{1}{4}$  #186 5  
W S 25 S 30 W

New BT's: 22" D. Fir S. 79° E. 5.5 ft. mkd:  $\frac{1}{4}$  S30 CS BT.

12" D. Fir N. 83° W. 32.9 ft. mkd:  $\frac{1}{4}$  S25 CS BT.

Note - This corner lies approx. 16.0 ft. west of N - S fence line and 24.0 ft. north of small stream.

165

Section Corner to Sections 10 - 11 - 14 - 15.

Found - 1961 County Surveyor's Brass Cap, See Plan. #113.

20" D. Fir, now stub, N. 11° W. 108.8 ft., burnt scribe visible.

15" D. Fir, now stump, N. 69° E. 25.1 ft.

Set - 6 ft. steel fence post alongside Brass Cap 5 ft. above ground.

New BT: 11" D. Fir N. 10° W. 130.5 ft. scribed T29S R5W S10 CS BT.

This corner lies 2.0 ft. west of N-S fence line. No other trees available.

166

$\frac{1}{4}$  Corner to Sections 10 and 11.

Set from survey at prorated distance.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969  
T 29 S R 5 W  
 $\frac{1}{4}$  S 10 S 11

New BT's: 10" W. Oak N. 22° W. 43.2 ft. mkd: " $\frac{1}{4}$  S10 CS BT".

5" B. Oak N. 8° E. 27.6 ft. mkd: " $\frac{1}{4}$  S11 CS BT".

167

$\frac{1}{4}$  Corner to Section 26 and Section 35.

This corner set from survey at prorated distance.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1969  
T 29 S R 5 W  
 $\frac{1}{4}$  S 26 S 35

New BT's: 13" Maple S. 66° E. 110.6 ft. mkd: " $\frac{1}{4}$  S35 CS BT".

13" D. Fir N. 45° W. 84.2 ft. mkd: " $\frac{1}{4}$  S26 CS BT".

168

Section Corner to Sections 25 - 26 - 35 - 36.

Found - B. L. M. Brass Cap properly marked in 1957.

9" Fir, now 10" N. 72° E. 49.5 ft., pitched over scribe visible.

11" Fir, now 11", S. 23° E. 35.0 ft., pitched over scribe visible.

8" Laurel, now 9", N. 7° W. 48.8 ft., scribing visible, mostly grown over/

9" Fir, now snag, S. 76 $\frac{1}{2}$ ° W. 40.9 ft., pitched over, scribe visible.

New BT: 10" Laurel S. 33 $\frac{1}{2}$ ° W. 66.6 ft. mkd: "T29S R5W S35 CS BT".

This corner lies on top of large ridge, running north.

169

Center  $\frac{1}{4}$  Corner to Section 35.

This corner set from survey at pro-rated distance.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1969  
T 29 S R 5 W  
C  $\frac{1}{4}$  S35

New BT's: 13" Laurel N. 13 $\frac{1}{2}$ ° W. 14.4 ft. mkd: "C  $\frac{1}{4}$  S35 CS BT".

7" D. Fir N. 63° E. 13.8 ft. mkd: "C  $\frac{1}{4}$  S35 CS BT".

James W. Byron, Co. Surv.  
John M. Powell, & Crew  
March, 1969  
C. S. File No. 54/81

James W. Byron, Co. Surveyor  
John M. Powell & Crew  
April, 1969  
C. S. 54/84 Map File M 37 - 44