

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29 T. S. R 5 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 97401

192

R. B. Kimberling  
F. C. Silagy  
Doug. County Surveyors Office  
Dec. 12, 1977  
C.S. 59/42

Section Corner for Secs. 30 and 31; and Secs. 25 & 36 of T.29-6  
Found - A 3/4" x 34" Galv. I.P. 25" in the ground. Ren. #148  
A 10" now 38" W. Fir bears S.60°W., 11.2 ft. with visible scribing "S31--S in opened blaze. (OBT).  
A 36" now 40" D. Fir bears S.73 1/4°E., 55.5 ft. (Rec. 54.1 ft.) with visible bark scribing "T29S R5W S31 CS" and carved "K" on NW face.  
A 36" now 34" D. Fir bears N.67 1/2°W., 42.2 ft. with visible bark scribing "T29S R6W S25 CS BT"  
A 6" now 8" W. Fir bears N.7°E., 15.5 ft. with a well healed double blaze. #220  
A 9" now 14" W. Fir bears S.78 1/2°E., (Rec. S.81°E.) 26.2 ft. with a well healed double blaze.  
Set - A 1" x 36" I.P. with brass cap set 5" above ground and marked: "Douglas County Surveyor" 1977  
Set 3/4" x 34" I.P. at north edge of brass cap, 24" in the ground.

RE-RENEWED, SEE CORNER NO. #220

T 29 S		R	
R	S 25   S 30	R	
6	S 36   S 31	5	
W		W	

No new accessories. Corner is south 1.2 ft. of an E-W fence, due west 64.2 ft. of a 30" Fir stump which is a fence corner, fence to north and E-W and the SW cor. of clearcut unit.

12/12/77

Jan 78

193

1/4 Corner for Sec. 31 and Sec. 36 of T29-6  
Set - At midpoint set 5/8" x 30" Iron rod and alum. cap.  
BT's - 7" Oak, S.40°W., 3.5 ft.  
9" Oak, S.58°E., 5.5 ft.  
Found - 3/4" I.P. S.48°W., 51.9 ft. Ren. #45

Section corner for Sec. 31; and sec. 36, T29-6, sec. 1, T30-6, Sec. 6, T30-5.  
Found - 3/4" I.P. and 4 BTs (all down) Ren. #47  
Set - 5/8" x 30" Iron rod and alum. cap in I.P.  
New BT's - 6" Pine, N.4 1/2°W., 50.0 ft.  
8" Pine, N.67°E., 3.6 ft.  
12" Pine, S.85°W., 31.3 ft.  
8" Pine, S.29°E., 41.3 ft.

194

Howard Johnstone  
For: Roseburg  
Lumber Company  
April 1978  
R M 3 - 12

195

Center 1/4 Corner for Section 31  
Set - 5/8" x 30" Iron rod and alum. cap.  
BT's - 8" Fir, N.79°W., 7.6 ft.  
9" Oak S.34°W., 33.3 ft. See Ren. #30-A  
Found rock mound, S.68°W., 33.8 ft.

4/78

Section corner for Secs. 22, 23, 27 and 26.  
Found - A 1957 Cadastral brass cap properly marked. Ren. #2  
3/4" I.P. bears N.6°W., 3.08 ft. Ren. #2  
Orig. BT, a W. Oak 12" now 24" bears N.6°W., 231.5 ft. (Rec. 231.0)  
Single blaze has been previously opened to the heart of the tree.  
A W. Oak 18" bears N.58°E., 70.1 ft. to center of base (Rec. 69.6)  
Tree has well healed single blaze. Ren. #2  
A W. Oak 12" now 15" bears S.13°W., 100 ft. Tree has partially healed single blaze.  
A W. Oak 12 1/2" now 15" bears S.36°W., 51.4 ft. to center of base (Rec. S.37°W., 50.8 ft.) Tree has well healed single blaze.  
A W. Oak 15" now 18" bears N.15 1/2°W., 140.6 ft. Tree has well healed single blaze.

Fd. OK  
by G. GAUSS  
DEC. 1981  
RM 3-52

196

No new monument or accessories set.

10/5/78

Fwd. OK  
10-91 1992-0021  
H. ABRAHAM  
& J. ABRAHAM  
4/92  
M115-220

Larry Monrean  
P.L. Earle  
T.R. Plouff  
Doug. Co. Surveyors Office  
Oct. 5, 1978  
C.S. 60/17