

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 29    T. S.    R 5    R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

205

C O N T. - - - - -  
S. Flauser, Deputy  
S. Means Witness  
Doug. Co. Surveyors Off.  
Feb. 28, 1980  
C.S. 61/6

A 12" W. Oak, S.10°W., 36.0 ft.  
Also, we double blaze and scribe 1/4 S11 CS BT on a 6" B. Oak  
N.28°W., 24.6 ft.  
A 5/8" I.R. (property corner of Longhorn Ranches Subd.) bears  
S.87°E., 70.6 ft.  
The 5/8" I.R. marking position of 1961 Brass cap bears S.30°W., 3.0'

Oreg. St. Hwy.  
Kavres; L. Nunh  
V. Helmke  
Aug: 1970  
C.S. 60/6 (see

Section corner for Secs. 21, 22, 27 and 28.  
Found - Section corner axle. (N 10,415.58 E 10,948.01) Ren. #4 ~~72-A~~  
Re-set- With brass cap, Aug. 7, 1970. (Oreg. ST. Hwy F.B. #2268.  
See sketch in file #C.S. 60/6  
also Oreg. St. Hwy Map C.S. file M-1) *FD. CAP in Pavement 7/91 w Ruppert m 112-32*

206

William J. Ruppert  
LS #866  
For: Darrel Green  
May 1980  
M 83 - 65 A&B

1/4 Corner for Section 31 and Section 6, T.30S. R.5W. Ren. #12  
Fd- 1/2" x 48" Iron Pipe  
36" W. Oak bears North 40°30'E., 63.5 ft. good scar now dead.  
30" W. Oak bears S.72°16'E., 33.5 ft.  
Set - A 1" x 30" galvanized iron pipe with 2 1/2" brass cap at position  
of 1/2" pipe. Stamped brass cap: T29S S31 1/4 R5W PLS866 1980  
T30S S6  
Replaced 1/2" pipe along east side of Brass Cap.  
New BT- 16" W. Oak bears N.44°50'W., 95.65 ft. scribed 1/4 S31 BT. Attached brass washer LS 866 to lower blaze.

207

William J. Ruppert  
LS#866  
For: Michaels/Shirt-  
Cliff Assoc.  
Aug. 1980  
M 85 - 44

S.E. Corner of the Henry Adams D.L.C. #42 See Ren. #93  
Fd. - Orig. 36" rotted stump (possibly oak) bears N.53°47'W., 66.7 ft.  
15" W. Oak bears N.38°34'W., 83.0 ft. with good scar. See Ren. #  
93.  
19" B. Oak bears N.5°33'E., 65.0 ft. with good scar. See Ren. #  
93.  
Burned remains of corner post bears N.23°36'W., 6.5 ft.  
Down woven wire fence runs to North and to West from post.  
Set - 1" x 36" galvanized Iron pipe 24" into the ground with a 2 1/2"  
Brass Cap properly mkd.

208

*FD. B.C.  
7/91 w. RUPPERT  
m 112-32*

1/4 Corner to Secs. 33 and 34 Ren. #60 & 129  
Fd.- 1 3/4" Iron pipe and a "chilled" plow shear pointing up. Ren. #129.  
Parts of an old leather glove and parts of an old rotted post in  
in the ground near pipe.  
Set - 1" x 30" iron pipe set 24" into the ground with a 2 1/2" BRASS CAP  
attached properly mkd.  
Note - I buried pipe, plow shear, glove and other evidence in hole next to  
1" pipe. Fence corner bears East 2.0 ft.

209

William Ruppert  
For: Ron Kuehn  
October 1980  
M 84 - 58  
C.S. 58/143 (n)  
(See notation re:  
bearings)

NOTE: ROTATION ERROR OF 3° ON MAPS M 82 - 10 and M 81 - 29 AND CORRESPONDING  
ROTATION OF BEARING TREE BEARINGS.  
Section corner for Secs. 4, 5, 7 and 8  
Found - 1" Iron Pipe. See Renewals 211, 76 and 138  
18" Maple, S.79 1/2°E., 110.8 ft.  
24" Fir stump, S.20 3/4°E., 5.6 ft.  
28" Fir stump, S.15 1/2°W., 38.0 ft. Scar  
36" Madrone, N.33 3/4°W., 106.9 ft. scribe partly visible.

210

# 235

1/4 Corner for Sections 4 and 5.  
Found - 2 1/2" Brass cap. Ren. #201  
30" W. Oak, S.70°W., 60.0 ft. scar.  
23" W. Oak, S.36 1/4°W., 69.3 ft. Scar

211

Section Corner for Secs. 5 and 4; and 32 and 33 of T.28-5  
Found - 2 1/2" Brass cap. Ren. #200. Also see #152 and orig.  
28" W. Oak, S.76 3/4°W., 118.7 ft. Scar  
28" B. Oak, S.22 3/4°E., 146.9 ft. Scar  
36" B. Oak, S.65 3/4°W., 174.1 ft. Scar  
B. Oak, N.30 1/4°W., 69.0 ft. Scar

212