

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29

T. S.

R 5

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 9181

222

North 1/4 Corner for Sec. 4 only, T.30-5  
(Brass cap monument from Ren. #174 missing. Searched for, not found)  
Found - A 6" B. Oak now a 9" D.B.H. B. Oak with a fully healed  
single blaze, which is opened to reveal visible scribing  
"1/4" bears S.77 1/2° W., 4.5 ft. (per rec.)  
A 13" Laurel now a 15" D.B.H. Madrone with a fully healed  
single blaze which is opened to reveal visible illegible  
scribing bears S.80°E., 42.3 ft. (Rec. S.80°W., 42.3 ft.)  
Set - A distance-distance intersection from the found bearing  
trees indicates that bearing originally recorded to the  
laurel (madrone) was incorrect; this conclusion is cor-  
roborated by the bearing tree tag, found on the tree, which  
was marked in 1970 during Ren. #174, and which indicates  
a bearing of S.80°E. A new 2 3/8" dia. brass cap marked  
"Douglas County Surveyors T29S R5W 1/4 S4 T30S R5W  
1986 Office", on a 1 1/4" O.D. iron pipe, 32" long is set  
26" in the ground at the distance-distance intersection from  
the found bearing trees as explained above.  
New BT - A 9" D.B.H. Madrone double blazed and scribed "1/4 S4 CS BT"  
bears S.60 1/4° E., 76.4 ft.  
Note: Monument lies approx. 4 ft. North from an old east-west  
fence and approx. 550 ft. east from the paved end of Clark St.

Douglas County  
Surveyors Office  
Stephen Flause  
R. W. Smith  
Sept. 5, 1986  
C.S. 62/37

*Fd. B.C. 3/90  
1990-0027*

223

A POINT OF SURVEY DESIGNATED AS 1/4 S34 and S35 (per M 11 - 39)  
Found - 3/4" iron rod protruding 5 inches above ground. Ren. #98  
24" now 35" dia. Incense cedar with a partially healed double  
blaze "4" and partial scribing visible, "X" axed in bark  
above blazes, bears N.26 1/2°E., 32.8 ft. (agrees with record)  
18" now 30" dia. D. fir with a fully healed double blaze and  
"X" axed in bark above blazes, bears S.0 1/2°E., 30.4 ft. (rec.  
S.57°32'W., 30.4 ft.) Blazes face iron rod.  
(No original BTs found)  
3/4" iron rod set in 1955 by Gene Johnson, M 11 - 39, is a point of survey.  
Monument originally set as proportionate 1/4 cor. position between 34/35.  
Subsequent 1957 BLM resurvey shows position of section corner to south set  
in 1951 by John Markham (C.S. file #40/259) in error. 3/4" iron rod used  
as 1/4 cor. position in 1969 survey by Douglas County Surveyors office to  
subdivide sec. 35. (M 37 - 44)  
Corner lies on east slope approx 50 ft. west of small creek.

Douglas County  
Surveyors Office  
Randall W. Smith,  
Party Chief  
Stephen J. Flause,  
Notekeeper.  
William Spencer, Land  
owner, witness.  
Jan. 15, 1987  
C.S. 62/40

*Fd. & 2/Sec  
7/90  
M110-61*

1/15/87

224

Section Corner for Sections 33 and 34 only  
Found - A 1969 BLM 3 1/4" brass cap on a 2 1/2" dia. iron pipe protruding  
9" above ground (from 1969 BLM resurvey)  
1" dia. iron pipe from Ren. #67 not seen.  
10" B. oak now root hole bears N.45°E., 14.5 ft. (agrees with  
record) Orig. BT.  
10"B. Oak now root hole bears S.55°W., 6.0 ft. (agrees with  
Renewal No. 67 records) Orig. bT.  
16" now 30" dia. 4 ft. high D. fir stump with a fully healed  
single blaze, bears N.11°E., 14.6 ft. (Rec. N.11°E 14.0 ft.  
Ren. No. 67) and 15.2 ft. BLM Resurvey. Ren. No. 67  
8" Fir now root hole bears N.53°W., 14.0 ft. (agrees with Ren.  
BLM 1969 record N.53°E., 15.2 ft.) Ren. No. 67  
13" now 19" dia. 1 ft. high D. fir stump with a fully healed  
lower blaze, bears N.71 1/2°W., 32.1 ft. (Rec. N.71 1/2°W., 34.0 ft.  
distance is a slope measurement) From 1969 BLM resurvey.  
New BTS - 19" dia. 6 ft. high D. fir stump, a 1/2" square x 8 1/4" long iron  
boat spike with a 1 1/8" dia. head is set through a BT tag  
on top of stump, top of boat spike is stamped "B02 1989"  
Boat spike bears N.77 1/2°W., 6.9 ft.  
20" dia. 3 ft. high D. fir stump, a 1/2" square x 8 1/4" long iron  
boat spike with a 1 1/8" head is set through a bT tag on top  
of stump, top of boat spike is stamped "B01 1989". Boat spike  
bears N.47°E., 38.9 ft.  
Corner lies in a recent burn and clear cut. No live trees close.

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Sept. 22, 1989  
C.S. 64/1