

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21881

Mark Smalley L.S. #2354
For: Roseburg Forest Products Co.
July / Sept. 1993 M 119-2

1/4 Cor. Secs. 4 & 9
Set - 5/8"x48" IR & Aluminum cap marked "LS 2354"
New BTs -

20" Fir, S.50°W., 180.0', "1/4 S BT"
14" Alder, N.63°W., 27.1', "1/4 S BT". Bark scribe.
18" Cedar, N.12°W., 345.0', "1/4 S BT"
28" Cedar, North, 283.0', "1/4 S BT"

POSITION OF MARKHAM'S 1/4 CORNER BEARS N.18°06'21"W., 27.07' (REN # 137). No pipe was found, based on Markham's BTs.

236

Cor. Secs. 3, 4, 9, & 10

Set - 5/8"x48" Iron rod & Aluminum cap mkd: "LS 2354".
New BTs -

10" Fir, S.58°E., 12.4', "S 10 BT".
36" Fir, N.64°W., 15.0', "S 4 BT".
22" Cedar, N.68°E., 22.8', "S 3 BT".
30" Fir, N.2°W., 43.8', "S 4 BT".

MARKHAM'S IRON PIPE BEARS N.45°34'05"W., 24.14' (REN. # 62)

237

1/4 Cor. Secs. 3 & 10

Found - 1973 County Surveyor BCIP & 3/4" IP (Ren. # 181)

BTs - 30" Fir, N.70°W., 125.7', healed.
24" Fir, N.15°W., 88.7', healed.
12" Fir, S.2°E., 55.8', rotten stump.

THIS MONUMENT BEARS N.38°52'58"W., 12.24', FROM THE POSITION CALCULATED FOR THIS CORNER.

238

1/4 Cor. Secs. 8 & 9

Found - 1962 County Surveyor BCIP (Ren. # 141)

30" Oak, S.85°E., 54.1', healed OBT.
9" Oak, S.69°W., 5.9', healed.

New BTs -

11" Cedar, S.8°W., 16.6', "1/4 S8 BT"
8" Cedar, N.31°E., 19.0', "1/4 S9 BT"

239

C 1/4 Cor. Sec. 9

Set - 5/8"x48" Iron Rod & Aluminum Cap mkd: "LS 2354".

New BTs -

32" Cedar, S.11°E., 45.0', "C 1/4 S9 BT"
6" Pine, S.11°W., 47.3', "C 1/4 S9 BT"
15" Oak, N.72°W., 49.5', "C 1/4 S9 BT"
26" Fir, N.26°E., 62.9', "C 1/4 S9 BT"

240

1/4 Cor. Secs. 9|10

Set - 5/8"x48" Iron rod & aluminum cap mkd: "LS 2354"

New BTs -

21" Cedar, N.79°W., 15.2', "1/4 S9 BT"
16" Fir, N.50°E., "1/4 S10 BT" 24.0'
16" Cedar, S.25°E., 25.3', "1/4 S10 BT"
24" Fir, N.13°W., 46.4', "1/4 S9 BT"

WENDEROTH'S IRON PIPE BEARS N.25°09'03"W., 16.93' (Ren. # 101)

241

Cor. Secs. 8, 9, 16, & 17

Found - Stone with chiseled "+" on top & North (Ren. # 142).

25" Pine, N.11°E., 114.7', healed.
14" Fir, N.0 1/2°W., 111.0', healed.

New BTs -

8" Myrtle, S.74°W., 30.3', "S 17 BT".
8" Pine, N.25°W., 57.2', "S 8 BT".

Set steel fence post in mound of stones S.12°E., 13.0'.

242