

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

6

R. W. W. M.

J. W. Cole C.S.
E. Richardson chain
H. E. Bergh chain
February 2, 1923.
See F.B. 35 Pg. 18

N.E. CORNER OF A. G. WILLIS D.L.C. # 45.

34

Renewed corner from old rotten Oak Stake marked, C.S. CL. 45 from which stump of 30" Fir bears N.10°W., 25 lks. Marked B.T.S also

A Fir 14" marked C.S. CL. 45 B.T. N.49°30'W., 7 ft.

A Fir 14" marked C.S. CL. 45 B.T. S.41°00'W., 14.6 ft. #99

Both Firs look as though they had been marked approximately 5 years previous. Erected mound of rock around old stake. The $\frac{1}{2}$ corner between 16 and 21 bears East 430 ft. and South 121.4 ft.

C. W. Springer
D.C.S.
H.E. Bergh Chain
John Prowell
March 13, 1923.
J. D. and Edgar Walker cs 6/27
K. 3 Pg 140
F.B. 10
Pg 72

SECTION CORNER COMMON TO SECTIONS 5 and 6 T. 28-6 S. 31 and 32 T. 28-6.

35

Two original B.T.s standing, one badly rotted. Other two B.T.s down. I renew from the two good trees and the stumps of the other two. Drive an Iron Pipe $1\frac{1}{2}$ " x 48" in ground from which I marked four new trees as follows

A Fir 12" dia. bears S.31°50'W., 37.3 ft.

A Fir 10" dia. bears S.69°30'E., 24.0 ft.

A Fir 6" dia. bears N.22°00'E., 11.5 ft.

A Fir 24" dia. bears N.47°00'E., 34.3 ft. An Orig. B.T.

SEE CORNER NO. 145

C. W. Springer
C. Sherrill
John Prowell
Otto Parker
Ray Powell
J. D. and Edgar Walker cs 6/27
Mar. 31, 1923.
K. 3 Pg 140
F.B. 10
Pg 72

SECTION CORNER BETWEEN SECTIONS 5 and 6.

36

Replaced corner from original B.T.s, one in bad shape and other one fair. Drove an Iron Pipe $1\frac{1}{2}$ " x 40" in ground and marked two new B.T.s

A Fir 12" dia. N.59°40'W., 26.6 ft.

Black Oak 10" dia. N.24°00'E., 27.3 ft.

Both original B.T.s are in evidence at the time.

SEE CORNER NO. 196

C. W. Springer
J. H. Smich
E. Richardson
W. F. Iles
May 30, 1923
June 4, 1923

S.E. INTERIOR "L" CORNER OF W. R. WILLIS D.L.C. 44.

37

Replaced corner from one original B.T. standing with scribe marks rotted but still in evidence and evidence of the other tree at the proper course and distance. Tree gone though. Drove a steel shaft $1\frac{1}{2}$ " x 36" in ground and set an Oak Stake by it. Marked two new bearing trees as follows

Oak 10" dia. N.86°00'E., 60.4 ft.

Ash 8" dia. S.37°45'W., 15.2 ft.

CORNER BETWEEN SECTION 21 and 28.

38

I could find no trace of original corner. I renewed this corner on true section line one half way between section corners. I set an Iron Pipe one in. by third-six inches, 24 inches in the ground from which

Fir dia. N.12°W., 11.0 ft.

Laurel 36" dia. S.29 $\frac{1}{2}$ °W., 36.8 ft.

SEE CORNER NO. 170

CORNER BETWEEN SECTIONS 20 and 29.

39

I found a fir stake standing from which a Fir bearing tree corresponding with field notes of Surveyor Fred Mench. Could find no evidence of original trees or rock. Fir tree dead I marked new trees

Fir 20" dia. N.36°30'W., 48.0 ft.

Fir 14" dia. S. 8°15'E., 48.5 ft.

I set an Iron Pipe $1\frac{1}{2}$ " x 40". 30" in ground at corner.

RENEWED SEE CORNER NO. 160

CORNER BETWEEN SECTIONS 28 and 29.

40

I found no evidence of the original corner but placed the corner on the true section line $\frac{1}{2}$ way between section corners. The corner fell in creek on bed rock. I set an Iron Pipe $1\frac{1}{2}$ " x 36" and erected mound of rock around pipe from which I marked

Fir 48" dia. S.39°45'W., 20.5 ft.

Fir 48" dia. N.63°00'W., 39.7 ft.

RENEWED SEE CORNER NO. #254

March 1924
J. W. Coler County Surveyor
Wit.
M. B. Hawkins
Tog Rice