

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

6

R. W. W. M.

KOKS-CHAPMAN CO., EUGENE, ORE. 97196

James W. Byron, Deputy County Sur.
Ray Irving, John Fee.
November 22, 23, 1954
See C. S. File No. 46/63.

Section corner to secs. 12 and 13, T 29 S, R 6 W., and secs. 7 and 18, T 29 S, R 5 W. 109
Found: Original N. E. BT. Now down and rotted. Part of old blaze O. K., scribing T 29 W. visible. Orig. S. E. BT standing, center rotted. Shows old blaze. The NW and SW BTs gone.
Set 1 inch iron pipe with brass cap at corner using N. E. BT and S. E. BT. Cap marked T29S T29S
R6W 12 7 R5W County Surveyors Office
13 18 1954

Blazed and Scribbed:
10 inch W. O., N.74°W., 37.5 feet dist., mkd. T 29 S, R 6 W., S 12 CS BT.
14 in. W.O., S.6°W., 32.5 feet dist., mkd. T29S, R6W., S 13 CS BT.
10 in. W.O., N.21°E., 18.0 feet dist., mkd. T29S, R5W, S 7 CS BT.
12 in. W.O., S.89°E., 21.4 feet dist., mkd. T29S, R5W, S 18 CS BT.

Cole, Smick, Richardson, Taylor.
July 6, 8, 1921
See F. B. No. 51, Pages 42 - 46.
Work done for A. Taylor.

N. E. Corner of Donation Land Claim No. 47 (Harrison Rice DLC). 139
Found Stake in place from which original BT, A W. O., 40 inches in dia. bears N.40°E., 4.0 feet.
Piled rocks around stake and remarked tree.

S. W. Corner of the Harrison Rice Donation Land Claim No. 47. 111
Set Oak stake also, from which stump of 30 inch B. Oak bears S.75°E., 33.7 feet. A 24 inch W. Oak bearing chopped scars bears S.2°30'E., 71.3 feet.

Marked New Trees:
A W. Oak, 30 inches dia., bears S.40°E., 113.5 feet.
A W. Oak, 30 inches dia., bears S.79°E., 176.0 feet.
Set iron plow frame 15 inches below ground.

S. E. Corner of Donation Land Claim No. 47 (Harrison Rice DLC). 112
Set Oak stake, also iron pipe 1 1/2 dia. mkd. Cl. 47.
No live trees near. 138

C. C. Gall
Resident Engineer
State Hwy Dept.
Myrtle Creek, Ore.
March 11, 1955.
C. S. File 41/3461

Southeast corner of the James A. Clark D. L. C. No. 40. 113
This corner falls inside of the State Highway right of way. Marked by a 12" X 14" X 14" triangular rock. The corner was not disturbed. The corner lies 110.0 ft. northeasterly of the highway right of way centerline and 5 feet above the centerline of the pavement.
A 4" X 4" white wood guard post set by the corner and marked "D.L.C."
SEE RM 1-79
FD. 8/70 DON GARRETT COEE/159

Section corner to secs. 28, 29, 32, and 33. 114
Point for corner determined by O. B. T.s:
A 21 inch La. bears N.25°E., 29.0 feet dist. I remarked S 28 B. T.
A 30 inch Laurel bears S.26°E., 29.0 feet dist. - I rescribed S33 B. T.
A 20 inch Fir stump (logged) bears S.66°W., 43.0 feet dist.
A 14 inch chip bears N.44°W., 37.5 feet dist. Found old scribe in good condition.
At corner point found pile of stones and set 1/2 inch X 24 inch iron rod.
From which:
A 6 inch chip. bears S.86°W., 14.0 feet dist. mkd. S 32 B. T.

John H. Markham Jr.
Done for Stomar Lumber Co.
August and October, 1956.
C. S. File No. 42/190.

South section corner to sections 32 and 33. (only) 115
Point for corner determined by old B. T.s.
A 24 inch White Fir, bears N.43°E., 20.5 feet dist.
At corner point set a 1 1/2 inch x 35 inch truck axel with flange up. # 232
From which:
A 48 inch Fir, bears N.80°E., 107.0 feet dist. bark scribed S 32 B. T.
A 20 inch Cedar bears S.30°W., 101.5 feet dist. marked S 4 B. T. X
Corner lies in creek along East edge of old landing.
Sec. corner to 3 and 4 is West about 700 feet.
5 + 4