

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

$\frac{1}{4}$  corner to secs. 13 and 24.

128

Position of corner located by retracing the North line of Sec. 24.  $\frac{1}{4}$  corner set at midpoint on true line between section corners. - Cor. Ren # 85

Set an iron pipe with brass cap at corner point mkd.  $\frac{1}{4}$  cor 13/24 T29S, R6W, County Surveyors Office, 1957.

From which:

36 inch Cedar bears S.27°E., 12.3 feet scribed  $\frac{1}{4}$  S 24 CS BT.

40 inch Fir stump bears N.8°E., 24.2 feet scribed  $\frac{1}{4}$  S 13 CS BT.

SEE CORNER NO. 198

James W. Byron, Deputy County Surveyor  
June 24, 1957.  
C. S. File No. 47/195.

Section corner to secs. 13, 14, 23 and 24.

129

Found all BTs and  $1\frac{1}{2}$  inch iron pipe as recorded by Frear in 1919. All trees dead except 6 inch Fir (now 12 inches), S.58 $\frac{1}{2}$ °W., 9.3 feet which is alive and in good condition-I do not open. - Ren. # 11

Blaze and scribe new trees:

12 inch R. Fir, N.6°W., 15.8 feet scribed T29S, R6W, S 14 CS BT.

6 inch W. O., N.58 $\frac{1}{2}$ °E., 12.7 feet scribed T29S, R6W, S 13 CS BT.

6 inch R. Fir, S.57°E., 16.2 feet scribed S 24 CS BT.

$\frac{1}{4}$  corner to secs. 24 & 25.

130

Corner renewed by Markhams BTs as renewed in 1951-poor condition-bark scribed. - Ren. # 76

Set an iron pipe with brass cap marked County Surveyors Office, 1957, T29S R6W  $\frac{1}{4}$  S 24/25.

From which:

15 inch Fir, S.18 $\frac{1}{2}$ °W., 26.8 feet mkd.  $\frac{1}{4}$  S 25 CS BT.

10 inch Fir, N.56°E., 33.1 feet mkd.  $\frac{1}{4}$  S 24 CS BT.

SEE CORNER NO. 199

Section corner to secs. 7 & 18, T29S, R6W., and secs. 12 & 13, T29S, R7W.

131

Location of corner established by proportional measurement.

Set an 1 inch iron pipe for corner,

from which:

A Maple, 14 inches in diameter bearing N.77°30'E., a distance of 70.2 feet, scribed T 29 S, R 6 W, S 7 B.T.

A Maple, 16 inches in diameter bearing S.41°10'E., a distance of 86.8 feet scribed T 29 S, R 7 W, S 18 B.T.

A Fir, 14 inches in diameter bearing S.70°W., a distance of 125.0 feet scribed T 29 S, R 7 W, S 13 B.T.

No trees in Northwest quarter.

Clifford M. Bryden  
Surveyor for Roseburg Lumber Co.  
May 21, 1957  
M 5 - 41.

$\frac{1}{4}$  corner to sec. 18, T29S, R6W., and sec. 13, T29S, R7W.

132

Location of corner established by proportional measurement.

Set  $\frac{3}{4}$  inch iron pipe for  $\frac{1}{4}$  corner,

from which:

A Fir, 14 inches in diameter bears S.78°50'E., a distance of 36.6 feet, scribed  $\frac{1}{4}$  T 29 S, S 18 B.T.

A Fir, 12 inches in diameter bears S.62°W., a distance of 70.7 feet scribed  $\frac{1}{4}$  T 29 S, S 13 B.T.

$\frac{1}{4}$  corner to sec. 7, T29S, R6W., and sec. 12, T29S, R7W.

133

Found - Both original B.T.s: The 15 inch B. O., S.56°E., (now 36 inch snag) shows old face and short sections of reverse scribe marks found near rotted area. 4 inch Laurel, S.55°W. (now 18 inches) has been dozed out and is now laying 30 feet down hill-shows old rotted face and possible faint scribe marks.

Also found 2 fir stumps with good scribing, face to corner. A 12 inch Fir bears N.24 $\frac{1}{2}$ °W., 19.6 feet scribed  $\frac{1}{4}$  S 7 BT. A 12 inch Fir bears S.61°E., 12.8 feet with good scribing. These trees scribed by Art Boyer about 30 years ago states Geo. Voytilla. Not recorded. (See signed statement in file).

Set an iron pipe with brass cap at corner mkd.  $\frac{1}{4}$  S T29S | County Surveyors  
12 7 | Office, 1957.  
R7W R6W

from which:

10 inch R. Fir, N.61°W., 101.6 feet, mkd.  $\frac{1}{4}$  S T29S R7W, C. S. BT.

12 inch Laurel, S.80°W., feet, mkd.  $\frac{1}{4}$  S T29S R7W, C. S. BT.

James W. Byron, Deputy County Surveyor.  
June 7, 1957.  
C. S. File No. 47/194.