

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 4, 5, 8, & 9.

141

Found - $\frac{3}{4}$ " I. Bolt, See Page 10-A of notes in file.

Set 1" I.P. with Brass Cap marked $\frac{S5}{S8} \frac{4}{9}$ T29S R6W County Surveyor's Office, 1954.

Blazed & Scribed: 15" W.O. S. $19\frac{1}{2}^\circ$ W. 116.0 ft. S8 T29S R6W CS BT.
10" W.O. N. $21\frac{1}{2}^\circ$ E. 31.5 ft. S4 T29S R6W CS BT.
15" W.O. N. 85° W. 27.6 ft. S5 T29S R6W CS BT.
18" B.O. S. 68° E. 94.0 ft. S9 T29S R6W CS BT.

James W. Byron
R. Irving
J. Fee
Dec. 23, 1954
Filed 12/10/57
C.S. File No. 49/40

Section Corner to Sections 2, 3, 10, & 11.

142

Found - 3 of the original BTs. All check for bearing & distance.

The original N.W. BT. now 30" B.O. is alive. Shows old scar.

I do not open.

The original S.W. BT. now 36" Snag, shows old scar. I do not open.

The original 4" W.O. now 22" N. $73\frac{1}{2}^\circ$ E. 46.9 ft. I open & find good scribe "BT".

Set Brass Cap at Corner marked $\frac{S3}{S10} \frac{S2}{S11}$ T29S R6W County Surveyor's Office, 1957

(See Sketch in file for relation of Brass Cap to Fence Corner.)

New BTs: 8" W.O. bears N. 83° W. 34.0 ft. scribed T29S R6W S3 CS BT.
10" W.O. bears S. $35\frac{1}{2}^\circ$ W. 75.3 ft. scribed T29S R6W S10 CS BT.
6" B.O. bears S. 71° E. 63.8 ft. scribed T29S R6W S11 CS BT.
12" Laurel " N. 79° E. 9.0 ft. scribed T29S R6W S2 CS BT.

James W. Byron, Dep. Co. Surveyor
M. Godfrey
S. Bilow
Dec. 27, 1957
C.S. File No. 49/52

$\frac{1}{4}$ Section Corner to Sections 25 & 26. as det by O.B.T.'s.

143

24" Fir N. 89° W. 39.0 ft. O.B.T.

42" Fir N. 55° E. 8.0 ft. O.B.T.

At Corner Point Found 11" Maple & Set 1"x30" I.P. from which:

14" W. Fir bears N. 68° E. 75.0 ft. dist. mkd. $\frac{1}{2}$ S25 B.T.

14" Maple bears N. 70° E. 108.0 ft. dist. mkd. $\frac{1}{2}$ S25 B.T.

Creek bears North 160.0 ft.

Creek bears West 157.0 ft.

Top of 60.0 ft. Stone bears S. 5° E. 180.0 ft.

Fence bears East & West from Corner.

NOT ORIG.
BT'S
PROPORTIONED
BY CHAIN

Ren. #19

SEE CORNER NO. #234

John H. Markham, Jr.
Wit. R.G. Boyd
For Stomar Lbr. Co.
Jan. 21, 1958
C.S. File No. 42/325

	R7W	R6W	
Twp. Corner	S36	S31	T28S
	S1	S6	T29S

144

Found - Orig. NW. BT. Find 24" Oak Snag, I open & find good scribing "S36 BT".

I do not find other orig. BT's. Find partly rotted Laurel

Stump that was opened years ago, no scribing found today,

record, S. 22° E. 54.2 ft., I find to be S. 26° E. 51.0 ft.

I believe these are the BT's. found by Eppstein, 1928.

All of Eppstein's BT's. have been cut & no scribing can

be found on any stump except I do find good scribing on

SW BT. which is in slide area & far out of position. I

find 18" Cut Fir in slide area scribed for S.E. BT. The

evidence I find of Eppstein's BT's. do not agree with

orig. nor do they come to a common corner, therefore I

use the Orig. record bearing & distance from N.W. BT. to

set corner, N. $71\frac{1}{2}^\circ$ W. 39.6 ft.

Set Brass Cap at Corner Mkd: County Surveyor's $\frac{S36}{S1} \frac{S31}{S6}$ T28S Office, 1958 T29S

New BT's: 15" R. Fir bears N. 27° E. 55.6 ft. scribed T28S R6W S31 CS BT.
15" R. Fir bears N. 28° W. 47.9 ft. scribed T28S R7W S36 CS BT.
13" R. Fir bears S. 54° W. 124.6 ft. scribed T29S R7W S1 CS BT.
No trees near to S. E.

James W. Byron, Deputy
Mild Godfrey
S. A. Bilow
November 1958
C.S. File No. 49/50

S. 50° E.
110'