

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

145

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
November 1958
C. S. File No. 49/50

Section Corner to Sections 5 & 6, T29S R6W, & Secs. 31 & 32, T28S R6W.
Found - 1 1/2" Iron Pipe at Corner. REN. NO. 35
10", now 24" R. Fir S. 69 1/2° E. 24.0 ft., shows good scribing
on open face.
24", now 36" Fir Stump N. 47° E. 34.3 ft., shows good scar, I
do not open.
6", now 16" Fir record N. 22° E. 11.5 ft., I find should be
N. 86° W. 11.0 ft., shows good scar, I do not open.
No trace of Springer's SW BT.

I do not set Brass Cap at Corner.

New BT's:

16" R. Fir N. 86° W. 11.0 ft. scribed S31 T28S R6W CS BT.
6" R. Fir S. 42° W. 44.4 ft. scribed S 6 CS BT.
25" R. Fir N. 1 1/2° E. 29.1 ft. scribed S32 T28S R6W CS BT.

FD OK. 2/75 - W.S. BARNES M 55-47

146

John Markham
For Stomar Lbr. Co.
Jan. 16, 1959
C.S. File No. 42/325

1/4 Section Corner to Sections 23 & 26.
as determined by O.B.T's.

34" Fir bears N. 6° W. 9.2 ft. dist. O.B.T. } Ren. = 50
26" Fir bears S. 55° E. 9.2 ft. dist. O.B.T. }

At Corner Point Set 3/4" x 36" Iron Pipe from which:

14" Laurel bears N. 54° W. 65.0 ft. dist. mkd. 1/4 S T29S R6W S23 B.T.
12" Laurel bears N. 69° W. 107.0 ft. dist. mkd. 1/4 S T29S R6W S23 B.T.

147

James W. Byron, Deputy
S. A. Bilow
April 27, 1959
C. S. File No. 49/139

Section Corner to Sections 30 & 31 T29S R6W, & Secs. 25 & 36, T29S R7W.
Found - Orig. 10", now 8" Laurel Snag, shows good scribing "S 3 T29S BT"
N. 33° E. 23.8 ft.

Orig. S. W. BT., down, dozed out of position, shows good
scribing "S36 T29S".

All BT's. as recorded by Boyer except N. E. BT., which is now
a snag. REN. # 41, T29-7W SEE C.S. 41/24 FOR BOYER'S CORNER.
1952 1/83 Z.R.

No other trees near to N. E.

Set Brass Cap at Corner & Alongside squared & scribed Corner Post.

Mkd. Brass Cap County Surveyor's Office, 1959 R7W

S25	S30
S36	S31

 T29S R6W

No New Trees Scribed.

148

1/4 Section Corner to Section 31, T29S R6W, & Section 36, T29S R7W.
Found - 1" Iron Pipe at Corner & both Orig. BT's.

Find Stone at Corner chisled 1/4.

Orig. S. W. BT., now Stump, shows good scar.

Orig. S. E. BT., now dead, shows good scribing "BT"

New BT's: 20" R. Fir bears S. 11° E. 5.0 ft. scribed S31 1/4 CS BT.
8" W. Fir bears N. 53° W. 44.1 ft. scribed 1/4 S36 CS BT.

149

Milo Godfrey
James W. Byron
Clete Putnam
June 15, 1961
C. S. File No. 49/52

1/4 Section Corner to Sections 26 and 35.
Found - 1" Iron Pipe. REN. # 51

W. Oak, now 18", S. 37 1/2° E. 68.6 ft., to face of tree, shows good scar.

W. Oak, now 22", N. 28° E. 66.0 ft. (to face of tree) shows good
bark scribing "1/4 S26 CS BT" Blaze & Rescribe this tree.

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961

S26	S35
S36	S31

 T29S R6W

Did not scribe any new trees. Both Oak Bearing Trees are in good
condition. No trace of Fir BT. could be found.

150

James W. Byron
D. McFarland
J. Powell
Sept. 1961
C.S. File No. 49/64

Sec. 1, T29-6 : Sec. 6, T29-5 : Sec. 36, T28-6 : Sec. 31, T28-5.
Found - Orig. 22", now 28" W. Oak N. 84° E. 84.0 ft. not 90.4 ft. We open
and find good scribing "S S".

Orig. 24", now 30" B. Oak Snag, center rotted, no scribing S. 45° W. 85.8'

Orig. N.W. BT. standing, shows good scars. Orig. S.E. BT. not found.

We find 1" I. P. bears N. 80° E. 18.8 ft.

Set Brass Cap at Cor. Mkd: County Surveyor's Office, 1961

S36	S31
S 1	S 6

 R6W T28S

New BT's: 10" W. Oak bears N. 83° W. 12.5 ft. scribed S36 T28S R6W CS BT.

12" W. Oak bears S. 36° W. 15.7 ft. scribed S 1 T29S R6W CS BT.

8" W. Oak bears S. 64° E. 21.0 ft. scribed S 6 T29S R5W CS BT.

11" W. Oak bears N. 30° E. 6.0 ft. scribed S31 T28S R5W CS BT.

Fd. brass-cap and all bearing trees o.k. 10/11/73