

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T.S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

199

Vernon R.
Tracy &
Crew
C.S. File
No. 49/139

$\frac{1}{4}$ Section Corner to Sections 24 & 25.
Found - 1" I.P. & Brass Cap, dated 1957 & Mkd: County Surveyor's
Office and one standing BT.: See Ren. #130.
10", now 11" D.Fir N.56°E. 33.1 ft.
Other BT. recorded, down.
New BT: 14" D.Fir S.52°W. 39.1 ft. Mkd: $\frac{1}{4}$ S25 CS BT.

FD. BC. 7/77
BLM ADMIN. Survey
SEE GIS FILE

Aug. 21, 1964

200

James W.
Byron,
Deputy
D. Mc. &
J. Powell
April
1962
C.S.
File
No. 49/139

Section Corner to Sections 11 - 12 - 13 - 14.
Found - 1 $\frac{1}{2}$ " I.Pipe at Corner 1.0 ft. West of North-South
Fence, See Ren. #9.
Orig. 30", now 32" Triple W. Oak S.73 $\frac{1}{2}$ °, W. 25.7 ft.,
shows old scribing.
Orig. S. E. BT., now snag.
Orig. N.8, W. BT., standing.
Also find Cain's N.48 $\frac{1}{2}$ °, W. 79.2, now 16" W.Oak,
shows scribing.
New BT: 11" W.Oak bears S.5, E. 56.4 ft. scribed.
Rescribed - O.B.T., now 32" W.Oak S.73 $\frac{1}{2}$ °, W. 25.7 ft, T29SR6WS14CSBT
Now 16" W.Oak N.48, W. 79.2 ft. mkd. S11 T29SR6WCS BT.

FD OK PER HOLT
M105-80 4-88

201

Bruce R. Rogers, Deputy
Mike Stone
June 15, 1965
C. S. File No. 49/139

S. E. Corner D. L. C. No. 42.
Found - Orig. 30" Oak, now 30", N.41°W. 99.0 ft., shows good scar.
Did not open.
 $\frac{3}{4}$ " Iron Rod at Corner.
No trace of Frear's Tree (See Ren. #17)
New BT's: 4" W.Oak S.25°W. 34.4 ft. Mkd:

202

S. W. Corner D. L. C. No. 42.
Found - Orig. 13" W.Oak, now 27", N.16°E. 224 lks. Tree has old
scar and is hollow.
 $\frac{3}{4}$ " Iron Rod - See Ren. #18.
6" Oak, now 10", S.14°W. 2 feet.
New BT: 6" Oak N.13°E. 18.3 ft. Mkd: SW Cl 42 CS BT.



MICROFILM TO HERE 10/67

203

John H.
Markham, Jr.
Sept. '68
C. S. File
No. 51/292

Section Corner to Secs. 1 & 2, T29-6W. & Secs. 35 & 36, T28-6.
N. E. Corner Section 2 - At Corner Point, found I-5 highway fill.
Brass Cap buried, from which: Orig. 18" W.O. N.85 E. 62.7 ft.
Ren. #151 Orig. 13" B.O. N. 2 W. 59.3 ft. 221
All other trees missing.
6" steel sign post set in concrete reads: Portland 187
Roseburg 10
bears S.60*30'W. 102.0 ft. slope dist.
East end freeway culvert 48" diam., bears S.30E 135.5 ft., slope dist.

204

Sec. Cor. to Secs. 19 & 30, T29-5 and Secs. 24 & 25, T29-6W.
Prorated Section Corner.
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 29 S R
Office 6 S 24 S 19 5
1969 W S 25 S 30 W
New BT's: 13" D.Fir S. 40° W. 25.1 ft. mkd: T29S R6W S25 CS BT.
14" D.Fir N. 43° W. 30.2 ft. mkd: T29S R6W S24 CS BT. #233
6" D.Fir S. 56° E. 25.2 ft. mkd: S30 CS BT.
No trees to the N.E. Quadrant.
Fence Corner running N. and W. bears N.15°W. 28.6 ft.

205

James W. Byron, Co. Surv.
John M. Powell & Crew
February, 1969
C.S. File 54/79 M 37 - 20

Pro-rated $\frac{1}{4}$ Corner to Sec. 19, T29-5W. and Sec. 24, T29-6W.
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 29 S R
Office 6 $\frac{1}{4}$ 5
1969 W S 24 S 19 W
New BT's: 10" D.Fir S.87°W. 21.3 ft. mkd: $\frac{1}{4}$ S24 CS BT.
7" Oak N.82°E. 16.1ft. mkd: $\frac{1}{4}$ S19 CS BT. #241
Note - N-S fence line bears E. 13.0 ft. and 119.0 S. of Boomer Hill Road.