

Douglas County Surveyor's Record of
Government Corners Renewed

T.29 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

206

1/4 Corner to Sec. 30, T29-5W. and Sec. 25, T29-6W.
Prorated - Set - Brass Cap at Cor.Mkd: County Surveyor's T29S
Office R6W 1/4 R5W
1969 S 25 | S 30

RE-RENEWED, SEE CORNER NO. #238
New BT's: 22" D.Fir S. 79° E. 5.5 ft. mkd: 1/4 S30 CS BT.
12" D.Fir N. 83° W. 32.9 ft. mkd: 1/4 S25 CS BT.
This corner lies approx. 16.0 ft. W. of N-S fence line and
24.0 ft. north of small stream.

J.W. Byron
J. Powell & Crew
Feb. 1969
C.S. 54/79
M 37 - 20

207

Section Corner to Sections 23 - 24 - 25 - 26.
Found - County Surveyor's Brass Cap, properly marked in 1962, Ren.#174.
50" D.Fir, now stump, N.85°E. 38.5 ft., no scribe visible
12" D.Fir, now snag, S.56°E. 32.0 ft., scribe visible
8" W.Oak, now cut down, N.59°W. 128.6 ft.
20" Laurel, now pushed out, S.17 1/2°W. 74.7 ft., scribe visible.
New BT's: 13" D.Fir N. 3° E. 65.5 ft. mkd: T29S R6W S24 CS BT.
7" W.Oak N.43°E. 24.0ft. mkd: T29S R6W S24 CSBT.
24" D.Fir S76°E. 94.4 ft. mkd: T29S R6W S25 CS BT.
13" D.Fir S.20°W. 142.4 ft. mkd: T29S R6W S26 CS BT.
This corner is in fence corner, fences are running approx. E. & S.

FD. 7/77
ADMIN. SURVEY - SEE
G.T.S. FILE
John M. Powell
Frank Jones & W. Penley
July, 1969
O.S. File No. 49/139

208

1/4 Corner to Sections 26 and 27.
Found - Cadastral Brass Cap at 1/4 Corner, properly marked in 1958.
30" D.Fir, now 38", S.30°W. 28.4 ft., scribe visible.
50" D.Fir, now 46", S.10°W. 17.2 ft. (Rec. 10.5) bark scribed
"1/4 S BT" See Ren. #78
1" Iron Pipe in mound of stone, See Ren. #78.
New BT: 14" Maple N.53°W. 53.2 ft. mkd: "1/4 S27 CS BT".
This corner will lie by new N - S fence line now being constructed.

RE-RENEWED, SEE CORNER NO. #246

209

1/4 Corner to Sec. 6, T29-5 and Sec. 1, T29-6W.
Prorated 1/4 Corner, See Survey M. 33 - 63.
Set - Brass Cap mkd: Eng.#2128-Nov.1969-1/4 Cor.
T29S R6W. Sec. 1 T29S R5W Sec.6
New BT: 24" Forked Ash by Creek, N.89°E. 162.4 ft.
Mkd: "1/4 S 6 BT".

Wm. B. Barnes
For: O. Clayton
C.S. File 55/136
M 33 - 63

Nov. 1969

210

Center of Section 30.
Set - 5/8" Iron Rod from which bears
A Madrona 5" diam. S.83°47'W. 19.7 ft. scribed
"1/4 S30 BT".
A Chinquapin 10" diam. S.30°37'E. 27.9 ft. scribed,
"C 1/4 S30 BT".

R. H. Gee
For:
Western Land
Mgt. Inc.
M 40 - 17

RE-RENEWED, SEE CORNER NO. #223

July, 1970

FDOK PER JOHNSTONE
12/89 M 101-72 211

S. E. Corner D. L. C. No. 43.
Found - 14" D. Fir, now stump, N.36°W. 33.0 ft., opened & burnt faint
scribe marks visible. See Ren. #5.
17" D.Fir, now stob, N.56°E. 9.9 ft., opened for scribing,
"S 29" and other marks.
Set - Brass Cap at Cor Mkd: County Surveyor's T 29 S R 6 W.
Office, 1970 SE DLC 43
New BT's: 12" Maple N.65°E. 69.0 ft. scribed "SE DLC 43 CS BT."
10" W.Oak S.18°W. 72.5 ft. scribed "SE DLC 43 CS BT"
Note: This corner is approx. 10 ft. south of draw.

John M. Powell
W. Penley & J. Heritage
C. S. File 49/139

11/10/70

FDOK PER JOHNSTONE
12/89 M 101-72 212

S. W. Corner D. L. C. No. 43.
Found - 50" D.Fir, now 52", S.23°E. 36.3 ft., shows good scar.
9", now 15" D.Fir, S.52 1/2°W. 13.2 ft., shows good scar. Ren. No. 4
30" D.Fir, now stump, N.23°W. 52.1 ft., opened for scribe "29S R".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 6 W
Office, 1970 SW
DLC 43
New BT: 9" Cedar N.35°E. 14.9 ft. scribed "SW DLC 43 CS BT".

11/10/70

MARCH 71