

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 6 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

220

S. E. Corner D. L. C. No. 41.  
Re-established from found BT's., as follows: See Ren. #62.  
2 1/4" Cedar, now 3 1/4" Stump, bears S. 35° W. 43.2 ft. (near R. Bank of Creek)  
22" W. Fir, now 28" Stump, bears S. 5° E. 47.3 ft. (near R. Bank of Creek)  
Found part of rotted face with scribes.  
Set - 5/8" Iron Rod at Corner.  
Blazed & Scribed New BT., as follows:  
18" W. Oak on R. Creek Bank bears S. 43° W. 55.3 ft.  
(Scribed "T29S R6W Ch1")

Victor M.  
McLind  
For:  
Willis Ck.  
Prop.  
M 42 - 33  
July, 1971

JAN. 1972

221

Sec. Corner, Secs. 35 & 36, T.28-6, Secs. 1 & 2, T.29  
Found - 13" B. Oak, N.3°W., 59.3 ft. scribed S35 T28S  
R6W CS BT.  
18" (now 22") W. Oak, N.85 1/2° E., 64.7 ft. scribed  
S36 T28S R6 CS BT. Ren. 203  
6" Steel sign post set in concrete bears S.62°W.  
East end of culvert 48" diam., bears S.31°E.  
Set - Brass cap at section corner mkd.

L. E. Monrean  
Pete Earle  
C.S. 56/39  
10/23/73

COUNTY SURVEYORS T 28 S R 6 W  
OFFICE S35 S36  
1973 S 2 S 1  
T 29 S R 6 W

New BT - 18" W. Oak, bears S.34 1/2° E., 196.4 ft. scribed  
T29S R6W S1 CS BT. Following are slope distances  
and angles taken to BT: 82°@ 19° = 77.5 ft.  
100°@ 4°30' = 99.7 ft.  
19.2' level = 19.2  
196.4ft.

222

Center 1/4 Section 15

Found - Iron Pipe with brass cap mkd. U.S. Dept. of Interior  
BLM Cadastral Survey C 1/4 S15 T29S R6W 1971.

19" Ash, bears S.85°W., 156.6 ft. scribing visible  
"C 1/4 S15 BT" Note Tree is blown down and will  
be removed.

21" Maple bears N.71°E., 132.7 ft. scribing visible  
"C1/4 S15 BT"

20" Myrtle, burlled at the base. bears N.34°E., 33.6 ft.  
(32.2 ft. to face of tree) Record N.45°E., 32.0 ft.  
Axe marks and partial scar visible, I do not open.  
Ren. #64

New BT: 17" Double ash, bears N.6°E., 89.7 ft. Scribed C1/4  
S15 CS BT. Note, This tree stands on edge of  
high bank on the northerly side of east  
Willis Creek.

Note: This corner lies in small open meadow about 60 ft.  
south of east Willis Crk. & 5 ft. west of N-S fence  
line and small storage shed.

12/12/73

223

Center 1/4 Corner for Sec. 30.

Set - 5/8" I.R. from which bears Ren. No. 210  
5" Madrone, S.86°07' W., 26.0 ft. scribed C 1/4  
S 30 BT.  
10" Chinquapin, S.18°18' E., 24.9 ft. scribed C 1/4  
S 30 BT.

R. H. Gee  
for Western Land  
Management  
M 52 - 25  
Nov. 1973

REN. #210 IN ERROR - DESTROYED BY R. GEE

224

EASTERLY

N.E. Corner DLC #40

Set - 5/8" Iron Rod projected from C.S. File 55/159.

10/73

Harold Ball  
for S & S Builders  
M 52 - 28