

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

231

C O N T -

New BT's - A 14" G. Fir, bears S.22°W., 30.4 ft. scribed "1/4 S33 CS Bt" on a double blaze.
A 6" G.Fir, bears N.72 1/2°E., 26.2 ft. scribed "1/4 S34 CS BT" on a single blaze.

There are remains of a down fence running East from this corner, also South. Nov. 10, 1976
11/10/76 C.S. 59/26

232

Closing Corner for Secs. 32 and 33 only. South boundary.

Found - A 1 1/2" axle with flange up at corner point REN.#115
From Which:

An. orig. 12" now 24" White Fir (snag) bears N.43°E., 20.5 ft. visible "29W S33 BT" on previously opened blaze.

A 48" now 49" Fir bears N.85°E., (Rec. N.80°E.,) 97.0 ft. (Rec. 107.0 ft.) Tree is alive and shows illegible bark scribing.

A 20" now 24" freshly cut Cedar bears S.30°W., 101.5 ft. Lower blaze previously opened but no scribing visible. We open upper blaze and find "X" scribe.

New BT's-A 9" Fir bears S.6°W., 52.8 ft. mkd. "T30S R6W S4 CC CS BT" in a double blaze.

An 11" D. Fir bears N.51°E., 63.7 ft. mkd. "T29S R6W S33 CC CS BT" in a double blaze.

An 11" D. Fir bears N.5°W., 59.5 ft. mkd. "CC T29S R6W S32 CS BT" in a double blaze.

Note: In 1958, BLM ran South on the line between S32 and S33 and reported that the point referenced by the found orig. BT fell 21 lks. North of the South boundary of T29S. They reported setting a brass cap 21 lks. South of the point and on line but it was not found. They also scribed two trees:

A 10" Fir, bearing N.58°E., 96.4 ft. and a
10" Cedar bearing N.22 1/2°W., 248.8 ft.

We find the Cedar but not the Fir. We pull out the recorded Bearing and distance from Cedar and miss the reported corner point (BLM's corner) The axle bears N.35 1/2°E., 27.3 ft. from point established from BLM's Cedar bearing tree.

11/18/76

233

Sec. Cor. for 24 and 25; and Secs. 19 and 30 of T29-5.

Found - 1969 County Surveyors Office brass cap properly marked bears N.68°E., 17.4 ft. from orig. corner located from O.B.T..

From brass Cap: Ren. #204

A 13" now 18" D. Fir bears S.40°W., 25.1 ft.

A 14" now 22" D. Fir bears N.43°W., 30.2 ft.

A 6" now 8" D. Fir bears S.56°E., 35.3 ft. (Rec. 25.2 ft.) BT tag said 35.2 ft.

All BT's had double well healed blazes.

From Apparent Orig. Corner Location:

A D. Fir stump, 15" now 40" bears S.2°E., 137.3 ft. with prev. opened single blaze. Found scribing "2" S30 BT.

Set - Reset brass cap in orig. location stamped to now read:

County Surveyor's Office		T 29 S	R
1969	R	S 24 S 19	5
	6	S 25 S 30	W
	W	Reset	
		1977	

FD. 7/77 BLM ADMIN. SURVEY
SEE GIS FILE

Drove a 5/8" Iron Rod with alum cap at location where we removed brass cap. Alum cap bears N.68°E., 17.4 ft. stamped "CS 1977" We used already scribed BT's which now face 5/8" I.R., as follows:

A 18" D. Fir bears S.0°30'W., 13.7 ft.

A 22" D. Fir bears N.9°W., 28.4 ft.

A 8" Twin trunked D. Fir bears S.75°E., 47.9 ft.

All BT's have double well healed blaze.

A wire fence running W & N has corner which bears N.15°E., 35.0 ft. dist.

6/14/77

G. Langlitz, Doug.
Co. Surveyors Off.
A.V. Cangie; M.Tompk
Witness: R. Mosher,
BLM

A. Vicror Cangie, Doug. Co. Surveyors Off.
Mike Tompkins
Karen Cheney
Pete Earle
Nov. 18, 1976
C.S. 59/26

R. Kimberling
P. Earle
June 14, 1977
C.S. 59/34
County Surveyors Office