

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 7 R. W. W. M.

KOYE-CHAPMAN CO., EUGENE, ORE. 97196

Vol. 2 P. 261

Surveyor: A. Boyer
Witnesses: Frank Smith,
B. B. Lewis, & Mr. Hollenback
April 24, 1952

A. Boyer
J. Byron
June 9, 1953.
In connection with line run
for L. D. Lockwood-File 41/187

R. C. Grant
Witnesses:
William Hart
A. R. Evans
July 7, 1953
Filed in 41/250
Work done for:
Nyberg-Lumber Co.

A. R. Evans
Witnesses:
R. C. Grant
July 7, 1953
Filed in 41/250
Work done for:
Nyberg-Lumber Co.

1/4 sec. cor. bet secs. 4 and 9. 50
Set a sandstone 12x10x10 from which a wh. oak 7" dia. bears
S. 4° W 2.50 Chains distant.
A white oak 34 di. bears N. 73 W 2 1/4 chains distant.
Present T.F. Fisher and B. Caster line;
One original B.T. standing but dead and stump of the other re-
maining; part of letters visible. April 28. 1899.

1/4 cor. South side Sec. 36
Set Post marked B.T.
Pine 30" N 27° E 254 lks.
Pine 20" S 22° W 353 lks.
Nov. 1887 Briggs

SEE CORNER NO. 83 51

Cor. ~~29/28~~ ~~32/33~~ Set post,
Set cor. from stump and O.B.T.
B.T. W. Oak 12"- S 55° E 119 lks O.B.T.
W. Oak 5"- S 62 1/2 W 11 lks N.B.T.
W. Oak 6"- N 84 1/2 W 63 lks N.B.T.
W. Oak 5"- N 66 E 40 lks N.B. 1.

SEE CORNER NO. 66 52

N. E. SEC. 36, also S. W. Corner of above Section.
24" Fir N. 89 degrees 30' E., 18.5 Ft. Trees marked
Sec. 30 Twp. 29 S. Rge. 6 W. B. T.
18" Fir S. 56 degrees E., 73 Ft. bark blaze, Trees
marked Sec. 31 Twp. 29 S. Rge. 6 W. B.T.
18" Fir N 27 degrees 30' W., 79 Ft. bark blaze, Trees
marked Sec. 25 Twp. 29 S. Rge. 7 W.
23" Fir stump S. 56 degrees 30' W., 75 Ft. Marked
Sec. 36 Twp. 29 S. Rge. 7 W. B.T.
The corner is about 15 feet east of the new road.

SEE CORNER NO. 95 53

~~1/4 sec. corner between secs. 9 and 10. DESTROYED BY
Set 4" x 4" Maple post scribed on West side 1/4 S 9.
Scribed on South side T29S, R7W.
Scribed on East side 1/4 S 10.
Scribed on North side 1581.
Blazed and scribed two trees:
12" Red Fir, bears S57°W, 30.2', 1/4 S9, T29S, R7W., 1581 B. T.
14" Maple, bears S32°E., 27', 1/4 S10, T29S, R7W., 1581 B. T.
This corner was renewed from orig. B.T.-a 9" fir bears N.42°E., 27 lks.
dist. We found a possible scribe mark on apparent old blaze. Also
this places the cor. 12' North of old fence and South of sec. cor.
to North. In view of the fact that the South half of this section is
in error and the type of work done by the orig. surveyor, we have
used the above evidence to renew the 1/4 corner.~~

CADASTRAL ENGINEER
See RESURVEY, 1956
SEE ALSO REN. # 209

1/4 corner between secs. 10 and 11. 55
Set from O. B. T. which is 23" Oak S.50W., 66.0.
Marked New BT. - 13" Fir S.24E., 20.8'.
Set 4" x 4" Cedar Stake.

1/4 corner between secs. 10 and 15. 56
Renewed from O. B. T. - Stump Oak N.70W., 30 lks.
New B.Ts. marked:
10" Fir S.65W., 3.1 feet.
8" Fir N.35W., 12.3 feet.
Set Cedar stake for corner.

? Refer To
C. S. File No. 49/4

SEE GOV'T. MAP - BRASS CAP SET BY
PROP. MEASUREMENT, 1957