

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97198

$\frac{1}{4}$ corner to secs 8 and 9. 57

Corner renewed from BT - 36" Red Fir, S.65°30'E., 62.7 feet. Bt. in good condition - R. Fir S.40°W., 6.6 feet down. REN. No. 36

Set a 5/8 inch by 30 inch iron rod for the $\frac{1}{4}$ corner. 193

Blazed and scribed two new trees-

Red Fir, 8 inches in dia., S.87°E., 31.5 feet dist., marked $\frac{1}{4}$ S 9 CS BT.

Red Fir, 6 inches in dia., S.80°W., 134 feet dist., marked $\frac{1}{4}$ S 8 CS BT.

Southeast corner of Donation Land Claim No. 40. 58

Corner renewed from old B. T. N.50°W., 26.4'. B. T. is standing but dead center and old blaze rotted out. No scribe left. Old blaze faces o. k. and corner is O. K. with old barbed wire fence corner.

Set a 5/8 inch x 30 inch iron rod for the corner. 194

Blazed and scribed two trees-

Red Fir, 12 inches in dia., south 35.6 feet dist., marked S. E. Cl. 40, C. S. B. T.

Red Fir, 16 inches in dia., N.79°W., 52.3 feet dist., marked S. E.

Cl. 40, C. S. B. T.

Section corner to secs. 5, 4, 8 and 9. #291 59

Corner renewed from old B. T.s standing and in good condition. We find

24 inch B. O. N.29°30'W., instead as recorded N.20°W. Distance O. K. Ren 5

Set a 3 inch iron pipe with $\frac{1}{2}$ inch iron rod inside, 14 inches below surface.

Blazed and scribed two new trees-

Apple tree, 6 inches in dia., S.56°W., 173.0 feet dist., marked S 8 C. S.

B. T. Maple, 12 inches in dia., N.76°W., 226.7 feet dist., marked S 5 C. S. B. T.

Southwest Interior "L" corner Elijah Croxton's Donation Land Claim No. 45. 60

Corner renewed from old B Ts - a 36 inch B. O. N.80°E., 14 lks. standing but center rotted out. Stump of 24 inch B. O. S.85°W., standing with center rotted out. Both check for bearings and distances. Also within 10 feet of fence corner.

Set a 5/8 inch by 30 inch iron rod for corner.

Blazed and scribed two new trees.

Red Fir, 12 inches in diam., N.51°W., 12.2' dist. mkd. Int L cl 45 CS BT.

Red Fir, 18 inches in diam., S.5°W., 51.0 feet dist mkd. SW Int L Cl 45

CS BT.

West exterior "L" corner Elijah Croxton's Donation Land Claim No. 45. 61

Corner renewed from old Black Oak S.40°W. We cut out and found several old scribe marks. Also distance from Pine stump hole checks bearing and distance to B. O. The Pine is laying about 50' down the slope from its original position - rotted.

Set 36 inch iron pipe with brass cap mkd. S. W. Ext. L D.L.C. 45, 1954, County Surveyors Office.

Blazed and Scribed two trees-

R. Fir, 18 inches in diam., N.35°E., 23.0 feet dist., marked S W Ext L Cl 45 CS BT.

R. Fir, 16 inches in diam., S.60°E., 32.5 feet dist., marked S W Ext L Cl 45 CS BT.

Section corner to secs. 8, 9, 17 and 16. FA OK 2-93 BT BENTZ 62

Corner renewed from 24 inch Cedar S.38 $\frac{1}{2}$ °W., 133.6 feet in good condition Ren #46 and 20 inch W. O. S.12 $\frac{1}{2}$ °E., 172.9 feet in fair condition. Found a yellow tag on fence corner at corner. Ren #35

Set a 36 inch by 1 inch iron pipe with brass cap marked Sec. 8, Sec. 9, Sec. 16 and Sec. 17, County Surveyor's Office, T 29 S, R 7 W - 1954.

Blazed and Scribed two trees-

Red Fir, 14 inches in diam., N.2°15'E., 90.4 feet dist., marked S 8 CS BT.

Red Fir, 12 inches in diam., S.40°E., 125.3 feet dist., marked S 16 CS BT.

County Surveyor's Office - Ben B. Irvine, County Surveyor - February, 1954. Done at request of County Court and filed in Road Drawer,
Jim Byron
Ray Irvine
Roads No. 38,
See C.S. File No. 46/36