

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

68  
South  $\frac{1}{4}$  corner, section 32.  
Corner positively identified. Brass cap at corner and 6 inch red fir,  
N.38°E., 13 lks. standing. SEE CORNER NO. 161  
Blazed and scribed two trees:-  
8 inch red fir, N.28°W., 4.4 feet dist., mkd. T 29 S,  $\frac{1}{4}$  S 32 C.S. BT.  
10 inch red fir, N.51°E., 12.0 feet dist., mkd. T 29 S,  $\frac{1}{4}$  S 32 C.S. BT.

69  
West exterior "L" corner of Donation Land Claim 46 (A. E. McCullough's).  
Found 2 inch iron pipe. SEE CORNER NO. 146  
40 inch Ash, S.10°W., 334 lks. previously remarked.  
20 inch Fir, N.89°E., 121 feet, previously remarked, C 46 T29S W S BT -  
W fork of 3 prong tree.

70  
Southeast corner of A. E. McCullough's Donation Land Claim No. 46  
Stump of O. B. T. (out of ground - stump hole) S.70°W., 10 lks.  
Drove  $\frac{3}{4}$  inch by 36 inch Rod at corner.  
New BTs:-  
10 inch Fir, N.73°E., 21.8 feet dist., mkd. C 46 C.S. BT.  
14 inch Fir, N.60°W., 68.7 feet dist., mkd. C 46 C.S. BT.

71  
Northwest corner of John Byron's Donation Land Claim No. 38.  
Location identified from 3 BTs as set by Frear in 1936. - REN. No. 45  
Oak N.20°W., destroyed.  
Corner destroyed. SEE CORNER NO. 90  
Set 1 inch by 36 inch iron pipe with a brass cap stamped County Surveyor's  
office.

72  
Southeast corner of John Byron's Donation Land Claim No. 38. (The most  
southerly exterior L).  
Corner positively identified from 16 inch W. O. standing and in good condition.  
Also found 1 inch iron pipe. - REN. # 25  
Blazed and scribed:  
8 inch W. O., N.22°E., 76.6 feet dist., marked S.E. CL 38 CS BT.

73  
Southwest corner of John Byron's Donation Land Claim No. 38.  
Corner positively identified from 16 inch W. O., S.13°W., 71.0 feet, which  
is down. Also 1 inch iron at corner. - REN. # 24  
Blazed and Scribed two trees:  
16 inch W. O., N.73°W., 18 feet dist., marked SW CL 38 CS BT.  
10 inch W. O., N.12°W., 148.8 feet dist., marked SW CL 38 CS BT.

74  
Northeast corner of John Byron's Donation Land Claim No. 38.  
We found sandstone rock 12 inches above ground. Oscar Olsen states it was  
set by John Byron for corner. Also original B. O., 20 inches in diam.,  
N.70°W., 23 lks. dist. Stump but scribe marks not visible, rotted, 12  
inch B. O. N.5°W., 31 lks. Part of old stump left. Bearings and distance  
to sandstone rock O. K. ← FD. SK 4/10 W. Ruppert. M 93-41  
Blazed and scribed two new trees:  
14 inch red fir, N.46°W., 100.51 feet dist., marked NE CL 38 CS BT.  
12 inch red fir, N.29°E., 147.2 feet dist., marked NE CL 38 CS BT.

Ben B. Irving, James W. Byron, and Ray Irving, County Surveyor's Office.  
Work done under order of County Court, in cooperation with County Engineer's Office  
in connection with their road survey of County Road No. 38.  
February, 1954. See County Surveyor's File 46/36.

↑ CORNERS FOUND SEE RM 2 - 35