

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 7 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 31891

Clifford M. Brydon  
Surveyor for Roseburg Lumber Co.  
May 21, 1957  
Map File No. M 5 - 41.

Section corner to secs. 12 & 13, T29S, R7W., and secs. 7 & 18, T29S, R6W.  
Location of corner established by proportional measurement.

Set an 1 inch iron pipe for corner,  
from which;

- A Maple, 14 inches in diameter bears N.77°30'E., a distance of 70.2 feet scribed T 29 S, R 6 W, S 7 BT.
- A Maple, 16 inches in diameter bears S.41°10'E., a distance of 86.8 feet, scribed T 29 S, R 7 W, S 18 BT.
- A Fir, 14 inches in diameter bears S.70°W., a distance of 125.0 feet scribed T 29 S, R 7 W, S 13 BT.
- No trees in Northwest quarter.

85

$\frac{1}{4}$  corner to sec. 13, T29S, R7W., and sec. 18, T29S, R6W.  
Location of corner established by proportional measurement.

Set  $\frac{3}{4}$  inch iron pipe for  $\frac{1}{4}$  corner,  
from which;

- A Fir, 14 inches in diameter bears S.78°50'E., a distance of 36.6 feet, scribed  $\frac{1}{4}$  T 29 S, S 18 BT.
- A Fir, 12 inches in diameter bears S.62°W., a distance of 70.7 feet scribed  $\frac{1}{4}$  T 29 S, S 13 BT.

85A

James W. Byron, Deputy County  
Surveyor.  
June 7, 1957.  
C. S. File No. 47/194.

$\frac{1}{4}$  corner to sec. 12, T29S, R7W., and sec. 7, T29S, R6W.

Found - Both original B.T.s: The 15 inch B. O., S.56°E., (now 36" snag) shows old face and short sections of reverse scribe marks found near rotted area. 4 inch Laurel, S.55°W., (now 18 inches) has been dozed out and is now laying 30 feet down hill-shows old rotted face and possible faint scribe marks.

Also found 2 fir stumps with good scribing, face to corner. A 12 inch Fir bears N.24 $\frac{1}{2}$ °W., 19.6 scribed  $\frac{1}{4}$  S 7 BT. A 12 inch Fir bears S.61°E., 12.8 feet with good scribing. These trees scribed by Art Boyer about 30 years ago states Geo. Voytilla. Not recorded. (See signed statement in file).

Set an iron pipe with brass cap at corner mkd.  $\frac{1}{4}$  S T29S 12 | 7 County

R7W | R6W Surveyor's  
Office, 1957

from which:

- 10 inch R. Fir, N.61°W., 101.6 feet, mkd.  $\frac{1}{4}$  S T29S R7W, C.S. BT.
- 12 inch Laurel, S.80°W., feet, mkd.  $\frac{1}{4}$  S T29S R7W, C.S. BT.

86

James W. Byron, Dep. Co.  
Surveyor  
June 28, 1957  
C. S. File No. 47/197.

$\frac{1}{4}$  corner to secs. 7 and 18.

Found both BTs as scribed in 1924, new stumps only and faces burned. Also found B. O., now 40 inch snag - all check for bearing and distance. I find scribe mark "T" on face of SE BT, now 24 inches, and short piece of scribe mark on Northwest BT, now 22 inches. I open B. O., no scribe marks found.

No BTs found for brass cap at present location. I move brass cap N.80E., 73.7 feet and reset to agree with true location.

New BTs:

- 30 inch B. O. bears N.61°W., 48.1 feet scribed  $\frac{1}{4}$  S 7 CS BT.
- 12 inch R. Fir bears S.65°W., 52.2 feet scribed  $\frac{1}{4}$  S 18 CS BT.

87

Ben B. Irving  
N. E. Richardson  
July, August, 1947  
C. S. File 38/188  
M 6-14

$\frac{1}{4}$  Section Corner to Section 7 & 8.

Found and Reset Government Iron Pipe with Brass Cap 1"X 36" marked  $\frac{1}{4}$  S.7 S.8, 1924.

Bearing Trees: Stump of Old BT (W. Oak) S.20°W. 99.7 ft.

W. Oak Old BT S.12°E. 81.2 ft.

24" W. Oak New BT 114.8 ft. S.14°W.

163

88

Center  $\frac{1}{4}$  Corner to Section 7

Set 1"X 36" Iron Pipe.

Bearing Trees: 26" Cedar N.86°W. 27.6 ft.

40" Fir S.2°W. 39.0 ft.

89

208