

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

90

N. W. Corner D.L.C. No. 38.
At Corner find Iron Pipe with Brass Cap stamped "County Surveyor's
Office, 1954, N.W. Corner D.L.C. No. 38". Ren. No. 45 & No. 71
Found: 14" Fir stump N.81°W. 9.5 ft., bark scribing "S NW C 38 BT"
visible.
Fir Bearing Tree to S.E. is uprooted & down -- cannot get accurate
bearing or distance to it.
Blaze & Scribe 2 New Trees: 40" Incense Cedar S.28°W. 20.0 ft.
17" Incense Cedar S.26°E. 47.9 ft.
"Scribed "N.W. CL 38 CS BT"

James W. Byron
M. Godfrey
S. Blilow
Dec. 17, 1957
C.S. File No. 49/139

91

Section Corner to Sections 3 & 4, T29S R7W & Secs. 33 & 34, T28S R7W.
Set from O.B.T. S.80°E. 235 lks., which Eugene Ollivant testifies
is Orig. B.T. This tree has deep cut on N.W. face & old axe
marks in cut & is E.264.7 ft. from N $\frac{1}{2}$ Cor. Sec. 4.
Drove 2" sq. hd. Bolt & remarked Orig. B.T.
Scribed New Trees: 24" Cedar S.27 $\frac{1}{2}$ °E. 44.5 ft. "S3 T29S R7W 1581 BT."
14" Forked W.Oak N.34°E. 181.0 ft. "S34 T28S R7W."
7" W.Oak S.89°W. 61.0 ft. "S4 T29S R7W 1581 BT"
Corner is about 300 ft. West of Center Olalla Creek and on N. side
of Dry Creek.

RE-RENEWED CORNER NO. 264

Arthur Boyer, #1581
Witness: H. L. Northcraft
John Fletcher
For Arthur Gilbert
October, 1958
Map File No. 12 - 72

92

$\frac{1}{4}$ Section Corner to Secs. 3, T29S R7W, & Sec. 34 T28S R7W.
Set on line at mid-point bet. Corners $\frac{1}{2}$ mi. to East & West.
Drove Cedar Post & buried Rock 4x8x10 & scribed:
48" Oak N.32°E. 254 ft. " $\frac{1}{4}$ S34 T28S R7W 1581 BT"
15" Forked W.Oak S.80°E. 294 ft. " $\frac{1}{4}$ S3 T29S R7W 1581 BT."
10" W.Oak on an E. & W. Fence Line N.58°W. 386 ft. " $\frac{1}{4}$ S34 T28S
R7W 1581 BT."

RE-RENEWED CORNER NO. #259

93

$\frac{1}{4}$ Section Corner between Secs. 3 & 4.
Set by Prop'n'l measurement on line between N.W. & S.W. Corners of
Section 3
Drove 1 $\frac{1}{2}$ " Iron Pipe & scribed following trees:
24" Fir N.19°27'E. 410.4 ft. " $\frac{1}{4}$ S3 T29S R7W 1581 BT".
24" B.Oak S.85°40'W. 446 ft. " $\frac{1}{4}$ S4 T29S R7W 1581 BT".
30" Fir N.0°40'E. 329 ft. " $\frac{1}{4}$ S3 T29S R7W 1581 BT".
FD. C.K. G. BAUGHMAN 9.20 M 85-35

Center Section 3.
Set at Intersection N. & S. and E. & W. mid-section lines.
Drove 3"x 3" Fir Stake, scribed:
24" Fir Stump N.10°E. 34 ft. on slope "Cen S3 T29S R7W 1581 BT".
12" Leaning Fir S.33°E. 14.5 ft. "Cen S3 1/16 S3 T29S R7W BT".

RE-RENEWED CORNER NO. 265

94

Section Corner to Secs. 25 & 36, T29S R7W, & Secs. 30 & 31, T29S R6W.
Found - Orig. 10", now 8" Laurel Snag, shows good scribing,
"S 3 T29S BT" N.33°E. 23.8 ft. **95**
Orig. S. W. BT., down, dozed out of position, shows good
scribing "S36 T29S".
All BT's. as recorded by Boyer, except N. E. BT., which
is now a Snag. - Ren. #41 & 53
No other Trees near to N. E.
Set Brass Cap at Corner & alongside squared & scribed Corner Post.
Mkd. Brass Cap County Surveyor's
Office, 1959

S25	S30	T29S
R7W	S31	R6W

No New Trees Scribed.

James W. Byron, Deputy
S. A. Blilow
April 27, 1959
C. S. File No. 49/139

96

$\frac{1}{4}$ Section Corner to Sec. 31, T29S R6W, & Sec. 36, T29S R7W.
Found - 1" Iron Pipe at Corner & Both Orig. BT's.
Find Stone at Corner chisled $\frac{1}{4}$.
Orig. S. W. BT., now Stump, shows good scar.
Orig. S. E. BT., now dead, shows good scribing "BT".
New BT's: 20" R. Fir bears S.11°E. 5.0 ft. scribed S31 $\frac{1}{4}$ CS BT.
8" W. Fir bears N.53°W. 44.1 ft. scribed $\frac{1}{4}$ S36 CS BT.

SEE ALSO
1887 CORNER
Vol. 1 P. 108