

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Marvin C. Ramsey
For J. H. Baxter &
July 20, 1959
C.S. File No.
51/32

1/4 Section Corner bet. Sections 22 and 27.
Determined the Corner Point from the only extant Original - *see Ren #33*
Bearing Tree, a D. Fir Snag 20" diam, bears S.45°W., 28 lks.
Set an Iron Pipe 3' long 1 1/2" diam., 28" in the ground, mkd.:
RS404 & Mark new bearing trees:
8" W. Fir bears S.68 1/2°W. 29 lks. dist., mkd. 1/4 S27 RS404 BT.
18" D. Fir bears N.57°W. 30 lks. dist., mks. 1/4 S22 RS404 BT.

97

*FO. I. R. 43 BT's
10/24 H.
Johnstone
M 97-54*

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
Nov. 2, 1960
C.S. File No. 49/139

West 1/4 Corner to Section 7.
Found - Brass Cap at Corner & W. P. N.82°43'W. 1.93 chs. (1924)
B. T's. gone, renewed BT's., now stumps. *see #47*
New BT's: 4" Laurel bears S.22°E. 74.0 ft. scribed 1/4 S 7 CS BT.
15" B.Oak bears N.13°E. 40.0 ft. scribed 1/4 S7 CS BT.

98

W. P. N.82°43'W. 1.93 ch. from W. 1/4 corner Section 7.
Found - Brass Cap at Corner & BT's. as recorded by Mensch, 1924.
All are now stumps. I open NE BT. & find good scribing "B".
New BT's: 7" R.Fir bears S.42°W. 31.0 ft. scribed W.P. CS BT.
10" R.Fir bears S.28°E. 40.4 ft. scribed W.P. CS BT.

98A

*"Destroyed By Laccine"
C.G. 62/1 - 8/24/82
C. Surveyor
Repair*

1/4 Corner to Sec. 5, T29-7W. & Sec. 32, T28-7W.
Found - 2" x 2" Stake at Corner & 27" B.Oak N.44°W. 36.0 ft., shows
good scribing "1/4 S32 BT". *REN. NO. 21*
26" Fir Stump bears S.79°W. 52.0 ft. We open near base &
find good scribing "T".
Stump Section of 30" B.Oak, shows old scar N.39°W. 28.0 ft.
Set - Brass Cap alongside Corner Stake & Mark County Surveyor's
Office, 1961
1/4 S32 T28S R7W
S 5 T29S
202
New BT: 6" R.Fir bears S.51°W. 25.4 ft. scribed 1/4 S 5 CSBT.

99

See renewal of this corner by Irving, Cor. No. 21. Refer also to
Corner No. 49. Not the same corner.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
April 1961
C.S. File No. 49/50

Renew Sec. 6, T29-7W. & Sec. 31, T28-7W.
Found - Both Fir BT's. Recorded by Mensch, each is now down.
We open & find good scribing.
Brass Cap (1924) not found.
Set Brass Cap Mkd:

CL	S31	T28	R7W	County Surveyor's
	S 6	T29		Office, 1961

New BT's: 6" Cedar bears N.31 1/2°E. 82.7 ft. scribed S31 T28SR7W CS BT.
12" R.Fir bears S.28 1/2°E. 99.7 ft. scribed S 6 T29S R7W CS BT.

100

1/4 Corner to Sec. 6, T29-7W. & Sec. 31, T28-7W.
Found - Brass Cap at Corner & Stump of S.E. BT., *REN. NO. 1*
Rotted Remains of N. W. BT. found.
New BT's: 5" W.Oak bears S.70°W. scribed 1/4 S 6 CS BT.
12" Ash bears N.9R W. 11.6 ft. scribed 1/4 S31 CS BT.

101

Section Corner to Sections 2 & 3, T29-7W. & Secs. 34 & 35, T28-7W.
Found - Geared Axle at Corner. Orig. 30", now 36" W.Oak N.73°E.
132 ft., shows good scar. I do not open.
Orig. 30", now 40" down Oak. We open & find good reverse
scribing, "B"(Record S.73°E. 159.7 ft.) We find should be
S.59°E. 102.0 ft.
If we use record dist. & bear. to locate Sec. Cor. from SE BT. it
wouldn't check with Real old Stump Section in NW. Quad.
New BT: 34" W.Oak bears N.24 1/2°W. 410.0 ft. This BT. scribed within
the last few years but not of record, See M 12 - 72. # 211

102

*See also
211*

RE-DEVELOPED CORNER

May 19, 1961