

Douglas County Surveyor's Record of
Government Corners Renewed

29 S T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

188
1/4 Corner Sections 1 & 12
Found - 1" O.D I.P. with copper plug stamped "RS 404" & BT's as recorded in Ren. #17, as follows
12" now 11" Maple S. 76 1/2° E. 10.7 Ft. alive - open & shows
1/4 S Scribe
8" Now 15" B. Oak N. 43° W. 27.0 ft. alive - open blaze decayed away no scribe fd.
Set - Brass Cap at Cor I" IP Mkd:

County Surveyors T. 29S R 7 W
Office, 1969 1/4 S 1
S 12

and Mk. new B.T.S.
14" D. Fir S. 27° W. 41.7 Ft. Mkd. 1/4 S12 CS BT
10" Myrtle N. 62 1/2° E. 24.1 Ft. Mkd. "1/4 S1 CS BT"
This Cor. lies on moderate N. E. slope approx. 100 ft. S. of Adams Creek Course S. E.
3-7-69

Vernon "Ray" Tracy
F. Jones & V. Perron
3-6-69
C. S. File #49/139

189
1/4 Corner to Sections 23 and 24.
Found - 14", now 16" D. Fir, N. 26 1/2° W. 17.2 ft., shows good scar.
24" D. Fir, now stump, S. 52 1/2° E. 32.3 ft., opened for scribe.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 7 W
Office, 1969 1/4 S 23 | S 24
New BT: 18" D. Fir N. 61° E. 29.0 ft. mkd: "1/4 S24 CS BT".
10/15/69

Section Corner to Sections 23 - 24 - 25 - 26.
Found - 1 1/2" Iron Pipe at Corner, Unrecorded.
Orig. 12" D. Fir, now stump, N. 16 1/2° W. 19.1 ft., scribe visible.
Orig. 24" Laurel, now dead, N. 84 1/2° E. 29.0 ft., scribe visible.
Unrecorded 13" D. Fir, now stump burnt face, scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 7 W
Office 1969 S 23 | S 24
S 26 | S 25
New BT's: 30" D. Fir N. 21° W. 117.3 ft. scribed "T29S R7W S23 CS BT".
15" D. Fir N. 59° W. 80.8 ft. scribed "T29S R7W S23 CS BT".
No other trees available for this corner.
10/15/69

191
1/4 Corner to Sections 29 and 32.
Found - G.L.O. Brass Cap at 1/4 corner, properly marked in 1924.
14" D. Fir, now dead, S. 1° E. 20.5 ft., shows good scar.)
10", now " D. Fir, N. 75° E. 70.0 ft., shows good scar.) See Ren. #67.
New BT: 7" D. Fir S. 59° W. 20.4 ft. scribed "1/4 S 32 CS BT".
This corner lies on E - W blazed line on steep, east slope, approximately 150.0 ft. from bench.
7/16/70

192
S. E. Corner D. L. C. No. 44.
Found - 1" I. Pipe, flush with ground, See Ren. #6.
12", now 14" W. Oak, N. 17 1/2° E. 75.2 ft., opened for scribe "44".
40" B. Oak N. 40° W., down & burnt.
Renewal - New BT: 12" Maple (S. trunk of triple Maple) N. 41° W. 87.5 ft.
scribed "SE DLC 44 CS BT".
9/9/70

193
1/4 Corner to Sections 8 and 9.
Found - 1955 G. L. O. Brass Cap at 1/4 Corner, properly marked.
Also Iron alongside. Ren. No. 57
GLO Trees: 25" D. Fir, N. 42 1/2° E. (Rec. S. 42 1/2° E) 33.0 ft., shows good scar.
22" D. Fir, now down, S. 60° W. 21.8 feet.
Co. Trees: 8" D. Fir, now 10", S. 87° E. 31.5 ft., shows good scar.
No trace of S.W. Bearing Tree.
New BT: 6" D. Fir S. 76° W. 30.2 ft. scribed "1/4 S8 CS BT".
10/19/70

John M. Powell
Frank Jones & W. Penley
C.S. File No. 49/139

J.W. Byron
Co. Surveyor
C.S. File
No. 54/115

John M. Powell
W. Penley & Jack H.
C.S. File No.
49/139

John M. Powell
&
Crew
C.S. File
No.
49/139

FD. OK 12/90
M 111-17
FO. OK 2/93 BY BEUTZ
M 116-49

FD OK 8/89
H. Johnson
M 101-60
FD OK 8/89
H. Johnson
M 101-60