

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Glenn Baughman for
Carl Summerlin
M 50 - 11 C.S. 55/306
July 1973

1/4 Corner Sections 6 and 7.

Found - 1924 GLO Brass Cap.

No bearing trees found.

New BT's - 2" White Fir, bears N.52°W., 1.65 ft., not scribed.

6" Alder, bears S.1°E., 185.1 ft. scribed N. 1/4 Cor. Sec. 7.

RE-RENEWED, SEE CORNER NO. #283

206

1/4 Corner Sections 7 and 18.

Found - Found and reset 1924 GLO brass cap.

12" Douglas Fir, bears S.65°W., 52.5 ft. Good face, no visible scribing.

New BT - 7" Douglas Fir, bears S.12 1/2°W., 2.2 ft. scribed 1/4 S.18 BT.

RE-RENEWED, SEE CORNER NO. #231

207

Center 1/4 Corner Section 7.

Found - 1" I.P. with a 2" Angle iron welded on side.

30" Cedar, bears S.87°W., 29.4 ft. Visible scribing
C 1/4 S7 BT.

This corner was erroneously set by survey M 6 - 14.

Set - 2" I.P. with brass cap mkd. C 1/4 Sec. 7, T.24S., R7W., W.M.

New BT's - 6" Douglas Fir, bears N.45°E., 11.3 ft. scribed C 1/4 S.7 BT.

8" Douglas Fir, bears S.42°E., 19.7 ft. scribed C 1/4 S.7 BT.

7/73

208

1/4 Corner for Sections 9 and 10.

Found - 1955 U.S. GLO iron pipe with brass cap properly mkd.

32" now 36" D.Fir, bears N.14°W., 44.2 ft. scribing visible on healing blaze.

The NE bearing tree is now down, scribing is visible on open blaze.

New BT - 29" D.Fir bears S.88°E., 62.1 ft. scribed "1/4 S10 CS BT".

Note - At this time we also find the two BT's marked by Boyer and Byron in 1953 (Ren. #54) approx. 300 ft. SE of the brass cap. We examined the remains of what was said to be the NE OBT and can find no evidence of any scribing.

Gary Langlitz
P. Earle
5/1/74
C.S. 56/51

209

Don E. Garrett
for: Mrs. Chard
C.S. 58/41 6/75

SE Corner D.L.C. #39

Set - 6' Steel fencepost 4' in ground.

See Ren. #75

RE-RENEWED, SEE CORNER NO. #213

210

Clell Goodwin
Gary Langlitz
Vic Cangie
Lenora Radig
10/21/75
CS 57/36

Sec. Corner to Sec. 34 and 35 T28-7 and Sec. 2 & 3 T29-7

Found: Geared axle at fence which has been generally accepted as the corner

From which: An orig. 30" now 40" white oak cut but reveal reverse scribe

"BT" bears N 73°E., 138.4 ft. call P. N 77°E., 132.0 ft)

A 37" was 34" white oak bears N 24 1/2°W., 408.6 ft (call by renewal #171: 1287

N 24 1/2°W., 410.0 ft)

A 40" down oak in the S E Quadrant with visible scribe marks does not fit call

FD. O.K. G. BO G. BAUGHMAN MBS-35

RE-RENEWED, SEE CORNER NO. #273

SEE #171 T28SR7W
#102 T29SR7W
211

211

Center West 1/16 of Sec. 21

Found: U.S.B.L.M. cadastral survey brass cap properly marked (1966)

BT's- A Fir snag 8 (now 9) inch diameter bears N 15°E., 11.6 ft. (rec N 13°E) scribed "CW 1/16 S21 BT"

An oak stump, 18" dia., bears S 8°E., 26.2 ft. (Rec. S.11°E., 27.4 ft.) Scribed "CW 1/16 S 21" stump cut flush with ground, portion of scribed tree setting on top. Stump enclosed in Galvanized metal cylinder, on edge of logging road.

Set-5/8" Dia. iron rod in a 46" dia. fir stump. Placed Co. Surveyors Office aluminium cap on rod and stamped "B.O.#1" bears S14"W, 16.9 ft.

Set-5/8" dia. iron rod in a 28" dia. fir stump. Placed County Surveyors Office aluminium cap on rod and stamped "BO #2". Bears N60 1/2°E., 41.0 ft.

A douglas fir, 29" dia. bears N54 1/2°E., 113.0 ft. tree blazed and scribed

"CW 1/16 S 21 CS BT"

11/3/75

L.E. Monrean
P.L.E.
J.H.C.
C.S. 57/39
11

212