

Douglas County Surveyor's Record of  
Government Corners Renewed

29

T. S.

7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

S.E. DLC #39 A.P.6 REN #75,76,198 & 210  
Found-3 pronged cedar 6 ft. dia. at base, blazed trunk only portion standing.  
bears N 52°W.204.6 ft.  
Note: Fence post set by Garrett not found, set temporary point  
From which;A 5/8" diameter iron rod set by Garrett (see CS58/41) bears south  
181.6 ft.  
A 1" iron bar with eye on top bears north 100 ft.(Ren#198) from which  
A 7" ash bears N 14°E,7.2 ft.blazed and scribed "WP AP 6 BT"  
Set-From temporary point at AP 6 DLC#39 (S.E. Cor) A witness point, north  
135.0 ft. Witness point is a brass cap stamped

213

L.E.Monrean  
P.L.E.  
J.H.C.  
CS 57/39  
12/9/75

COUNTY SURVEYORS OFFICE  
1975

T 29 S R 7 W  
W P  
135 feet  
South to  
A.P.6 DLC 39

From which; An ash,6" dia. bearsN38°W,60.5 ft. Tree blazed and scribed "W P  
A P6 CS BT"  
A red cedar,8" Dia. bears S79 1/2°W,25.0 ft. Tree blazed and scribed  
WP AP 6 CS BT"  
SET-Replace 5/8 Dia. iron rod set by Garrett (CS 58/41)with brass cap,  
witness point bears south, 181.6 ft. from a.p.#6 DLC 39.Brass cap mkd:

COUNTY SURVEYORS OFFICE  
1975

T 29 S R 7 W  
W P  
181.6 feet  
north to  
A P 6 DLC 39

From which; an ash, 17" dia. bears S 10°W,33.7 ft. Tree blazed and scribed  
"WP AP 6 DLC 39 CS BT" Tree is forked at base, bearing and distance  
recorded to base.  
A maple, 9" dia. bears N 61°E,18.7 ft. Tree blazed and scribed " WP AP 6 CS  
BT". Note: As AP 6 (SE Cor DLC 39) falls in Olalla Creek I did not  
remonument the corner the 1" bar set by Byron is one foot from the  
edge of badly erroded creek bank Compass Declination 12/9/75

214

1/4 Corner for Secs. 20 and 29.  
Set - 5/8" Iron Rod with Aluminum cap.

8/75

H. W. Johnstone  
For: Gordon McDowell  
August, 1975  
M 57-76

1/4 Corner for Secs. 19 and 20.

Found - 1924 GLO brass cap properly stamped, attached to a 1"x36" I.P.,  
approx. 18" above ground.  
Orig. 10" Fir, now 23" stump bears S.64°W., 4.6 ft. (rec. 4.0 ft.)  
I do not open for scribing.  
Orig. SE BT is gone.  
A R. Fir, 13" now a dead snag 15", bears N.14 1/2°W., 34.8 ft.  
(rec. N.16°W., 34.0 ft.) Ren. #144. Tree double blazed, scribing  
visible "S19 CS BT".

Renewal - As monument is 18" above ground and slightly loose, I reference  
position of cap and lower it to approx. 6" above ground at the  
referenced position.

New BT's - A 18" Cedar bears N.17 1/2°W., 35.2 ft. Tree double blazed and  
scribed "1/4 S19 CS BT".

This corner falls near north edge of cree bed (creek rerouted by beaver dam)  
and on south edge of road.

There are no trees suitable for scribing in Sec. 20. 1/10/77

1/4 Corner for Secs. 20 and 29.

Found - 5/8" I.R. with alum. cap. Ren. #214  
12" Cedar bears N.20°E., 37.0 ft. scribed 1/4S BT with a Rsbg.  
Lumber Co. tag that reads S.20°W., 37.0 ft. to corner.  
A 6" Fir bears S.60°E., 14.4 ft. scribed 1/4 S BT with a Roseburg  
Lumber Co. tag that reads N.63°W., 14.1 ft. to corner.  
Both trees are single blazed.

At corner point WE SET: Douglas County Surveyor T 29 S R 7 W  
1977

1/4 S 20  
S 29

We place orig. I.R. on the north side of our brass cap.

216

Larry Monrean  
K. Cheney  
P.L. Earle  
Jan. 10, 1977  
C.S. 59/29  
Douglas County Surveyors  
Office  
Mike Tompkins  
Vic Cangie  
Jan. 10, 1977  
C.S. 59/29  
Gary L. Langlitz

1/10/77