

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

221

1/4 Corner for Secs. 18 and 17.

Found - 1924 GLO brass cap firmly set and extending 8" above ground properly marked.

From which:

An orig. 30" now 40" White Oak bears N.81°E., 55.6 ft. (rec. N.77°E., 54.1 ft.), (Rec. per 1924 resurvey N.81°E., 54.1 ft.) This tree has split and half has fallen exposing area of orig. marks, no marks found due to rotten condition. Remainder of tree is alive.

And an Orig. 8" now 34" B. Oak bears S.36 1/2°W., 39.8 ft. (rec. S.40°W., 37.6 ft.)(rec. per 1924 resurvey S.66 1/2°W., 37.6 ft.) Tree is alive and well healed.

It appearing that the measurements taken in 1924 were to the face of the OBT's and not the centers, we determine that the orig. measurements agree closely at a point which bears S.23 1/2°E., 4.4 ft., from the found position of the GLO brass cap. For additional verification, we open the orig. SW bearing tree and find evidence of natural healing and fragmentary reverse scribe marks. We therefore replace the GLO brass cap with a 5/8" x 30" I. Rod with alum cap attached marked "DouglasCo. Surveyor" and RESET the GLO brass cap at the position dictated by record idstances from the centers of the orig. bearing trees. At the corner point, WE SET a 1" x 36" Iron pipe 28" in the ground, with brass cap attached marked as described in the official record of the 1924 resurvey. WE ADD the markings "CS 1977".

From which:

The orig. NE bearing tree, a 40" W. Oak bears N.77°E., 54.1 ft. Orig. SW bt, a 34" B. Oak bears S.42°W., 37.6 ft. (rec. S.40°W., 37.6 ft.).

and trees marked in 1924:

- A 25" now 27" B. Oak, alive and well healed bears S.35°E., 40.6 ft. (rec. S.34°E., 44.9 ft.)
- A 5" now 12" W. Oak, alive with no indication of previous blaze bears S.62°W., 34.8 ft. (rec. S.55°W., 36.3 ft.) We rescribe "1/4 S18 CS BT" on a double blaze.
- A 5/8" I. Rod with aluminum cap set as noted previously bears N.23 1/2°W., 4.4 ft.

1/31/77

East 1/4 Corner for Sec. 13, T.29-8.

222

Found - 1" I.P. approx. 1 ft. above ground with 1924 GLO brass cap properly stamped. From Which:

- A 24" now 34" Fir stump bears N.47 1/2°E., 18.5 ft. to face, 19.5 ft. to center (orig. N.44°E.,; 1924 Rec. N.45°E.).
- A 16" now 19" Fir, bears S.54 1/2°W., 12.5 ft. (1924 Rec. S.52°W.) Tree has well healed single blaze.
- A 8" now 10" Fir, stump bears N.85°W., 26.4 ft. (1924 Rec. N.87°W., 27.1 ft.) Stump rotted "BT visible.
- A 9" now 10" R. Fir bears N.87 1/2°W., 16.0 ft. Tree is tipped out, partially rotted. Open blaze, scribe visible " 1/4 S13 C.S." Ren. #137
- A 10" Fir, bears N.32°W., 15.2 ft. Tree has open single blaze, scribed "1/4 S13 BT". (1975 survey).

1/31/77

223

Section Corner for Secs. 12 and 13 only, T29-8.

Found - 1924 GLO brass cap properly stamped.

BT's Per 1855 Hathorn survey:

- A B. Oak 20" now 52" bears S.45°E., 50.9 ft. Tree has paint blaze.
- An Oak, down and rotted bears N.56°E., 25.7 ft. No scribing found.

BT's Per 1924 GLO survey:

- An Oak down and rotted bears S.57°W., 40.9 ft. No scribing found, outling of blaze visible.
- A Black Oak, 12" now 14" bears N.5°W., 22.4 ft. blaze rotting out.

BT Per Ren. #140:

- A 19" now 26" Pine bears S.62°W., 10.3 ft. Tree has well healed double blaze.

Renewal:

I double blaze and rescribe the 12" Black Oak scribed in 1924. Tree bears N.5°W., 22.4 ft. I blaze the area to the East of the old blaze and scribe "T29S R8W S12 CS BT".

2/3/77

Gary Langlitz, Doug. Co. Surveyor's Office
Karen Cheney
Jan. 31, 1977
C.S. 59/29

Larry E. Monrean, Doug. Co. Surveyors Office
P. L. Earle
K. Cheney
Jan. 31, 1977 and Feb. 3, 1977
C.S. 59/29

