

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29 T. S. R 7 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21851

243

R. B. Kimberling  
K. Cheney  
S. Flause  
Doug. Co. Surveyors Office  
June 13, 1977  
C.S. 59/34

Sec. Corner for Secs. 26 1/2, 26, 34 1/2, and 35.  
Found - A 1962 Douglas Co. Brass cap properly marked on a 1" x 30" I. Pipe 10" out of ground at a 45° angle. (apparently had slid down hill). Ren. #119  
A 1" x 27" I. Pipe buried along side cap.  
A conglomerate stone 6" x 12" x 10" buried 24" in ground.  
A 30" D. Fir now 30" bears S.31°45'E., 26.4 ft (Rec. as a 24" tree 1924) with visible healed blaze.  
A 30" D. Fir now 28" bears N.15°E., (Rec. N.12°45'E.) 29.7 ft. Recorded as a 20" tree in 1924 resurvey) visible healed double blaze.  
Set - Replace Douglas County Brass cap in proper position stamped "Reset 1977"  
A conglomerate stone 6" x 12" x 10" buried 24" under ground on East side of brass cap.  
A 1" x 27" I. Pipe on NE side of cap.  
No other trees available.

6/13/77

244

North 1/16 Corner SEcs. 18 and 17.  
No monuments or accessories found.  
Set - Location determined by single proportionate measurement. Set 3/4" x 24" I.P. flush in the ground on a moderate westerly slope, with anchor rod extended and brass cap marked:  
Douglas County Surveyor  
N 1/16  
S 18 | S 17  
T 29 S R 7 W  
1977

BT 's - A 15" D. Fir, double trunked, double blazed and scribed "N 1/16 S18 CS BT" bears N.79°W., 55.2 ft. to center of root crown.  
A 20" W. Oak scribed "N 1/16 S17 CS BT" on a double blaze bears N.34°E., 146.7 ft.  
Note: Corner located approx. 3 ft. north of an E-W fenceline in a natural opening. We place steel fencepost with survey marker witness sign 1 ft. North of the corner.

10/4/77

245

Center 1/4 Sec. 18  
No monuments or accessories found.  
Set - Location determined by intersection of lines between opposite 1/4 corners. Set 1" x 30" I.P. 25" in the ground with brass cap attached marked: Douglas County Surveyor  
T 29 S R 7 W  
S 1/4 S 18  
1977

BT 's - A 14" D. Fir scribed "C 1/4 S18 CS BT" on a double blaze bears S.84°W., 65.0 ft.  
A 24" D. Fir scribed "C 1/4 S18 CS BT" on a double blaze bears N.29°E., 66.7 ft.  
Note: Located along northerly edge of clearing. Placed steel fence post with survey marker witness sign attached one foot north of corner.

10/5/77

246

Center North 1/16 for SEc. 18.  
No monuments or accessories found.  
Set - By single proportion measurement set a 3/4" x 24" I.P. with 5/8" I.R. protruding from bottom and a brass cap attached 2" above ground marked: "Douglas Co. Surveyor" T 29 S R 7 W  
1977  
N 1/16 | C | S 18  
C

BT 's - A 14" D. Fir bears S.33°W., 164.4 ft. scribe "CN 1/16 S18 CS BT" on double blaze.  
A 7" S. Pine bears N.76 1/2°W., 60.7 ft. scribe CN 1/16 S18 CS BT on a double blaze.  
Note: Corner lies on a SE slope approx. 100 ft. North of an E-W fence line

10/5/77

Douglas County Surveyors Office  
Gary L. Langlitz  
Larry E. Monrean - P. L. Earle - S. J. Flause  
Berry Creek Project  
October, 1977  
C.S. 59/40

R M 3-8