

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29 T.S. R 7 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Howard Johnstone  
L.S. #498  
For: Roseburg Lbr. Co.  
June 29, 1984  
C.S. 58/296  
(and M 97 - 54  
10/2/84)

Section corner for Sections 16, 15, 21 and 22  
Found - 1957 and 1966 BLM cadastral brass cap.  
7" D. fir, N.67°W., 7.3 ft. good condition. 1966 BT.  
59" D. fir, N.58°E., 48.8 ft. now a stump. 1957 & 1966 CAD.  
24" D. fir, S.51°E., 53.5 ft. good condition. 1966 CAD.  
33" D. fir, S.24°W., 32.3 ft. good condition. 1966 CAD.  
New BT - 20" D. fir, S.84°E., 74.7 ft. scribed "T29S R7W S22 BT."  
Note: NW of section 15 has been recently clear cut. No remaining trees  
suitable for BTs. Corner is about 300 ft. west of road at  
corner of recent clearcut.

278

Howard Johnstone  
L.S. #498  
For: Roseburg  
Lbr. Company  
Oct. 2, 1984 M 97 - 54

Center 1/4 Corner for Section 22  
Set - 5/8" x 36" iron rod and alum. cap mkd. "LS 498".  
New BTs- 6" Cedar, S.68°E., 23.1 ft.  
4" fir, N.50°E., 18.6 ft.

279

Clifford Bryden  
For: Roseburg Lbr.  
May/June 1956  
M 2 - 46 and  
C.S. 42/158  
(This corner  
Recorded Jan. 15,  
1985 by this of-  
fice)

Section corner for Sections 10, 11, 14 and 15  
Found - Old original 18" laurel, S.18°W., 50 lks. found by R.C. Grant  
in 1951. This tree is down and rotted out.  
New BTs - 20" fir, N.36°E., 20.6 ft.  
14" fir, N.40°W., 34.9 ft.  
12" fir, S.79 1/2°W., 8.8 ft.  
22" fir, S.22°30'E., 8.5 ft.  
All scribed R.E. 3937 B.T.  
Set - 4" x 4" x 4 ft. fir post.  
NOTE: (The above corner description is from a "voided" survey M 2 - 46  
dated June 7, 1956. From evidence researched from M 2 - 46; C.S. 42/158;  
and M 5 - 41, it is felt that this corner is still valid and not "voided".  
BLM survey dated April, 1957 to May 1957, does not mention finding these  
BT's. January 15, 1985 - Virginia Laugen)

FIND OK 4/91  
M 113-6

280

Douglas County  
Surveyor Office  
Randall Smith  
Stephen Flause  
Dec. 11, 1985  
C.S. 62/29

Angle Point 1, DLC #44  
Found - Bearing objects found per Ren. #271:  
5/8" I. rod with alum. cap stamped "AP1A" bears N.84 1/2°W.,  
110.85 ft. (agrees with rec.)  
5/8" I. rod with alum. cap stamped "AP1B" bears N.84 1/2°W  
216.11 ft. (Rec. N.84 1/2°W., 105.26 ft.; 216.11 ft. is 105.26  
plus 110.85 ft.)  
5/8" I. rod bears N.20°W., 129.77 ft. (AP1C) alum. cap gone, I.R.  
bent northerly.  
22" now 24" dia. D. fir with PK nail bears N.20°W., 512.90 ft.  
(rec. N.20°W., 383.13 ft.; 512.90 is 129.77 plus 383.13 ft.)  
No monument for corner found. NE BT per Ren. #4 gone, taken out with new  
road construction.  
Set - A DCSO disk on an I.P. set 7 ins. below ground. Cap stamped:  
"Douglas County Surveyor T29S R7W S6 AP1 DLC 44 1985".  
New BT - 9" Apple double blazed and scribed "X BT" bears S.31 1/2°E.,  
86.7 ft.  
See sketch in C.S. file 62/29 to clarify distance discrepancies with record  
per "referenced corner" #271. (Reference sketch was in C.S.59/30).

FDOK - Heimbarger 5/3/56  
BY M. Heimbarger 7-93  
1993-0051  
AEB

281

Eugene A. Bloom  
L.S. 492  
For: Lucille Okeeffe  
March 1986  
M 100 - 50

Section corner for Secs. 6 and 7 only. (West)  
Found - 17" D. Fir with healed scar bears S.22°E., 50.8 ft. Ren. No. 141  
5/8" Iron Rod bears N.40°W., 38.51 ft. Ren. No. 270  
5/8" Iron Rod bears N.18 1/2°E., 39.88 ft. Ren. No. 270  
Set - Hub and tack for section corner secs. 6 and 7 only.  
Note: Witness Point for secs. 6 and 7 bears N.89°16'26"W., 119.40 ft.  
Found DCSO brass cap mkd. "WP"

282