

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

SEE CORNER NO. 58 34

SEC. COR. 21-22-27-28

Found 3 original B.T. and reset corner which is a 6" x 6" x 4"

Cedar post marked S 21, S 22, S 27, S 28 on respective sides.

60" Fir bears N 78° W 29.7 ft. mkd. S 21 T 29 S R 8 W B T 1581

26" Fir snag bears S 48° W 29.0 ft. mkd.  $\frac{1}{4}$ " S in bark

28" Fir bears S 82° E 23.8ft. mkd.  $\frac{1}{4}$ " S in bark

All being original trees.

New tree-24" Fir bears S 37° W 29.5 ft. mkd. S 28 T 29 S R 8 W B T 1581.

A. Boyer - Surv.  
Gee  
Hendrikson-Witnesses

April 1949

CS  
40/19 Z

Ben B. Irving  
Deputy Co. Surveyor  
RL Irving -Witnesses  
Louis Papst

October 28, 1938

C.S. 37/200  
C.S. 15/11

$\frac{1}{4}$  SEC. COR BETWEEN SECS. 9 and 16

Location identified by both orig. BTs badly rotted.

Set  $\frac{3}{4}$ " x 16" iron bar with 4" x 4" post alongside.

A Fir 22" diam. bears N 48° E 22.7 ft. blazed and scribed  $\frac{1}{4}$ " S 9 CS BT.

A Fir 18" diam. bears S 76 $\frac{1}{4}$ ° W 21.5 ft. blazed and scribed  $\frac{1}{4}$ " S 16 CS BT.

SEE CORNER NO. 91 35

SEC. COR. 8-9-16-17

Location identified from OBT. 36" Douglas fir N 20° E 30.4 ft. in good condition. Cedar BT N E only rotted stump remaining.

Set 4" x 4" x 36" Cedar Post for corner at Fence Corner

24" White Fir S 80° W 13.8 ft. marked T 29 S R 8 W S 17 CS BT

12" White Fir N 35° E 9.4 ft. marked T 29 S R 8 W S 9 CS BT

12" Doug. Fir S 40° E 29. ft. marked T 29 S R 8 W S 16 CS BT

SEE CORNER NO. 94 36

A. R. Evans  
Aug. 30, 1953  
Witnesses:

G. E. Johnson  
T. S. Harris  
For J. Harmonson  
File 41/249

$\frac{1}{4}$  corner secs. 28 and 29.

Found stump old BT. - 18" Cedar, N. 54., 13 lks. - scribe marks visible.

Set 4" x 4" x 36" Cedar Stake.

2 N.B.T.s.

10" White Fir, N: 28E., 8.2 feet, mkd. 13 - 28, RE 2741 BT.

8" Hemlock, West, 11.0 feet, Mkd. 9 - 29 S R. E. 2741 BT. / 38

37

Floyd C. Frear  
Paulin  
Garrett  
Skelton  
McWhorter

Oct. 1, 1954  
File 46/56.

N. W. corner of the F. J. Higginson D. L. C. No. 50.

Set a 1 $\frac{1}{2}$  inch by 48 inch G. I. P. from old B. T. stump (fir bearing #64 S. 65° E., 27 lks. - Scribing visible but rotten).

Blazed and Scribed New B. T.

18 inch Yew wood Tree, bearing S. 60° 30' W., 80.71 feet.

RE-RENEWED, SEE CORNER NO. 64  
SAME AS COR # 64

38

Arthur Boyer - Registered Professional  
Engineer No. 1581.  
Witnesses: Bernard Denn  
W. E. Howard  
Leo Denn

February, 1955.  
C. S. File No. 41/353 A.

$\frac{1}{4}$  sec. corner between sec. 19 (T29S, R8W) and sec. 24 (T29S, R9W).

Set this corner from O. B. T. in Section 19.

Drove a  $\frac{1}{2}$  inch X 20 inch iron pipe for corner from which a  $\frac{1}{2}$  inch X 23 inch iron pipe in fence line bears S. 89° 38' W., 20.0 feet and a 1 inch X 19 inch iron pipe in fence line bears N. 89° 38' E., 18.7 feet.

Corner is in County Road. Original B. T. in Sec. 19 still standing.

(See Also Calc - FB 48 Pg 12) Feb. 7, 1955.

RE-RENEWED, SEE CORNER NO. 164

39

Section corner to secs. 19 & 30 (T29S, R8W) and secs. 24 & 25 (T29S, R9W).

Found rock with cross on top 18 inches below ground surface on the east shoulder of County Road.

Set a  $\frac{1}{2}$  inch iron pipe 18 inches long on top of this cross, on rock, which is 13 feet west of the east side of road as fenced and it is 247.5 feet south of a  $\frac{1}{2}$  inch X 30 inch iron pipe which is driven in the fence on the east side of road. This  $\frac{1}{2}$  inch X 30 inch pipe is in line with a fence that runs west from the road.

Feb. 8, 1955.

RE-RENEWED, SEE CORNER NO. 163

40

Floyd C. Frear  
Arthur Boyer  
June, 1957  
Map file  
M 5 - 45.

Southwest corner of N. O. Watters D.L.C. No. 45.

Renewed from original B. T. (Pine)

Set a 2 $\frac{1}{2}$  inch x 4 foot iron pipe & rock at corner, from which:

a 7 inch R. Fir, S. 86° W., 15.4 feet.

a 5 inch W. Fir, S. 82° E., 21.7 feet.

RE-RENEWED, SEE CORNER NO. 127

41