

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97195

West  $\frac{1}{4}$  corner to sec. 21.  
Found geared axle and old B. T., 30 inch Fir S.20°E., 16 lks., in good condition.

Blazed and scribed new trees:

6" R. Fir, N.23°W., 123.6 feet mkd.  $\frac{1}{4}$  S 20 CS BT.

8" R. Fir, N.79°E., 219.9 feet mkd.  $\frac{1}{4}$  S 21 CS BT.

Variation, 21 $\frac{1}{2}$ .

**RE-RENEWED, SEE CORNER NO. #197**

42

James W. Byron,  
Dep. Co. Surveyor  
Jan. 22, 1954  
C. S. File No.  
45/235.

Renew Section Corner  $\frac{34}{32}$  T 28S R 8W  
 $\frac{35}{29S}$

Found Boyer's BT, 1935, 12 inch now 14 inch Fir, good condition, S 72°W 50.5 ft.  
None of the original BTs found. See Ren. No. 25

Set brass cap at corner marked County Surveyor's Office, 1957  $\frac{34}{32}$  T28S R8W  
 $\frac{35}{29S}$

New Bearing Trees: 14 inch Fir N 2°W 24.0 feet, scribed S 34 T28S, R8W CS BT.  
10 inch Fir N 17 $\frac{1}{2}$ °E 17.2 ft. scribed S 35, T28S, R8W CS BT.  
12 inch Fir S 10°E 30.5 ft. scribed S 2, T29S, R8W, CS BT.

**RE-RENEWED, SEE CORNER NO. #207**

43

James W. Byron  
M. Godfrey  
J. Fee  
August 6, 1957  
C.S. File No. 49/5

Section Corner to Secs. 6 & 5, T 29 S, & Secs. 31 & 32, T 28S, R 8 W. 44

Found - Original BT. 15 inch now 32 inch Fir stump, N.32°E., 14.0 ft. I open & find good scribing "B".

Also find parts of face with good scribing of the original 12 inch, now 15 inch Fir, S.42°E., I cannot find the original N.W. BT. & the original S.W. BT. is face down uprooted.

Set Brass Cap at corner marked: S.  $\frac{31}{65}$  T 28 S. R 8 W. County Surveyor's Office, 1957.

From Which:  
24 inch Fir bears S.56°E., 15.3 ft. scribed, T 29S. R 8W. S 5 CS BT.  
7 inch Laurel bears S.34 $\frac{1}{2}$ °W., 28.8 ft. scribed T29S, R8W. S 6 CS BT.  
6 inch Chinquapin bears N.51°W. 37.5 ft. scribed S 31 CS BT.  
6 inch R. Fir bears N.37 $\frac{1}{2}$ °E. 54.7 ft. scribed S 32 CS BT.

SEPT. 6, 1957

Section Corner to Secs. 5 & 4, T 29 S, and 32 & 33, T 28 S. 45

Found - Original 24 inch, now 32 inch Fir, S.40°W., 16.5 feet. I open & find good scribing, "S 5".

Find 15 inch, now 24 inch Fir N. 15°W., 28.4 ft, shows old face. I do not open. Checks bearings & distances, using old faces for distances.

Set Brass Cap at corner marked: S.  $\frac{32}{54}$  T28S. County Surveyor's Office, 1957.

New B.T. I rescribe (Bark) the original N.15°W. BT. New distance 29.4 feet, T.28S, R.8W., S 32 CS BT.

Bark Scribe 48 inch R. Fir N.7°E., 14.0 ft. T28S, R8W, S 33 CS BT.

Blaze & Scribe 9 inch Cedar S.9°E., 17.6 ft. T29S, R8W. S 4 CS BT.

The original S.W. bearing tree is in good condition.

SEPT. 9, 1957

R9W. R8W.

Renew Township Corner  $\frac{36}{16}$  T 28 S.  
 $\frac{31}{29 S}$

Found -  $\frac{3}{4}$  inch iron pipe at corner & one original BT. 15 inch now 24 inch rotted stump N.86 $\frac{1}{2}$ °W., 23.8 feet. Good scribing on chip of old face.

This corner renewed by C.A.S. (Coos Head Tbr. Co.) Aug. 1956, per notes on yellow tag. Original Bt checks bearing & distance to  $\frac{3}{4}$  inch iron pipe.

I find these BTs. (scribed, 1956)

7 inch R. Fir S.8°W., 22.8 ft. scribed BT S 1, T 29 S, R 9 W.

6 inch R. Fir N.76 $\frac{1}{2}$ °E., 21.0 ft. scribed BT S 31, T 28 S, R 8 W.

24 inch Cedar N.3°E., 86.9 ft. scribed BT S 31, T28 S, R 8 W.

SEPT. 10, 1957

$\frac{1}{4}$  Corner to Section 5, T.29 S. R 8W., and Section 32, T.28S. R8W. 47

Found - Both original BTs. 40 inch now 50 inch Fir S.40°W., 26 feet, shows old scribing " $\frac{1}{4}$  S BT" (Bark Scribed). Also newer scribing " $\frac{1}{4}$  S BT"

I open 5 inch now 14 inch W. Fir N.35°E, 12.5 feet. Good scribe mks. "BT".

BTs check record bearings & distances.

Set Brass Cap at corner marked:  $\frac{1}{4}$  S  $\frac{32}{5}$  T 28 S County Surveyor's Office 1957.  
T 29 S

I rescribe 14 inch W. Fir which bears N.35°E., 12.5 feet,  $\frac{1}{4}$  S 32 CS BT.

SEPT. 6, 1957