

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 8 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

58

Section Corner to Sections 21, 22, 27, & 28.
Found - BT's. as recorded by Boyer, 1949, except the N. W. BT. which
is now down. REN. No. 34
Scribed Stake at Corner.
The S. W. BT., now stump.
Set Brass Cap at Corner Mkd: $\frac{S21}{S28} \frac{S22}{S27}$ T29S R8W County Surveyor's
Office, 1958.
New BT's: 12" Cedar bears N.39°E. 42.4 ft. scribed S22 T29S R8W CS BT.
10" W.Fir bears N.14°W. 15.3 ft. scribed S21 T29S R8W CS BT.
12" W.Fir bears S.45°W. 8.3 ft. scribed S28 T29S R8W CS BT.

59

Section Corner to Sections 20, 21, 28, & 29.
Found - BT's. as recorded by Cole, 1923. REN #1
The S.W. BT., now Stump, shows good scribing.
N. E. BT. shows good Scar.
S. E. BT. shows good bark scribing, now dead.
Orig. S.27°E. BT. has Log at base, impossible to read.
Set Brass Cap at Corner Mkd: $\frac{S20}{S29} \frac{S21}{S28}$ T 29S R8W County Surveyor's
Office, 1958.
New BT's: 24" Double Laurel N.80½°W. 29.6 ft. scribed S20 T29S R8W CS BT.
18" R. Fir bears S.18°E. 14.8 ft. scribed S28 T29S R8W CS BT.
20" R. Fir bears N.22°E. 34.3 ft. scribed S21 T29S R8W CS BT.
14" Chinquipin S.69°W. 12.0 ft. scribed several yrs. ago,
partly covered.
Fence to North & to West Bears N.45°W. 3.0 ft.

60

¼ Section Corner to Sections 10 & 11.
Found - Orig. 40", now 52" Fir Snag N.38°W. 33.7 ft. I open near base
& find good scribing "BT".
No trace of Orig. N.E. BT.
Set Brass Cap at Corner Mkd.: ¼ S10/S11 T29S R8W County Surveyor's
Office, 1958
New BT's: 16" R.Fir bears N.22½°E. 113.1 ft. scribed ¼ S11 CS BT.
14" R.Fir bears S.76°W. 61.3 ft. scribed ¼ S10 CS BT.

61

¼ Section Corner to Sec. 6, T29S R8W, & Sec. 1, T29S R9W.
Found - Orig. 12", now 28" Fir Stump Corner Tree shows old scars, I
do not open.
Orig. 9", now 24" Fir Stump N.75°W. 13.9 ft., I open & find
good scribing "BT".
No trace of Orig. N. E. BT.
Set Brass Cap for Witness Corner to ¼ Corner Mkd. Brass Cap, Wit. Cor.
5' South to ¼ S1/S6 T29S County Surveyor's Office, 1958.
R9W R8W
New BT's: 12" R.Fir bears N.55½°W. 38.0 ft. scribed WC ¼ S1 CS BT.
12" R.Fir bears S.50°E. 76.9 ft. scribed WC ¼ S6 CS BT.

62

Section Corner to Secs. 6 & 7, T29S R8W, & Secs. 1 & 12, T29S R9W.
Found - Orig. 18", now 40" R.Fir N.75°E. 3.3 ft., shows old bark
scribing, "T29S". Also shows newer scribing.
Orig. 12", now 30" Fir Stump S.67°W. 40.2 ft., shows old bark
scribing "T29S R9W". Also shows newer bark scribing.
Stump Hole that checks bearing & distance for S.E. BT.
No Trace of N.W. BT.
Find 3" x 6" x 12" Sandstone at Corner.
Set Brass Cap at Corner Mkd: $\frac{S1}{R9W} \frac{S6}{S7}$ T29S County Surveyor's Office,
R8W 1958
New BT's: 12" R.Fir bears N.42°W. 59.2 ft. scribed S1 T29S R9W CS BT.
16" R.Fir bears S.59½°W. 44.5 ft. scribed S12 T29S R9W CS BT.
Rerbark scribe 40" R.Fir N.75°E. 4.2 ft. S6 T29S R8W CS BT.
14" R.Fir bears S.28°E. 42.7 ft. scribed S7 T29S R8W CS BT.

James W. Byron, Deputy County Surveyor
Chairmen: Milo Godfrey
S. A. Bilow
September, 1958
C. S. File No. 49/100

FD. B.C. 12/84
E. Bloom
M98-14

FD. 7/11/86
O.S.H.D.
C.S. 63/9