

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

James W. Byron, Deputy County Surveyor
Milo Godfrey
S. A. Bilow
September & October, 1958
C.S. File No. 49/100

FD. OK 12/84
E. Bloom
1178-13
7/3/61 OSND
2563/9

$\frac{1}{4}$ Section Corner to Sections 4 & 5. 69
Found - Orig. 50", now 56" R. Fir S. 70° E. 8.0 ft. I open near base &
find good scribing "B". This BT. is bark scribed above but
not old enough for Orig.
No trace of Orig. N. W. BT. found.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S5/S4 T29S R8W County Surveyor's
Office, 1958
New BT's: 8" W. Fir bears S. 75° W. 20.3 ft. scribed $\frac{1}{4}$ S5 CS BT.
14" R. Fir bears S. 46 $\frac{1}{2}$ ° E. 68.3 ft. scribed $\frac{1}{4}$ S4 CS BT.

Section Corner to Sections 5, 6, 7, & 8. 70
Found - 1" x 1" Iron Bar at Corner as recorded by Eppstein, ^{FD. OK L/S - R. HENDRICK}
24", now 36" Fir N. 76° E. 169.3 ft. (recorded 131.0 ft.), shows ^{M 84-19}
bark scribing "BT". ^{REN #10}
30", now 40" Down Fir S. 66 $\frac{1}{2}$ ° E. 34.0 ft., shows bark scribing "BT"
"S8"
No trace of Orig. S. E. BT. nor Eppstein's S. W. BT.
I do not set Brass Cap at Corner. Fence Thus:

New BT's: 8" R. Fir bears S. 56 $\frac{1}{2}$ ° W. 36.6 ft. scribed S7 T29S R8W CS BT.
11" Cedar bears S. 10° E. 53.9 ft. scribed S8 T29S R8W CS BT.
6" R. Fir bears N. 82° E. 21.7 ft. scribed S5 T29S R8W CS BT.
No suitable Trees near to N. W.

$\frac{1}{4}$ Section Corner to Section 7, T29S, R8W, & Sec. 12, T29S R9W. 71
Found - 20", now 30" Fir Stump S. 65° W. 71.5 ft., shows scribing "C".
24", now 30" Fir Stump S. 20° E., shows scribing "T".
I Do Not Find Rifle Barrel Set for Corner, 1922. REN. No. 11
Set $\frac{1}{2}$ " Iron Rod at Corner & 3" Under Road Surface.
New BT's: 15" Cedar bears S. 32° E. 68.3 ft. scribed $\frac{1}{4}$ S7 CS BT.
8" R. Fir bears S. 72° W. 63.0 ft. scribed $\frac{1}{4}$ S12 CS BT.

Section Corner to Sections 9, 10, 15, & 16. 72
Found - Orig. 40", now 48" Fir N. 10° E. 22.4 ft., shows good Orig.
bark scribing & more recent bark scribing. #177
Orig. 40", now 60" Down Fir S. 55° E. 3.3 ft., shows good Orig.
bark scribing & more recent bark scribing.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S9/S10 T29S R8W County Surveyor's
S16/S15 Office, 1958
New BT's: 12" R. Fir bears N. 41° W. 141.6 ft. scribed S9 T29S R8W CS BT.
5" Cedar bears N. 46° E. 8.0 ft. scribed S10 CS BT (5' above gr.)
3" R. Fir bears S. 58° W. 41.0 ft. scribed CS BT.
No trees near to S. E.

$\frac{1}{4}$ Section Corner to Sections 17 & 20. 73
Found - Rock at Corner with X on Top & both BT's as recorded by B.B.I.
BT's. show good scars. I do not open, now 30" diam.
Set Brass Cap at Corner & alongside Corner Stone Mkd. Cap $\frac{1}{4}$ S17
County Surveyor's Office, 1958 T29S R8W. S20
I do not scribe New BT's: SEE CORNER No. 14 FOR BEARING TREES.

Section Corner to Sections 16, 17, 20, & 21. 74
Found - Three Orig. BT's:
Orig. 5"; now 14" Fir Snag N. 85° E. 21.8 ft. This BT was
rescribed about 20 yrs. ago. I cut deeper & find Orig.
scribing "BT".
S. E. & S. W. BT's., now Stumps, but show good Scars. I do not open.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S17/S16 T29S R8W County Surveyor's
S20/S21 Office, 1958
New BT's: 12" W. Fir bears S. 76 $\frac{1}{2}$ ° E. 30.6 ft. scribed S21 T29S R8W CS BT.
6" Ewewood " S. 64° W. 35.2 ft. scribed CS S20 BT.
8" Ewewood " N. 56 $\frac{1}{2}$ ° W. 49.1 ft. scribed S17 T29S R8W CS BT.
5" Hemlock bears N. 16° E. 98.0 ft. scribed S16 T29S R8W CS BT.