

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron  
Milo Godfrey  
S. A. Blilow  
Oct. 8, 1958  
C. S. File No. 49/100

James W. Byron, Deputy County Surveyor  
Milo Godfrey  
S. A. Blilow  
October 10, 1958  
C. S. File No. 49/100

James W. Byron, Deputy  
Milo Godfrey  
S. A. Blilow  
Oct. 31, 1958  
C. S. File No. 49/100

**RE-RENEWED, SEE CORNER NO. #205 86**  
 $\frac{1}{4}$  Section Corner to Sections 22 & 27.  
 Found - Fir Tree, now 34" diam, N.77°W. 48.8 ft. showing good bark  
 scribing, "S", also good B. T. scar.  
 No evidence of Laurel to the S. W. remains.  
 Set Brass Cap Mkrd:  $\frac{1}{4}$  S22/S27 T29S R8W County Surveyor's Office,  
 1958  
 Blaze & Scribe following Trees:  
 12" Incense Cedar bears S.20°E. 7.7 ft. Mkd:  $\frac{1}{4}$  S27 CS BT.  
 6" D. Fir bears N.7°E. 14.8 ft., Mkd:  $\frac{1}{4}$  S22 CS BT.

**87**  
 Section Corner to Sections 22, 26, 27, & 23.  
 Found - Orig. 20", now 26" Rotted Snag S.47°E. 21.8 ft., I open  
 near base & find good scribing "BT".  
 Orig. 30", now 40" Fir Stump S.89°W. 33.0 ft., shows good  
 scar, I do not open.  
 No trace of othe Original BT's.  
 Set Brass Cap at Corner Mkd:  $\frac{1}{4}$  S22/S23 T29S R8W County Surveyor's  
 S27/S26 Office, 1958  
 New BT's: 10" R. Fir bears S.24 $\frac{1}{2}$ °E. 26.5 ft. scribed S26 T29S R8W CS BT.  
 6" R. Fir bears N.82°E. 4.0 ft. scribed S23 CS BT.  
 6" Chinquipin North 28.0 ft. scribed S22 T29S R8W CS BT.  
 9" Chinquipin S.65°W. 19.0 ft. scribed S27 T29S R8W CS BT.

**88**  
 $\frac{1}{4}$  Section Corner to Sections 23 & 26.  
 Found - Orig. 40", now 58" Down Fir. Open old scar & find good  
 scribing "B".  
 No trace of Orig. N. E. BT.  
 Set Brass Cap at Corner Mkd:  $\frac{1}{4}$  S23 T29S R8W County Surveyor's  
 S26 Office, 1958  
 New BT's: 30" R. Fir bears S.31°W. 17.0 ft. scribed  $\frac{1}{4}$  S26 CS BT.  
 12" Cedar bears N.29°E. 39.7 ft. scribed  $\frac{1}{4}$  S23 CS BT.  
 Note: Corner under 4' down Fir.

**89**  
 $\frac{1}{4}$  Section Corner to Sections 23 & 24.  
 Found - Orig. 20", now 34" Cedar S.10°E. 11.9 ft., previously  
 opened shows parts of good scribing on partly rotted  
 face "4".  
 No trace of Orig. S. W. BT. which would be in Creek.  
 Set Brass Cap at Corner Mkd:  $\frac{1}{4}$  S23/S24 T29S R8W County  
 Surveyor's Office, 1958.  
 New BT's: I rescribe 34" Cedar S.10°E. 12.7 ft.  $\frac{1}{4}$  S24 CS BT.  
 32" R. Fir bears S.55°W. 30.2 ft.

FD. #K  
11/10/80  
H. JOHNSTONE  
M81-75

**90**  
 $\frac{1}{4}$  Section Corner to Sections 16 & 17.  
 Found - Orig. 30", now 38" W. Oak N.85°E. 79.9 ft., I open & find  
 good scribe mks. "BT".  
 No trace of Orig. S. W. BT.  
 Find 16"x 16"x 8" Stone at Corner.  
 Set Brass Cap at Corner Mkd:  $\frac{1}{4}$  S17/S16 T29S R8W County Surveyor's  
 Office, 1958  
 (Doubtful)  
 New BT's: 12" Cedar bears N.18°E. 30.6 ft. scribed  $\frac{1}{4}$  S16 CS BT.  
 8" Cedar bears S.72°W. 70.0 ft. scribed  $\frac{1}{4}$  S17 CS BT.  
 Anchor Post bears N.85°W. 10.5 ft. Posts to North.

FD. -0540  
1/10/80  
C.S. 49/100

Reference  
see also Book 4 pg 12  
IN THIS...

**91**  
 $\frac{1}{4}$  Section Corner to Sections 9 & 16.  
 Found -  $\frac{3}{4}$ " x 16" Car Brake Lever Arm at Corner & Both BT's. as  
 recorded by B.B.I.: REN. NO. 35  
 18", now 24" Fir Stump S.76 $\frac{1}{2}$ °W. 21.5 ft., I open & find  
 good scribing "BT".  
 22", now 26" Fir shows good scars, N.48°E. 22.7 ft. I do  
 not open.  
 Also find "+ B0" on 10" x 10" x 4' Stone bears N.25°E. 13.3 ft.  
 Set Brass Cap at Corner & alongside Lever Mkd:  $\frac{1}{4}$  S9 T29S R8W  
 County Surveyor's Office S16 1958  
 New BT: 28" R. Fir bears S.34 $\frac{1}{2}$ °E. 21.6 ft. scribed  $\frac{1}{4}$  S16 CS BT.

**RE-RENEWED, SEE CORNER NO. #176**

FD. 7/1/86  
0540  
C.S. 49/100  
C.S. 63/19