

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R 8 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Renew Tr. 50 109
 AP 3 T29S R8W
 AP 2 Found - Brass Cap at Corner & N.E. BT., now snag.
 Tr. 51 shows good scar. S.E. BT. gone.
 New BT's: 8" R.Fir N.12°E. 28.7 ft. scribed AP 3 Tr 50 CS BT.
 R.Fir S.16°E. 10.9 ft. scribed AP 2 TR 51 CS BT.

COR. REFERENCED 11-2-81 BY R.E. QUIBELL
 DUE TO PENDING RD. WORK
 SECS. 59/30

Corner to S 6 T29S R7W 110
 S 7
 Found - Brass Cap at Corner. N.E. BT. now stump, shows old face.
 S.E. BT. O.K. & at edge of Roadway.
 New BT: 10" R.Fir bears S.22°E. 50.8 ft. scribed S 7 T29S R7W CS
 Note - County Road 16.0 ft. South of Corner. Also 1" I.P.
 Bears S.1°W. 47.0 ft.

RE-RENEWED CORNER NO. #200

FD. OK 1-96 BY DeGroot 1996-0064
 Renew Corner to Sections 1 and 12 only, S 1
 T29-8W S12 111
 Found - Brass Cap at corner & both BT's., now stumps. Sec #22
 N.W. BT. shows good scribing.
 New BT's: 10" R.Fir bears S.21½°E. 23.3 ft. scribed S7 T29S R7W CS BT.
 13" B.Oak bears N.55°E. 21.4 ft. scribed S7 T29S R7W CS BT.

Renew Corner S 7 T29-7W 112
 S18
 Found - Brass Cap at Corner. N.E. BT. shows scribing, now dead.
 S.E. BT. O.K., shows good scar.
 New BT: 19" R.Fir N.49°E. 17.7 ft. scribed S 7 T29S R7W CS BT.

Renew Corner S 12 T29S R8W 113
 S13
 Found - Brass Cap at Corner & both BT's. S.W. BT. in poor condition. #147
 New BT: 19" Pine bears S.62°W. 10.3 ft. scribed S13 T29S R8W CS BT.

Renew Corner S25 T29S 114
 R8W S36 R7W
 Found - Orig. 40", now 44" Fir N.59°W. 108.2 ft., shows good scar.
 Orig. S.W. BT., down. Also find Brass Cap at Corner &
 at East edge of 4.0 ft. down BT.
 New BT's: 10" Cedar bears N.37°W. 32.5 ft. scribed S25 T29S R8W CS BT.
 7" Fir bears S.28°W. 6.5 ft. scribed S36 CS BT.

Renew Corner to T29S R8W S36/S31 R7W T29½S 115
 Found - Brass Cap at Corner & both BT's. N.E. BT., now stump,
 shows scribing. We open N.W. BT. & find good scribing.
 New BT's: 13" R.Fir bears N.15°E. 33.7 ft. scribed T29½S R7W S31 CS BT.
 8" W.Fir bears S.72°W. 37.1 ft. scribed T30S R7W.S6 CS BT.

Renew T29S R8W Found - Cedar S.56°E. 17.5 ft. 116
 S36 Cedar N.27°E. 31.0 ft.
 T30-8W S 1 / S 6 T30-7W Both trees had been previously
 opened. Found old axe work on S.E. tree, but scribing has rotted.
 Evidence of corner being used. Corner also checks bearing & distance
 from 36, 31 & 6. (7.08 chains)
 Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R8W
 Office, 1962 S36
 T30-8W S 1/S 6 T30-7W
 Rescribed O.BT: 36" Cedar S.56°E. 12.5 ft. T30S R7W S6 CS BT.
 New BT's: 14" Hemlock N.1°E. 10.7 ft. T29S R8W S36 CS BT.
 14" Cedar S.71½°W. 21.4 ft. T30S R8W S1 CS BT.

James W. Byron, Deputy County Surveyor
 Dale McFarland and John Powell
 May and June 1962
 C. S. File No. 49/139