

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

123

Sec. Corner to Sections 11 - 12 - 13 - 14.

Found - G.L.O Brass Cap, 1924, properly marked.

18" B.Oak S.78°W. 8.6 ft., now gone.

9" Fir, now down. N. 64° E. 11.9 ft., found scribing "BT".

12" Fir, now 15", S. 82° E. 13.2 ft., shows good scar.

10", now 18" Fir, S. 66° W. 4.6 ft., shows good scar.

7", now 10" Fir, N. 33° W. 9.2 ft. This tree leaning badly.

New BT's: 13" D. Fir N. 40° E. 16.5 ft. mkd. T29S R8W S12 CS BT.

9" D. Fir N. 72° W. 15.9 ft. mkd. T29S R8W S11 CS BT.

RE-RENEWED, SEE CORNER NO. #169

124

1/4 Corner to Sections 11 and 12.

Found - Orig. 12", now 17" Laurel, S. 89° E. 44.9 ft., opened for scribe "1/4".

Orig. 30", now 40" D. Fir, N. 3° W. 19.8 ft. This tree badly cut up on face.

Set - Brass Cap at Cor. Mkd: County Surveyors Office 1966 T29S R8W S11/S12

New BT's: 9" Laurel S. 49° E. 16.1 ft. mkd. 1/4 S12 CS BT.

7" Hemlock N. 76° W. 9.5 ft. mkd. 1/4 S11 CS BT.

RE-RENEWED, SEE CORNER NO. #180

John M. Powell
Frank Jones & C. Stone
Nov. 28, 1966
C. S. File No. 5M/38

125

Section Corner to Sections 1 - 2 - 11 - 12.

Found - G.L.O. Brass Cap, 1924, properly marked.

40" D. Fir, now Stump, N. 26° E. 25.7 ft.

40" Cedar, now down, S. 75° W. 27.1 ft., opened for scribe.

12", now 18" Fir, N. 15° W. 31.7 ft., shows good scar.

No trace of S. E. BT.

New BT's: 18" Cedar N. 41° E. 55.0 ft. mkd. T29S R8W S 1 CS BT.

14" D. Fir S. 67° W. 59.3 ft. mkd. T29S R8W S11 CS BT.

19" W. Fir S. 16° E. 37.1 ft. mkd. T29S R8W S12 CS BT.

FD. Report
O.S.H.O. - 7/11/66
O.S. 63/19

FD. OK. R. Kimberling
7-81 - M 88-16
18-9 By cc. ST. Hwy Dept.
11-3

RE-RENEWED, SEE CORNER NO. #209

126

1/4 Corner to Sections 1 & 12.

Found - G.L.O. Brass Cap at 1/4 Cor., properly marked in 1924.

36" Fir, now stump, N. 59° E. 13.2 ft.

16" Fir, now down, N. 71° W. 33.9 ft., shows good scar.

12" Maple, now 16", S. 39° E. 31.7 ft., shows good scar.

New BT's: 11" Maple N. 18° E. 37.5 ft. mkd. 1/4 S 1 CS BT.

17" D. Fir S. 86° W. 23.0 ft. mkd. 1/4 S12 CS BT.

RE-RENEWED, SEE CORNER NO. #181

127

S.W. Corner D. L. C. No. 45.

Found - 2 1/2" I. Pipe and Stone at D.L.C. Corner. See Ren. #41.

Orig. 24" Pine, now Stump, N. 28 1/2° E. 40.9 ft., Tree opened.

Orig. 40" Fir, now Stump, N. 76° E. 46.9 ft., shows good scar.

7", now 11" D. Fir, S. 86° W. 15.4 ft, bark scribed "C BT" visible.

5", now 11" W. Fir, S. 82° E. 21.7 ft., shows good scar.

Reblazed & Rescribed: 11" D. Fir S. 86° W. 15.4 ft. mkd. "SW DLC 45 CS BT."

FD. 1978
O.S. 51. Hwy
Dept. 588 M-3

128

N. W. Corner D. L. C. No. 45.

Found - G.L.O. Brass Cap, 1924, properly marked.

8", not 15" B.Oak, S. 69° E. 62.7 ft., opened for scribe "5".

12" Pine (No trace of this BT).

New BT's: 17" B.Oak N. 48° E. 29.4 ft. mkd. NW DLC 45 CS BT.

Reblzd. & Rescrd: 15" B.Oak S. 69° E. 62.7 ft. mkd. NW DLC 45 CS BT.

129

Sec. Cor. to Secs. 35 & 36, T28-SW. & Secs. 1 & 2, T29-SW.

Found - G.L.O. Brass Cap at Cor., properly marked in 1924.

12", now 14" B.Oak, N. 66° E. 128.0 ft., rotten face, reverse scribng.

8", now 11" W.Oak S. 20° E. 91.7 ft., shows scar.

No trace of N.W. nor S.W. BT's.

New BT's: 9" Dbl. W. Oak S. 15° W. 86.0 ft. mkd. T29S R8W S2 CS BT.

9" D. Fir N. 14° E. 29.4 ft. mkd. T28S R8W S36 CS BT.

No trees available in N.W. Quad. This Corner lies 1.5 ft. S.W. of Fence Corner.

