

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 8 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

130

1/4 Corner to Sec. 36, T28-SW. & Sec. 1, T29-SW.  
Found - G.L.O. Brass Cap, properly marked in 1924.  
No trace of 1924 Bearing Trees. Evidently removed when fence was put in.  
(This corner lies North of fence Corner 1.5 feet.  
Orig. 20" B. Oak, now down, S. 69° E. 51.5 ft., opened for scribe, "S".  
Orgg. 30" W. Oak, now down, N. 8° W. 63.4 ft.  
New BT's: 6" D. Fir S. 42° E. 59.0 ft. mkd. 1/4 S 1 CS BT.  
18" D. Fir North 45.7 ft. mkd. 1/4 S 36 CS BT.

131

Section Corner to Sections 13 - 14 - 23 - 24.  
Found - G.L.O. Brass, properly marked in 1924.  
6", now 8" Cedar, N. 40° E. 5.9 ft., scribe visible T29SR8W S13 BT.  
38", now 40" Fir, S. 37° E. 31.7 ft., shows good scar.  
8", now 11" D. Fir, N. 7° W. 10.6 ft., shows good scar.  
10" Laurel S. 81° W. 30.4 ft. Tree had been badly cut up & rotted.  
New BT: 10" Cedar S. 36 1/2° W. 33.0 ft. mkd. T29S R8W S23 CS BT.  
(FD. 4/26/77 - CONDITION REPORT - C-5-59/31 G. LANGRISH, OFFICE)

132

1/4 Corner to Sections 13 and 14.  
Found - G.L.O. Brass, properly marked in 1924, but out of ground.  
Orig. 30", now 37" D. Fir, S. 12° W. 42.9 ft., bark scribed "1/4 S".  
16" D. Fir, now Snag, N. 89° E. 5.9 ft., opened for scribe "1/4" 13".  
22", now 27" D. Fir, N. 34° W. 13.9 ft., shows good scar.  
Reset - Brass Cap using all bearing & distances to BT's.  
New BT: 7" D. Fir S. 55° E. 38.4 ft. mkd. 1/4 S13 CS BT.  
(FD. 5/2/77 - CONDITION REPORT - C.S. 59/34 - L. MANREAN - OFFICE)

133

1/4 Corner to Sections 9 and 10.  
Found - 1/2" I. Rod at 1/4 Corner, See Ren. #27.  
30", now 33" Hemlock N. 70 1/2° W. 55.7 ft., shows good scar.  
48" D. Fir S. 46° E. 37.6 ft., bark scribed "1/4 S10 CS BT".  
Set - Brass Cap alongside I. R. Mkd: County Surveyor's T 29 S R 8 W  
Office, 1967 1/4 S 9 | S 10  
New BT: 15" Cedar S. 37° E. 11.4 ft. mkd. 1/4 S10 CS BT.  
March 23, 1967

134

1/4 Corner to Sections 28 and 33.  
Found - Scribed Post at 1/4 Corner, "1/4 S28, 1/4 S33", Ren. #30.  
12", now 17" D. Fir, N. 37° W. 9.0 ft., scribe marks visible, but not legible.  
14", now 17" D. Fir, S. 10° E. 18.6 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 8 W  
Office 1/4 S 28  
1/4 S 33

Bearing Trees is good condition. No new BT's. needed.

135

Section Corner to Sections 27 - 28 - 33 - 34.  
Found - Square Post at Sec. Corner, See Ren. #31.  
Also unrecorded 3/4" Iron Pipe.  
32", now 34" D. Fir, N. 65° E. 53.5 ft., shows pitched over face.  
50" D. Fir, now down 50", S. 63 1/4° E. 23.7 ft.  
22", now 28" W. Fir, S. 22 3/4° W. 59.7 ft., scribe visible "S".  
38" D. Fir, now down 38", N. 47° W. 27.0 ft., scribe visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 8 W  
Office S 28 | S 27  
1967 S 33 | S 34  
New BT's: 13" W. Fir S. 49° E. 9.0 ft. mkd. T29S R8W S34 CS BT.  
24" W. Fir N. 67 1/2° W. 25.9 ft. mkd. T29S R8W S28 CS BT.  
March 24, 1967

John M. Powell  
Frank Jones & Cliff Stone  
November and December, 1966  
C. S. File No. 54/38

FD. OK  
1-10-86  
A. JOHNTANE  
M 79-15

OWNER NO. #175