

Douglas County Surveyor's Record of
Government Corners Renewed

29

T.S.

8

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

162

Bruce A. Shaner
For: B.L.M.
Nov. 26, 1975
M 58 - 76
C.S. 58/82

Center 1/4 for Section 13.
Set - Iron post, 28" long, 2 1/4" diam. 20" in ground
with brass cap mkd. T29S R8W W.M.
C 1/4 S13
1975

from which:

A fir, 12" bears N.15°W., 27 lks. dist., mkd.
C 1/4 S13 BT.
A fir, 12", bears S.25°W., 129 lks. dist., mkd.
C 1/4 S13 BT.

FD OK 5/2/77. L. MONREAN - Co. Surveyors Off. C.S. 59/84

11/26/75

163

SE corner for Sec. 24, T29-9

Set - 1/2" x 10" R.R. Spike in black top. Set 5/8" x 42" I.R. at
right angles to section line. See also Ren. #40

Herbert Northcraft
For: James Atteberry
July-Aug. 1976
M 61 - 18

1/4 Corner for Section 24, East side, T29-9.

Did not dig up Co. Road but found witness corners and witness tree as
shown on C.S. M 61 - 2. See Ren. #39

Set - 1/2" R.R. Spike in black top.

FD OK PER ROGERS, P.
12-89 SEE 1990-0004

7-8/76

164

165

Burton Holt
For: Sun Studs Inc.
Sept. 1976
M 61 - 78

1/4 Corner for Secs. 33 and 34.

Found - Iron pipe. (unrecorded)

20" Madrone, bears N.13 1/2°E., 8 lks. (orig.)

Set - 1" x 40" Iron pipe.

9/76

168

East 1/4 Corner for Sec. 13 only.

Found - 1" I.P. approx. 1 ft. above ground with 1924 GLO brass cap
properly stamped. From which:

A 24" now 34" Fir stump bears N.47 1/2°E., 18.5 ft. to face,
19.5 ft. to center (orig. N.44°E.; 1924 Rec. N.45°E.)
A 16" now 19" Fir, bears S.54 1/2°W., 12.5 ft. (1924 Rec. S.52°W.)
Tree has well healed single blaze.
A 8" now 10" Fir, stump bears N.85°W., 26.4 ft. (1924 Rec. N.87°W.,
27.1 ft.) Stump rotted "BT" visible.
A 9" now 10" R. Fir bears N.87 1/2°W., 16.0 ft. Tree is tipped
out, partially rotted. Open blaze, scribe visible "1/4 S13
CS" Ren. #160
A 10" Fir, bears N.32°W., 15.2 ft. Tree has open single blaze.
scribed "1/4 S13 BT". (1975 Survey).

1/31/77

167

Section Corner for Secs. 12 and 13 only. East side.

Found - 1924 GLO brass cap properly stamped.

BT's Per 1855 Hathorn survey:

A B. Oak 20" now 52" bears S.45°E., 50.9 ft. Tree has paint blaze.
An Oak, down and rotted bears N.56°E., 25.7 ft. No scribing found.

BT's Per 1924 GLO survey:

An Oak down and rotted bears S.57°W., 40.9 ft. No scribing found,
outline of blaze visible.
A Black Oak, 12" now 14" bears N.5°W., 22.4 ft. Blaze rotting out.

BT Per Ren. #113:

A 19" now 26" Pine bears S.62°W., 10.3 ft. Tree has well healed double
blaze.

Renewal:

I double blaze and rescribe the 12" Black Oak scribed in 1924. Tree
bears N.5°W., 22.4 ft. I blaze the area to the East of the old
blaze and scribe "T29S R8W S12 CS BT"

2/3/77

Larry Monrean, Doug. Co Surveyors Office
P. L. Earle
K. Cheney
Jan. 31, 1977 and Feb. 3, 1977
C.S. 59/29

2/77