

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 29 T. S. R 8 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

180

1/4 Corner for Secs. 11 and 12.
 Found - A 1" Iron pipe extending 16" above ground with properly marked GLO 1966 brass cap.
 No trace of orig. corner post.
 An orig. 30" D. Fir, now a 40" stump, no markings found, bears N.3°W., 19.8 ft.
 Remains of an orig. BT, a 12" Laurel, now a 17" diam. 6 ft. tall stump previously opened, no markings visible, bears S.89°E., 46.3 ft. (Rec. S.89°E., 44.9 ft.)
 A 9" Laurel, now 10" and uprooted, root hole bearing approx. S.47°E., 14.6 ft. scribing "1/4" S12 CS BT" visible on unhealed double blaze. Ren. #124
 A 7" Hemlock, now 9" diam., 6 ft. tall stump with well-healed double blaze bears N.71°W., 9.5 ft. (Rec. N.76°W., 9.5 ft.)
 Set - At the position of the found 1966 monument and the exact corner point, we reset said 1966 monument to extend two inches above ground.
 New BT's- A 7" D. Fir, scribed "1/4 S12 CS BT" on a double blaze, bears S.43°E., 34.3 ft.
 A 8" G. Fir, scribed "1/4 S11 CS BT" on a double blaze bears S.4°W., 64.6 ft.
 Corner located in logged area. Placed location poster approx. 175 ft. west of logging road. Placed survey marker post and sign approx. one foot east of the corner.

10/2/78

181

1/4 Corner for Secs. 1 and 12.
 Found - A properly marked GLO 1924 brass cap on a 1" I.P. firmly set, extending 8" above ground.
 The remains of an orig. BT, a 24" Fir, now a badly decayed 36" stump with no markings bears N.59°E., 13.2 ft.
 No trace found of orig. SE Laurel BT.
 A 1924 BT, a 12" now 16" Maple alive with well healed single blaze bears S.39°E., 31.7 ft.
 A 16" D. Fir, now blown down with well healed single blaze bears N.71°W., 33.7 ft.
 An 11" now 13" Maple, alive with scribing "1/4 S1 CS" visible on partially healed double blaze, bears N.21°E., 34.6 ft. (Rec. N.18°E., 37.5 ft.) Ren. #126
 A 17" D. Fir, now an 18" blowdown with partially healed double blaze bears S.86°W., 23.0 ft.

No new monument set.

New BT - A 22" D. Fir scribed "1/4 S1 CS BT" on a double blaze, bears N.84°E., 29.7 ft.

Corner located beneath 36" Fir windfall.

10/2/78

182

Center East 1/16 Corner for Sec. 12.
 Found - An axle, 5 in. diam., 16" above ground bears N.74°E., 12.69 ft. dist. from proper corner. No record.
 Set - A 1 1/2" x 36" Iron pipe with brass cap marked "Douglas County Surveyor" T29S S12 C—C E 1/16 R8W 1978". Cap set at point one-half dist. between center 1/4 and E 1/4 S12.
 BT's - A 9" White Oak bears S.63°W., 14.5 ft. dist. marked "CE 1/16 S12 CS BT" in a double blaze.
 A 12" D. Fir bears S.57°E., 49.8 ft. dist. marked "CE 1/16 S12 CS BT" in double blaze.
 A steel post bears North, 1 ft. dist. with Surveyors marker sign attached.

12/18/79

183

Center 1/4 Corner for Sec. 12.
 Found - A 1" Alum tube covering a iron rod bears N.69°E., 19.33 ft. dist. from proper corner. Rod and tubing extend 18" above ground.
 Set - A 1 1/2" x 36" I.P. with brass cap marked "Douglas County Surveyor" T29S C 1/4 + S12 R8W 1978", buried 35" in the ground. Corner set by intersection N & S 1/4 and W & E 1/4 corners.
 BT's - A 10" D. Fir bears S.4 1/2°W., 14.4 ft. marked "C 1/4 S12 CS BT" in a double blaze.

Gary L. Langlitz, Douglas County Surveyors Office
 Frank C. Silagy
 Terrie Plouff
 October 2, 1978
 C.S. 60/17

Gary L. Langlitz
 Karen Reed
 Virginia Laugen
 Deloris Keady
 Doug. Co. Surveyors
 Office
 Dec. 18, 1978.
 C.S. 60/24 e
 C.S. 59/41