

Douglas County Surveyor's Record of
Government Corners Renewed

T 29

T. S.

R 8

R.W.W.M.

MOSE-CHAPMAN CO., EUGENE, ORE. 91881

Ronald Geisler
For: Champion
International
M 109 - 72
C.S. 63/113
March 1990

1/4 Corner for Sections 2 and 11

210

Found - 1980 BLM 3 1/4" BCIP, 5" above ground.
20" burned oak snag, 15 ft. tall, bears N.3°E., 112.7 ft. (Rec. 111.0 ft.) Rotted face. (1935)
14" W. oak bears S.18 1/2°W., (Rec. S.19 1/2°W) 129.0 ft. Partial scribing visible. (1935)
Burned Fir stump bears N.39°E., 11.2 ft. (1954) Ren. #154
Burned Fir stump bears S.29°W., 12.0 ft. (1954)
18" B. Oak bears N.28 1/2°E., 31.7 ft. (Rec. 31.2 ft.) Closed face.
New BTs - 9" Fir bears S.23°W., 48.49 ft. scribed 1/4 S11 BT.
23" Fir bears S.88°W., 143.89 ft. scribed 1/4 S11 BT.
No BTs available in the SE quadrant.

3/16/90

1/4 Corner for Sections 26 and 27

211

Set - 5/8" x 48" iron rod and alum. cap. Marked "1/4 27|26"
BTs - 12" Fir N.15°W., 24.0 ft. scribed "1/4 S27 BT"
14" Fir S.56°W., 29.3 ft. scribed "1/4 S27 BT"
7" Fir N.83°E., 20.9 ft. scribed "1/4 S26 BT"
13" Fir S.65°E., 33.0 ft. scribed "1/4 S26 BT"

212

Section Corner for Secs. 26, 27, 34 and 35 (Corner Report Only)

Found - 1958 County brass cap. Ren. No. 77
30" Cedar N.60°W., 2.0 ft. (Rec. N.70°W., 3.3 ft.)
24" Cedar N.85°E., 27.0 ft. scribe visible. (Rec. 23.1 ft.)
16" Cedar S.55°E., 28.0 ft. scribe visible. (Rec. S.49°E., 27.06 ft.)
30" Fir S.75°W., 5.0 ft. stump. (Rec. S.78°W., 5.94 ft.)

213

Section Corner for Secs. 23, 24, 25 and 26

Corner Report Only

Found - 1924 Cad. brass cap
18" Fir, N.33°E., 32.3 ft. stump.
24" Fir S.5°E., 35.6 ft. Healed. (Ren. #196 calls out S.15°E with record being S.5°E.)
5/8" iron rod and alum. cap N.65°W., 33.3 ft.
24" Fir S.35°W., 21.1 ft. Healed.

3/27/90

Center 1/4 Corner for Section 9

214

Found - 1980 BLM 3 1/4 dia. brass cap on a 2 1/2" O.D. iron pipe protruding 3" above ground.
10" now 12" dia. 19" high D. fir stump with a fully healed blaze bears N.57 3/4°E., 24.4 ft. (agrees with record) 1980 BLM
6" now 10" dia. W. fir with a fully healed single blaze bears S.7 1/2°W., 27.1 ft. (agrees with record) 1980 BLM
Set - A 2 3/8" dia. brass cap on a 1 3/8" O.D. x 32" long I.P. is set East 100 ft. from BLM BC/IP. Cap stamped "Douglas County Surveyors T29S Sec 9 BO 1 West 100ft. to C 1/4 R8W 1990 Office". DCSO BC/IP protrudes 3" above ground.
New BTs - (Bearings and distances from BO 1)
3" dia. D. fir double blazed and scribed "X BT" bears S.7°W., 10.3 ft.
3" dia. D. fir double blazed and scribed "X BT" bears N.61 1/4°E., 42.3 ft.
11" dia. madrone bark scribed "BO 1 C 1/4 S9 CS BT" bears N.80 3/4°E. 144.3 ft.
12" dia. Apple, did not blaze or scribe, bears S.14°E., 57.3 ft.
BLM BC/IP and BTd to C 1/4 Corner are to be destroyed by new highway construction.

3/30/90

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
March 30, 1990
C.S. 64/6