

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 9 R. W. W. M.

✓ 1/4 CORNER BETWEEN SECTIONS 20 and 26. **SEE CORNER NO. 47 12**  
Set from remains of Original B.T.s. Set 1" x 30" Iron Pipe  
from which  
A Fir 50" dia. S. 31 1/2° W., 61.5 ft.  
A Fir 36" dia. N. 81° W., 50.0 ft.

J. F. Cole deputy  
D.D. Wolford chain  
Sept. 13, 1920

✓ CORNER TO SECTIONS 13 and 24, 18 and 19. **SEE CORNER NO. 40 13**  
Set Rock 6" x 8" x 12" from which  
A Rock 6" x 8" x 14" bears East 17 ft.  
A Rock 6" x 8" x 14" bears West 22 ft.

FB  
48 P 644

✓ N.W. CORNER OF D.I.C. 37. **SEE CORNER NO. #81 14**  
Set from Original B.T. Set a 1 1/2" x 58" Iron pipe  
for corner. **RENEWED**  
SEE ALSO 1920 NOTES (Cole)  
F.B. 48 P. 10

G. G. Stewart  
May 22, 1922  
Wit.  
W. S. Greer  
E. J. Kennedy  
Vol. 3 P. 121

✓ 1/4 CORNER BETWEEN SECTIONS 30 and 31. **SEE CORNER NO. 35 15**  
Renewed O.B.T.s marks. Set Iron pipe for corner.

✓ 1/4 SECTION CORNER SOUTH SIDE OF SECTION 36. **SEE CORNER NO. #89 16**  
Set midway between S.E. and S.W. Corners. Drove a 2"  
Flue pipe from which  
A 50" Fir bears B. 55° W., 46.5 ft.  
A 12" Fir bears N. 18° E., 40.0 ft.  
Original B.T.s could not be found, the above trees are  
new ones.

A. Boyer D.C.S.  
Wit.  
J. N. Nelson  
J. W. Priest  
Vol. 4 P. 96  
Feb. 24, 1943

✓ S.W. CORNER OF SECTION 36. **SEE CORNER NO. 65 17**  
Renewed from two stumps of original witness trees in  
sections 35 and 36 which were found, both being at top  
of cut for highway. Set a 4" x 4" post for corner from  
which the following newly scribed trees bear  
A 13" Maple N. 5° W., 34.5 ft.  
A 12" Fir S. 42° W., 2.0 ft.  
A 24" Fir N. 72° W., 34.5 ft. measurements made on slopes.

Feb. 26, 1943

1/4 SECTION CORNER BETWEEN SECTIONS 9 and 10. **NOT FD. 18**  
At the 1/4 corner between Sections 9 and 10, T 29 S, R 9 W, W.M. I  
find the cedar bearing tree N 50° 00' E 14 lks to be a snag. No  
sign of the hemlock bearing tree S 83° 00' E 15 lks.  
I mark a red cedar 30 in. in diam. 1/4 S 10 BT 1743 bearing  
S 16° 00' E 15.5 ft. distant.

J. N. Gearhart  
Witnesses  
M. S. Hubbard  
Jack Densler  
June, 1950  
C-540/253

1/4 SECTION CORNER BETWEEN SECTIONS 10 and 15. **SEE CORNER NO. 44 19**  
I find both bearing trees to be dead snags.  
I mark a hemlock 9 in. in diam. 1/4 S 15 BT 1743 bearing S 4° 00' W  
20.2 ft. distant.  
Measurements to axillary center of tree at top of root crown.

F. C. Frear  
Witness  
H. Crowder - July 10, 1951

SECTION CORNER BETWEEN SECTIONS 25-26-35-36 **20**  
Found 3" pipe as set by J. W. Cole for corner 25-26-35-36, T 29 S  
R 9 W, W.M. - **SEE REN. NO. 4**  
Scribed 24" Fir N. 68° W 18.1 ft.  
14" Fir N. 56° E. 28.2 ft.  
**SEE GOV'T. NOTES - Vol. 34 P. 14006**

1/4 CORNER BETWEEN SECTIONS 26 and 35 **REN. #9 21**  
From stump of 10" Oak N 89 W 10.2 ft. I set a 1" x 36" Bo 1t 30"  
in ground. Marked two (2) new trees  
A 10" Fir N 7° 30' W 77.9 ft.  
A 18" White Oak N 59° 30' W 123.0 ft.  
**SEE CORNER NO. 28**

H. E. Cregger  
Witness John Stanley  
Wally M. Harkon Sen,  
Dec. 11 - 51  
C-544/41

Marked 1/4 Sec. T 29 S R 9 W Sec. 26