

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 9 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Secs. 13 & 24, T29S R9W, & Secs. 18, 19, T29S R8W. #92  
Found - Offset STONES as recorded by Cole, 1920 (REN. #13)  
6"x 8"x 14" East 17 ft. & 6"x 8"x 14" West 22.0 ft. 40  
Both Stones now covered. Did not search for Cor. Stone.  
Set Brass Cap alongside Stone to West. Mk. Brass Cap Wit. Cor.  
22.0 ft. East to S13 S18 T29S County Surveyor's Office,  
R9W S21 S19 R8W 1958  
New BT's: 16" Oak bears S.43 $\frac{1}{2}$ °E. 320.2 ft. scribed T29S R8W S19 CS BT.  
No suitable Trees near to S.W., N.W. or N.E.

James W. Byron, Deputy  
Milo Godfrey  
S. A. Blilow  
Sept. 1958  
C. S. File No. 49/100

$\frac{1}{4}$  Section Corner to Sec. 12, T29S R9W, & Sec. 7, T29S R8W. 41  
Found - 20", now 30" Fir Stump S.65°W. 71.5 ft., shows scribing "C".  
24", now 30" Fir Stump S.20°E. shows scribing "T".  
I do not find Rifle Barrel Set for Corner, 1922.  
Set  $\frac{3}{4}$ " Iron Rod at Corner & 3" Under Road Surface.  
New BT's: 15" Cedar bears S.32°E. 68.3 ft. scribed  $\frac{1}{4}$ " S7 CS BT.  
8" R.Fir bears S.72°W. 63.0 ft. scribed  $\frac{1}{4}$ " S12 CS BT.

Section Corner to Section 3, 4, 9 and 10. 42  
Found - All Original BT's:  
Orig. 90", now 90" Fir N.45°W. 4.0 ft., shows good  
original bark scribing & more recent bark scribing.  
Orig. 70", now 72" Fir S.25°E. 31.7 ft., shows good  
bark scribing.  
Orig. 8", now 14" Hemlock bears N.80°E. 19.1 ft., shows  
good scar.  
Orig. 10" Cedar, now 14", shows good scribing on old face.  
Set Brass Cap at Corner Marked:

Douglas Co. Surveyor's Office 1959	S 4	S 3
	S 9	S 10
T29S R9W		

FD 1996 RLM  
SEE GIS FILE

New BT's: 14" Hemlock bears N.87°W. 42.2 ft. scribed S 4 T29S R9W DCS BT.  
6" Hemlock bears S.53°E. 43.0 ft. scribed S10 T29S R9W DCS BT.

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
August 17, 1959  
C. S. File No. 49/100

Section Corner to Sections 15, 16, 21 and 22. 43  
Found - Orig. Corner Tree, now down & mostly rotted, Shows  
scribe marks "S".  
Orig. 38", now 40" Hemlock Snag, shows good scribing,  
"T29S R9W S21 BT" S.38°W. 27.7 ft.  
Orig. 50", now 50" Fir Snag N.43°W. 20 ft., record  
N.43°W. 26.4 ft., shows good scribing, "T29S".  
No trace of Original N.E. or S.E. BT's. found.  
Set Brass Cap at Corner Mkd: Doug. County Surveyor's Office, 1959  
Coos S16 S15 Doug. T29S R9W  
Co. S21 S22 Co.  
New BT's: 10" R.Fir bears S.63°W. 9.8 ft. scribed S21 T29S R9W DCS BT.  
11" R.Fir bears S.15°E. 16.5 ft. scribed S22 T29S R9W DCS BT.  
11" R.Fir bears N.38°W. 41.5 ft. scribed S16 T29S R9W DCS BT.  
10" R.Fir bears N.68°E. 44.2 ft. scribed S15 T29S R9W DCS BT.

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
September 1, 1959  
C. S. File No. 49/100

South  $\frac{1}{4}$  Corner of Section 10. 44  
Found - 9", now 9" Dead Hemlock S.4°W. 20.2 ft., scribing visible,  
" $\frac{1}{4}$ " S15 BT". This is BT. recorded by Gearhart, 1950 (REN. #19)  
I do not find Original BT's. Corner checks call West  
to Creek O. K.  
Set Brass Cap at Corner Mkd: South  $\frac{1}{4}$  S10 T29S R9W County  
Surveyor's Office, 1959.  
Note - Corner is under 30" Fir Log.  
New BT's: 60" Cedar Snag N.60°W. 55.5 ft. scribed S $\frac{1}{4}$  S10 CS BT.  
16" Hemlock bears N.72°E. 58.9 ft. scribed  $\frac{1}{4}$  S10 CS BT.