

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

9

R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 91881

51

$\frac{1}{4}$ Section Corner to Sections 14 and 23.

Found - Orig. 18", now 40" W. Oak S.45°W. 105.0 ft., (record 101.0 ft.), shows old face, now rotted, no scribing found.

Orig. 12"; now 14" Oak, down. ~~Opened & found good~~
scribing "BT". N.50°W. 33.0 ft.

Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S14 T29S R9W County
S23 Surveyor's Office, 1959
New BT's: 12" D. Fir bears N.27°E. 47.9 ft. scribed $\frac{1}{4}$ S14 CS BT.
17" R. Fir bears S.31°W. 4.8 ft. scribed $\frac{1}{4}$ S23 CS BT.

RE-RENEWED, SEE CORNER NO. #83

52

Section Corner to Sections 14, 15, 22 and 23.

Found - Fir, now 24", had been opened previously & scribe marks "S R9W S15 BT" plainly visible. This tree bears N.65°W. 17.2 ft. from corner.

Old uprooted Snag, 24" diam., S. 6°W. 5.9 ft., chopped open & found portion of scribe marks, illegible.

Rotted Fir Snag, 9" diam., S.70°E. 25.1 ft. (Porter calls for 8" Fir S.70°W. 25.1 ft. - wrong quadrant?) showing scribe "T29S R9W S23 BT", face had never grown over.

No trace of any other B.T.'s could be found.

At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1959

S15	S14	T29S R9W
S22	S23	

Blaze & Scribe following new Trees:

- 18" D. Fir S.60°W. 26.5 ft. mkd. "T29S R9W S22 CS BT."
- 15" D. Fir N. 2°E. 10.8 ft. mkd. "T29S R9W S14 CS BT".
- 15" Incense Cedar S.47°E. 43.2 ft. mkd. "T29S R9W S23 CS BT".

James W. Byron, Deputy
Milo E. Godfrey
Clete Putnam
September, 1959
C. S. File No. 49/100

53

Section Corner to Sections 22, 23, 26 and 27.

Found - 12", now 30" W. Fir N.50°E. 17.8 ft., shows good scars. I do not open.

Orig. 10", now 20" Fir S.50°E. 34.3 ft., previously opened, shows good scribing.

Orig. 12", now down 24" Fir N.50°W. 23.8 ft., shows scribing on old face.

No trace of S. W. BT. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S22	S23	T29S R9W
S27	S26	

- New BT's: 12" W. Fir bears S.67°E. 33.8 ft. scribed S23 T29S R9W CS BT.
- 12" Hemlock " N.32°W. 32.2 ft. scribed S22 T29S R9W CS BT.
- 26" R. Fir bears S.31 $\frac{1}{2}$ °W. 28.0 ft. scribed S27 T29S R9W CS BT.

FD. 1980-Blm
ADMIN SURVY
SEE GIS FILE

54

$\frac{1}{4}$ Section Corner to Sections 22 and 27.

Found - Stone at Corner as recorded by Porter & Both Orig. BT's.

Orig. 12", now 20" Fir Stump N.22°W. 9.0 ft., shows good scar. I do not open.

Orig. 12", now 26" Fir S.44°E. 8.6 ft., shows good scribing " $\frac{1}{4}$ ".

Set Brass Cap alongside Corner Stone & Mark $\frac{1}{4}$ S22 T29S R9W
County Surveyor's Office, 1959 S27

New BT's: 16" R. Fir N.22°W. 41.4 ft. scribed $\frac{1}{4}$ S22 CS BT.

RE-RENEWED, SEE CORNER NO. 78

55

$\frac{1}{4}$ Section Corner to Sections 12 and 13.

Found - Fir Stump, now 45", S.38°W. 13.2 ft. Chopped lower scar open & found scribe marks. Ring count proves this to be Original B.T.

Dead Fir, now 25", N.40°E., bark scribing " $\frac{1}{4}$ S", plainly visible. This tree also shows good lower scar.

Note - Line Notes, including BT's. for $\frac{1}{4}$ corner are recorded as line between Secs. 13 & 24 in Co. Surveyor's copy of Gov't Field Notes.

At Corner Set Iron Pipe with Brass Cap mkd: County Surveyor's
T29S R9W $\frac{1}{4}$ S12 Office, 1959
S13

(continued next page)