

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

82

North $\frac{1}{4}$ Corner for Section 1.

Found - 1959 GLO Brass cap buried approx 2 ft. under cut of old cat rd. mkd.
"T28S R9W S36 T29S S1 $\frac{1}{4}$ 1959".

A 1" I.P. 1 ft. above ground.

A 9" now 15" White Fir, bears N.29 $3\frac{1}{4}$ °W., well healed.

Found no trace of S.E. BT.

Note: Placed sign post 3 ft. east of corner.

New BT - A 7" White Fir, bears S.6°E., 24.3 ft. scribed " $\frac{1}{4}$ S1 CS BT" in
double blaze. (No larger trees to the south)

Note: Corner lies approx. 1000 ft. north of Lang Cr. Rd. in trees above
second large clear cut.

Declination: 20° East.

5/13/76

M. Lenora Ladig
Karen Cheney
Doug. Co. Surveyor's
Office
May 13, 1976
C.S. 59/15

1/4 Corner for Secs. 14 and 23

Found - 1959 County Surveyor's brass cap properly marked, laying on
ground, pulled out by cat. Ren. # 51

A 18" now 22" Fir, N.27°E., 47.9 ft. Tree is alive with
healed blaze.

A 14" Fir, S.8°W., 114.2 ft. with healed blaze. 1966 GLO notes

Reset - At true corner point: The DCSO Brass cap 2" above ground.
Added "DCSO 1976" to East side of cap.

Note: Corner lies in old cat road. Compass declination 20° East.

7/28/76

East 1/16 Corner for Secs. 14 and 23.

Found - A 13" W. Fir, N.60°E., 27.1 ft. Tree is dead with healed blaze.

A 11" now 13" W. Fir, S.11 $1\frac{1}{2}$ °W., 23.8 ft. Tree is alive with
healed blaze.

Found no trace of GLO Brass Cap. 1966 GLO Dependent Resurvey
(Pulled out by cat)

Set - At true corner point: A 1" x 36" I. Pipe with Brass cap stamped:
"Douglas Co. Surveyor
T 29 S R 9 W

E 1/16 $\frac{S 14}{S 23}$
1976

New BT - A 10" Fir, bears N.71°E., 78.3 ft. scribed "E 1/16 S14 CS BT"
in double blaze.

Compass declination 20° East.

7/28/76

SE corner for Sec. 24.

Set - 1/2" x 10" R.R. Spike in black top. Set 5/8" x 42" I. R. at
right angles to section line. See also Ren. #24

FD OK PER B. ROGERS
12/89 SEE 1350-0004

1/4 Corner for section 24, East side.

Did not dig up Co. Road but found witness corners and witness tree as
shown on C.S. M 61 - 2. See Ren. #23.

Set - 1/2" R.R. Spike in black top.

7-8/76

NW Corner D.L.C. #37

Found - 1 1/4" I. P. (See Vol. 3 Pg. 70) Ren. #14

Ash, S.60°E., 160.38 ft. identified by O. Standly. (See C.S. 32/13)

New BT - 15" W. Oak, N.32°E., 233.4 ft. scribed "NW Cor Cl. 37 T29S R9W"

10/76

Center 1/4 Corner for Sec. 36

Set - 5/8" Iron rod

BT's - 18" Madrone bears S.88°E., 17.7 ft. tagged.

18" W.F. bears N.04 $1\frac{1}{4}$ °E., 27.2 ft. tagged

Set - 4 foot fence posts, 1 south 3 feet and 1 east 3 feet.

2/77

FD OK PER PIESKE
JAN. 1986
M 101-13

83

M. Lenora Ladig, Do. Co. Surveyors Office
Jim H. Cook
July 28, 1976
C. S. 59/18

84

85

Herbert Northcraft
For: James Atteberry
July-Aug. 1976
M 61 - 18

86

87

H. Northcraft
For: Eugene Banks
Oct. 1976
M 61 - 80

88

Ronald E. Stuntzner
For: Dr. & Mrs.
Keizer
Feb. 1977
M 63 - 61