

Douglas County Surveyor's Record of
Government Corners Renewed

30

T. S.

1

R. W. W. M.

RE-RENEWED CORNER NO. # 161 10
 $\frac{1}{4}$ Corner 32/33, as det. by O.B.T.:
 30" Cedar S.5°W. 7.9 ft. O.B.T., fd. scribe.
 At Corner Point Set 2" x 36" Truck Axle with flange up, from which:
 6" Cedar S.51°E. 22.6 ft. $\frac{1}{4}$ S33 B.T.
 16" Ia. East 38.0 ft. mkd. $\frac{1}{4}$ S33 B.T.
 5" W.Fir N.55°E. 39.0 ft. $\frac{1}{4}$ S33 B.T.
 50" Fir N. 8°W. 47.4 ft. $\frac{1}{4}$ S32 B.T. FOUND. OK. 2-6-68 J.M.P. MARKHAM C.S. 54/59

C.S. File
No.
51/121

S. E. Corner Section 32. T.31 S., R. 1 W.
 as determined by O. B. T.'s:
~~30" W. Fir bears N.88°W. 37.6 ft. O.B.T., fd. scribe & remarked S32 B.T.
 16" W.Fir bears S.86°W. 39.6 ft. O.B.T.
 24" Fir Stump(logged) N.90°E. 27.8 ft. O.B.T. WRONG. TWP.
 At Corner Point Set 1" x 36" Iron Pipe from which: + RANGE
 5" Fir bears S.39°W. 15.5 ft. dist. mkd. S5 RLW B.T.
 5" Fir bears N.42°W. 20.7 ft. dist. mkd. S32 B.T.
 A Fence bears North and also West from Corner.
 Road bears North 355.0 ft.~~

Jan. 18,
1961,
C.S. File
51/142

RE-RENEWED CORNER NO. # 208 11
 Section Corner to Sections 29-30-31-32.
 as determined by O. B. T.:
 20" Fir Snag N.46°W. 19.8 ft. dist. O.B.T. I chopped
 out & found scribe.
 25" Fir Snag N.47°E. 16.2 ft. O.B.T.
 At Corner Point Set 1" x 36" Iron Pipe from which:
 14" W. Fir bears S.29°W. 8.7 ft. dist. mkd. X S31 X B.T.
 24" Fir bears S. 6°W. 38.0 ft. dist. mkd. S31 RLW B.T.
 32" W.Fir bears N.55°E. 31.7 ft. mkd. S29 B.T.
 14" Fir bears N. 8°W. 96.0 ft. dist. mkd. S30 B. T.
 Road bears North 230.0 ft. distant. MARKHAM

Jan. 18,
1961
C.S. File
No. 51/121

RE-RENEWED CORNER NO. # 165 12
 $\frac{1}{4}$ Corner to Sections 22 and 27.
 As determined by Old Bearing Trees:
 13" W.O. uproot bears S.18°W. 41.0 ft. O.B.T.
 10" W.O. Snag bears N.68°E. 21.8 ft. O.B.T.
 At Corner Point Set 1" x 30" Truck Axle with flange up, from which:
 5" Fir S.33°E. 24.0 ft. Mkd: $\frac{1}{4}$ S27 B.T.
 5" Fir S.34°W. 22.5 ft. Mkd: $\frac{1}{4}$ S XX BT.
 13" Cedar N.79°W. 51.8 ft. Mkd: $\frac{1}{4}$ S22 B.T.
 8" W.O. N.56°W. 47.0 ft. Mkd: $\frac{1}{4}$ S22 B.T.
 Rock road bears S.45°W. 185.0 ft. distance.

John H. Markham, Jr.
For Stomar Lumber Co.
Oct. 22, 1962
C.S. File No. 51/121

Center of Section 28 --- Set post 13
 Pine 20 " in diameter bears N. 78° W 72 lks.
 B. Oak 15" in diameter bears N. 67° E 140 lks.

W.F. Briggs, Co. Sur
Mar 13, 1889.
Rec. Vol 1, p 130

Center of Section 32 14
 Set corner by marking:
 a Fir tree 8" in diameter, on four sides $\frac{1}{4}$ S., gave sight
 line East.

W.F. Briggs
3-13-1889
Rec. Vol 1, page 130

15
 $\frac{1}{4}$ Corner to Sec. 31, T30-1W. & Sec. 6, T31-1W.
 Found - 6" Cedar Corner Tree, down.
 12" Fir, now snag, S. 35° W. 5.9 ft., opened for scribing "B".
 12" Fir, now stump, burnt off at ground, N. 75° E. 9.9 ft.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R $\frac{1}{4}$ S 31
 Office, 1966 T31S 1 $\frac{1}{4}$ S 6
 W
 New BT's:
 5" Fir N. 32 $\frac{1}{2}$ ° E. 13.4 ft. scribed $\frac{1}{4}$ S31 CS BT.
 4" Fir S. 87° E. 48.8 ft. scribed $\frac{1}{4}$ CS BT.
 (No larger trees available)
 Logging Road bears West 100.0 ft.

John K. Powell
Frank Jones & Joe Brady
June 6, 1966
C. S. File No. 54/28

June 6, 1966