

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

21

$\frac{1}{4}$ Corner to Sections 33 and 34.
Found - 15" S. Pine, now windfall, S. 10° W. 28.4 ft., opened for scribe "S".
No trace of N. E. Bearing Tree.
Chained in call on creek, hit edge of same 53.0 ft. (Record 52.8')
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's T 30 S R 1 W
Office, 1967 $\frac{1}{4}$ S 33 | S 34
New BT's: 12" Cedar N. 84° E. 16.4 ft. mkd. $\frac{1}{4}$ S34 CS BT.
10" Fir N. 77° W. 19.0 ft. mkd. $\frac{1}{4}$ S33 CS BT.

22

$\frac{1}{4}$ Corner to Sections 27 and 28.
Found - Orig. 30", now 36" D. Fir, N. 70° E. 10.6 ft., opened for scribe "BT".
No trace of S. W. Bearing Tree.
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's T 30 S R 1 W
Office, 1967 $\frac{1}{4}$ S 28 | S 27
New BT's: 18" Cedar S. 30° W. 28.0 ft. mkd. $\frac{1}{4}$ S28 CS BT.
19" Laurel N. 11° E. 20.0 ft. mkd. $\frac{1}{4}$ S27 CS BT.

23

Section Corner to Secs. 4 & 5, T30-1W. and Secs. 32 & 33, T29-1W.
Found - 20 x 12 x 10 Stone mkd: 4 notches on W. - 2 notches on E. side.
Orig. 8", now 9" W. Oak, N. 38° E. 47.5 ft., opened for scribe.
Orig. 12" D. Fir, now down, S. 28° W. 17.8 ft., opened for scribe.
Orig. 20", now 24" D. Fir, S. 55° E. 5.3 ft., shows good scar.
Orig. 10", not 15" D. Fir, N. 81° W. 35.0 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 1 W
Office 1967

S 32	S 33
S 5	S 4

T 30 S
New BT's: 16" D. Fir S. 62° W. 41.4 ft. mkd: T30S R1W S5 CS BT.
8" S. Fir N. 16° E. 29.6 ft. mkd: T29S R1W S33 CS BT.

24

Corner to Sections 33 and 34 only, T30S-R1W.
Found - G.L.O. Brass Cap, properly marked in 1923.
38" D. Fir, now dead, N. 59° W. 21.8 ft., scribe visible, "T30 RW BT".
30" D. Fir, now down, S. 35° E. 11.9 ft.
40" D. Fir, now stump, N. 72° E. 58.7 ft.
No trace of S.W. BT.
New BT's: 5" S. Fir N. 21° W. 6.8 ft. mkd. T30S R1W S33 CS BT.
12" S. Fir N. 24° E. 21.5 ft. mkd. T30S R1W S34 CS BT.
Note - This corner lies approximately 25.2 ft. west of creek.

25

E. $\frac{1}{4}$ Corner to Section 23 only.
Found - G.L.O. Brass Cap at $\frac{1}{4}$ Corner properly marked in 1923.
No trace of stone mound.
24", now 29" Cedar, S. 1° W. 153.4 ft., scribe visible "4".
New BT: 12" Laurel N. 22° W. 7.0 ft. mkd. $\frac{1}{4}$ S23 CS BT.
Note - This corner lies 226.7 ft. north of $\frac{1}{4}$ corner to Sec. 24 only
which was found in good condition.

26

Section Corner to Sections 23 and 26 only.
Found - G.L.O. Brass Cap at Sec. Cor. properly marked in 1923.
24", now 32" D. Fir, S. 3 $\frac{1}{2}$ ° W. 86.5 ft., shows good scar.
6", now 19" Cedar, N. 52° W. 73.3 ft., nothing visible.
As trees are far away and one south of other corner, I mark new BT's:
2" Cedar N. 23° W. 8.7 ft. mkd. T30S R1W S23 CS BT.
6" D. Fir S. 20° W. 4.3 ft. mkd. T30S R1W S26 CS BT.
Note - This corner lies 59.4 ft. north of section corner to
sections 24 and 25 only, which was found in good condition.

Jan. 2, 1968

John M. Powell
Frank Jones & W. Penley
December, 1967
C. S. File No. 54/59

RENEWED CORNER NO. #201