

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

39

Sec. Cor. to Secs. 1 & 12 only, T30-2W.
Found - Stone at section corner.
18", now 25" D.Fir, S.24°W. 19.8 ft., shows good scar.
16", now 22" Double D.Fir, N.55°W. 25.1 ft., shows good scar.
Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
Office 2 S 1 S 7 1
1968 W S 12 S 7 W.

Old Bearing Trees in good condition, tagged same.
Note - This corner lies 50.8 ft. south of sec. cor. to Secs. 6 & 7, T30-1W.

40

Sec. Cor. to Secs. 6 & 7 only, T30-1W.
Found - Stone at Section Corner.
30", now 39" D.Fir, S.80°E. 66.0 ft., bark scribe visible.
N.E. BT., down & rotten.

Set - Brass Cap at Sec.Cor.Mkd: County Surveyor's R T 30 S R
Office 2 S 1 S 6 1
1968 W S 1 S 7 W

New BT's: 9" D.Fir S.71°E. 30.4 ft. mkd. T30S RLW S2 CS BT.
14" Cedar N.66°E. 35.1 ft. mkd. T30S RLW S6 CS BT.
Note - This corner lies 50.8 ft. north of Sec. Cor. to 1 & 12, T30-2W.

41

Sec. Cor. to Section 1, T31-1W and Sec. 36, T30-1W only.
Found - Corner Stone, no marks.
30" D.Fir, now 40" Stump, S.30°W. 16.5 ft., opened & found scribe.
26" D.Fir, now 28" Snag, N. 2° W. 16.5 ft., opened & found scribe.

Set - Brass Cap at Sec.Cor.Mkd: County Surveyor's R T 30 S R
Office 1 S 36 S31 1
1968 W S 1 S31 E
T 31 S

New BT's:
6" Cedar S.60°W. 10.4 ft. scribed T31S RLW S1 CS BT.
36" D.Fir N.18°W. 15.2 ft. scribed T30S RLW S36CS BT.
Note - $\frac{1}{4}$ Cor. to Sec. 31 only is O.K. & lies north 236.3 ft., both corners on steep west slope.

42

Sec. Cor. to Sections 25 and 36 only, T30-1W.
Found - 18", now 22" D.Fir, S.64°W. 21.1 ft., scribe visible, "36".
18", now 22" D.Fir, N,10°W. 25.7 ft.(Rec.27.7'), shows good scar.
Old Mound of Stones at corner, no marks found.

Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
Office 1 S 25 S30 1
1968 W S 36 S30 E

Old bearing trees in good condition, tagged same.
Note - This corner lies 236.3 ft. south of $\frac{1}{4}$ cor. to Sec.30 only (O.K.).

43

$\frac{1}{4}$ Corner to Section 36 only, T30-1W.
Found - 36", now 39" D.Fir, N.28°W.(Rec.N.23°W.) 17.2 ft., shows good scar.
20" D.Fir, now down, S.75°W. 9.2 ft., scribe visible, " $\frac{1}{4}$ S36 BT".

Set - Brass Cap at $\frac{1}{4}$ Cor.Mkd: County Surveyor's R T 30 S R
Office 1 $\frac{1}{4}$ S 36 1
1968 W S 36 S30 E

New BT's: 26" D.Fir S.32°W. 29.5 ft., scribed $\frac{1}{4}$ S36 CS BT.
36" D.Fir N.28°W. 17.2 ft., tree O.K., new bearing.
Note - This corner lies 236.3 ft. south of Cor. to Secs.30& 31, T30-1E.(below)

44

Sec. Cor. to Sections 30 and 31 only, T30-1E.
Found - Brass Cap(1923 GLO Brass Cap) pulled out of ground by other blow-down.
18" D.Fir, blow-down, S.20°E. 8.6 ft., opened & found scribe.
34", now 38" D.Fir, N.44°E. 16.5 ft.(this dist. must be slope dist. to match bearings & other distances.)

Reset - 1923 GLO Brass Cap at Section Corner.
New BT: D.Fir S.87°E. 30.5 ft. mkd. T30S R1E S31 CS BT.
Note - This corner lies 236.3 ft. north $\frac{1}{4}$ cor.Sec. 36 only, T30-1W.(above).

Feb. 7/193 HAINES
FOR BLN. - SEE GDS
FILE.

John M. Powell
Frank Jones & W. Penley
January, 1968
C. S. File No. 54/59