

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell  
Frank Jones & W. Penley  
January - February, 1968  
C. S. File No. 54/59

51  
 $\frac{1}{4}$  Corner to Section 25 only. (WEST)  
 Found - 1923 G.L.O. Brass Cap at  $\frac{1}{4}$  Cor. Mkd. properly.  
 14" R.Fir, now stob, S.78°E. 31.0 ft., scribe visible " $\frac{1}{4}$ S25 BT".  
 No trace of N.E. Bearing Tree.  
 New BT's: 36" Fir N.31 $\frac{1}{2}$ °E. 40.8 ft. mkd.  $\frac{1}{4}$  S25 CS BT.  
 12" Fir S. 7° E. 4.9 ft. mkd.  $\frac{1}{4}$  S25 CS BT.  
 Note - This corner lies 61.4 ft. south of section 26 only which is O.K.

52  
 $\frac{1}{4}$  Corner to Section 26 only. (EAST)  
 Found - 1923 G.L.O. Brass Cap, properly marked at  $\frac{1}{4}$  corner.  
 42" D.Fir, now 42", S.78°W. 16.5 ft., shows good scar.  
 16", now 17" Cedar N.11°W. 20.5 ft., scribe visible, tree being smothered, not in good condition.  
 New BT: 15" Fir N.10°W. 37.7 ft. mkd.  $\frac{1}{4}$  S26 CS BT.  
 Note - This corner lies 61.4 ft. north of  $\frac{1}{4}$  S25 only, Ren. #51.

53  
 Sec. Cor. to Sections 19 & 30 only, T30-1E.  
 Found - 1923 G.L.O. Brass Cap at sec. cor., properly marked.  
 14" D.Fir, now stump, S.68°E. 24.4 ft., opened for scribe, " $\frac{1}{4}$ S30BT".  
 No trace of N.E. Bearing Tree.  
 No trees in area, cut unit:  
 24" D.Fir Stump S.81 $\frac{1}{2}$ °E. 23.0 ft., drove  $\frac{3}{4}$ " I.Rod in center of stump.  
 20" D.Fir Stump N.21 $\frac{1}{2}$ °E. 20.2 ft., drove  $\frac{3}{4}$ " I.Rod in center of stump.  
 Note - This corner lies 236.3 ft. north of  $\frac{1}{4}$  Sec. 25 only, Ren. #54.  
 Lies approx. 100 ft. south & 70 ft. W. of logging road above high cut bank.

54  
 $\frac{1}{4}$  Corner to Section 25 only, T30-1W.  
 Found - No trace of Stone at  $\frac{1}{4}$  corner.  
 30", now 38" D.Fir, S.17°W. 23.1 ft., opened for scribe "BT".  
 34", now 39" D.Fir, N.80°W. 21.8 ft., shows good scar.  
 Set - Brass Cap at Cor. Mkd: County Surveyor's R T 30 S R  
 Office 1 S 25  $\frac{1}{4}$  1  
 1968 W S 25  $\frac{1}{4}$  E  
 Bearing Trees O.K., tagged same.  
 Note - This corner lies approx. 340 ft. S. of logging road and 236.3 ft. south of Cor. 19 & 30 only, Ren. #53, above.

55  
 North  $\frac{1}{4}$  Corner to Section 2 only, T30-1W.  
 Found - Unrecorded 1967 aluminum cap mkd: USPC Prod.Corp, See M 36 - 14.  
 No trace of N.E. BT. T30S R1W  $\frac{1}{4}$   
 18" D.Fir, now stump, S.19°E. 1967 S 2 #236  
 42.2 ft., open for scribe. #287  
 Stone, firmly set at  $\frac{1}{4}$  cor. mkd:  $\frac{1}{4}$  on south face.  
 New BT's: 7" R.Fir S.47°W. 14.7 ft. mkd.  $\frac{1}{4}$  S2 CS BT.  
 9" D.Fir S.11 $\frac{1}{2}$ °W. 21.3 ft. mkd.  $\frac{1}{4}$  S2 CS BT.  
 Note - This corner lies approx. 50 ft. N. of logging road.

56  
 Sec. Corner to Secs. 32 & 33, T30-1W. & Secs. 4 & 5, T31-1W.  
 Found - GLO Brass Cap at cor., properly marked in 1923.  
 15" D.Fir, now 28", S.88°W. 9.2 ft., shows good scar.  
 20" D.Fir, now 34", N.40°E. 9.9 ft., shows good scar.  
 18" Pine, now stump, N.84°W. 38.3 ft.  
 New BT: 12" D.Fir N.59°W. 36.3 ft. mkd. T30S R1W S32 CS BT.  
 Note - This corner lies approx. 65.0 ft. south of Spring Branch.

57  
 $\frac{1}{4}$  Corner to Sec. 32, T30-1W. and Sec. 5, T31-1W.  
 Found - 50" S.Pine, now 50", S.87°E. 115.5 ft., scribe visible " $\frac{1}{4}$ S".  
 No trace of N.W. BT., falls in old skid road.  
 Set - Brass Cap at  $\frac{1}{4}$  Cor.Mkd: County Surveyor's T 30 S R 1 W  
 Office  $\frac{1}{4}$  S 32  
 1968 S 5  
 New BT's: 14" D.Fir N.57°E. 23.6 ft. mkd.  $\frac{1}{4}$  S32 CS BT.  
 15" D.Fir S.22°E. 35.2 ft. mkd.  $\frac{1}{4}$  S5 CS BT.