

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Township Corner

Section Corner to Sections 31 T29-1E & Sec. 6, T30-1E.

64

Found - 24" D.Fir, now down, S.49°E. 12.5 ft.
10" Cedar, now 13", N.61°E. 7.9 ft., opnd. for scribe "BT".
Stone at Township Corner, No Marks.

Set - Brass Cap at Sec.Cor.Mkd: County Surveyor's Office 1968

R	S	T 29 S	R
1	1	S 31	1
W	1	S 6	1
		T 30 S	E

New BT's: 15" Fir N.27°E. 12.3 ft. mkd. T29S R1E S31 CS BT
31" D.Fir S.58°E. 29.0 ft. mkd. T30S R1E S6 CS BT.
12" D.Fir S.76°W. 16.4 ft. mkd. T30S R1W S 1 CS BT.

1/4 Corner Section 1 only, T30-1W.

65

Found - 40" D.Fir, now stump, N.66°W. 28.4 ft., opened for scribe "1/4".
24" D.Fir, now stump, S.51°W.(Rec.S.30°W) 35.6 ft.
Using 1 bearing & 2 distances, I renew: No Corner Stone Found.

Set - Brass Cap at 1/4 Cor.Mkd: County Surveyor's Office 1968

R	1/4	S 1	R
1	1	S 1	1
W	1	T 30 S	E

New BT's: 22" Cedar S.57°W. 42.0 ft. mkd. 1/4 S1 CS BT.
15" Laurel N.40°W. 34.2 ft. mkd. 1/4 S1 CS BT.

Note - This corner lies in old skid road, running N-S,
Township Corner, see above., 266.4 ft. south.

Section Corner to Sections 10 - 11 - 14 - 15.

66

Found -24", now 36" B.Oak, N.12°E. 102.3 ft., shows good scars.
15" B.Oak, now dead, S.82°E. 94.4 ft., shows good scar.
12",now 18" W.Oak, N.85°W. 149.5 ft.(Rec.144.5), scribe marks
visible but not legible. Tree rotten.
No trace of 18" Fir, S. W.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1968

T 30 S	R 1 W
S 10	S 11
S 15	S 14

New BT's: 8" D.Fir N.35°W. 11.8 ft. mkd. T30S R1W S10 CS BT.
6" B.Oak S.55°E. 15.6 ft. mkd. T30S R1W S14 CS BT.
24" D.Fir S.56°W. 86.7 ft. mkd. T30S R1W S15 CS BT.

1/4 Corner to Sections 3 and 10.

67

Found - No trace of Corner Stone.
14",now 20" Maple, N.56°W. 43.6 ft., scribe visible "BT",rotten face.
9",now 9" Yew, S.59°W. 4.0 ft., scribe visible "1/4S".

Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1968

T 30 S	R 1 W
S 3	S 10

New BT's: 6" Hemlock S. 86° E. 11.0 ft. mkd. 1/4 S10 CS BT.
8" Hemlock N. 1° E. 16.3 ft. mkd. 1/4 S 3 CS BT.

Section Corner to Sections 9 - 10 - 15 - 16.

68

Found - Frank Cain's 1920 Renewal No. 1.
36",now 42" Pine, S.40°E. 33.7 ft., shows scribe "R".
10",now 18" Fir, N.89 1/2°E. 38.9 ft., shows face.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1968

T 30 S	R 1 W
S 9	S 10
S 16	S 15

Rescribed: 42" Pine S.40°E. 33.7 ft. mkd. T30S R1W S15 CS BT.
New BT's: 12" Y.Pine S.59°W. 24.6 ft. mkd.T30S R1W S16 CS BT.
12" S.Pine N.59°W. 36.4 ft. mkd. T30S R1W S9 CS BT.

Note - This corner lies in N. & S. Fence Line.

1/4 Corner to Sections 9 and 10.

69

Found - Corner Stone 12x8x6 with "1/4" on west side.
20",now 28" R.Fir, S.76°E. 14.0 ft. with good face.
40"R.Fir, now 42" Snag, west 13.2 ft., shows good bark scribing.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968

T 30 S	R 1 W
1/4	S 9/S 10

New BT: 30" R.Fir N.42 1/2°W. 14.1 ft. mkd. 1/4 S 9 CS BT.

Note - This corner lies on flat ground.

John M. Powell
Frank Jones & W. Penley
February, 1968
C. S. File No. 54/59

RE-RENEWED, SEE CORNER NO. #227

RE-RENEWED, SEE CORNER NO. 121

FOOK Shorer 7/1999
CS 65/23-15 M132-9

RE-RENEWED, SEE CORNER NO. #185