

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 1 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$ Corner to Section 7 and 8. # 235 76
 Found - 12", now 20" Hemlock N. 49° E. 11.9 ft., partly opened, opened
 more to confirm scribing "S".
 No trace of corner stone or S.W. BT. Corner lies in old logged area.
 Set - Brass Cap at Cor.Mkd: County Surveyor's T 30 S R 1 W
 Office, 1968 $\frac{1}{4}$ S 7 | S 8
 New BT's: 20" Hemlock N. 18° W. 22.3 ft. mkd. $\frac{1}{4}$ S 7 CS BT.
 22" Hemlock S. 28° E. 40.1 ft. mkd. $\frac{1}{4}$ S 8 CS BT.

$\frac{1}{4}$ Corner to Sections 5 and 8. 77
 Found - Possible Corner Stone, no legible marks.
 40", now 42" D.Fir, S. 8° W. 6.6 ft., opened for scribe "B".
 7", now 10" D.Fir, N.13° E. 32.0 ft., opnd., no scribing, old face.
 Set - Brass Cap at Cor.Mkd: County Surveyor's T 30 S R 1 W
 Office 1968 $\frac{1}{4}$ S 5 | S 8
 New BT's: 11" D.Fir S. 88° E. 9.4 ft. mkd: $\frac{1}{4}$ S 8 CS BT.
 12" Yew N. 80° E. 27.3 ft. mkd: $\frac{1}{4}$ S 5 CS BT.

$\frac{1}{4}$ Corner to Sections 9 and 16. 78
 Found - 40" B.Oak, rotted out, S. 22° W. 52.8 ft.
 30" W.Oak, now 29", N.62°W. 9.2 ft., shows good scar.
 14x10x8 Stone, "1" on N. face.
 Set - Brass Cap at Cor.Mkd: County Surveyor's T 30 S R 1 W
 Office 1968 $\frac{1}{4}$ S 9 | S 16
 New BT: 8" D.Fir S. 38° W. 30.0 ft. mkd. $\frac{1}{4}$ S 16 CS BT.
 Reblzd. & Rescrbd: 29" W.Oak N. 62° W. 9.2 ft. mkd. $\frac{1}{4}$ S 9 CS BT.
 Note - Corner lies 1.0 ft. W. of old N - S fence line.

$\frac{1}{4}$ Corner to Sections 4 only. 79
 Found - Stone at $\frac{1}{4}$ corner, mkd. "4".
 Orig. 14", now 22" Cedar, N. 56° W. 31.7 ft., shows good scars.
 10", now 17" Cedar, S. 43° W. 4.6 ft., shows good scar.
 Set - Brass Cap at Cor.Mkd: County Surveyor's T 30 S R 1 W
 Office 1968 $\frac{1}{4}$ S 4
 Bearing Trees O. K. and Tagged. - I do not destroy SW BT for control purposes.
 New BT: 8" Maple N.38°W. 14.3 ft. mkd. $\frac{1}{4}$ S 4 CS BT.

Closing Corner Sections 8 and 9. 80
 Found - Stone 20x12x8, firmly set, "CC" on S. & 4V on E.
 10" W. Fir, now rotten Stump S. 11° E. 24.1 ft.
 No trace of S.W. BT.
 Set - Brass Cap at Cor.Mkd: County Surveyor's T 30 S R 1 W
 Office 1968 $\frac{S}{S 8} \frac{4}{S 9}$
 New BT's: 26" Double Yew S. 64° W. 41.6 ft. mkd. T30S RLW S8 CC CS BT.
 7" Yew S. 42° E. 8.1 ft. mkd. T30S RLW S9 CC CS BT.
 Note - This corner lies 49.3 ft. East of Corner 5/4, see below.

Corner to Section 5 and 4. 81
 Found - 15x8x6 Stone, firmly set, 4 grooves on the east side.
 18", now 23" D.Fir, N. 76° E. 42.2 ft., shows good scars.
 14", now 15" Yew, N.13°W. 33.0 ft., scribe visible, "S5 BT".
 Set - Brass Cap at Cor.Mkd: County Surveyor's T 30 S R 1 W
 Office $\frac{S 5}{S 8} \frac{S 4}{S 8}$

Bearing Trees O. K. and Tagged.
 Note - This corner lies 49.3 ft. west of 8/9, see above.

$\frac{1}{4}$ Corner to Sections 5 and 4. 82
 Found - No trace of stone at corner.
 48" D.Fir, down & rotten, N.88°W. 7.9 ft., opened, found reverse scrbing.
 30" D.Fir, now snag, S.18°E. 15.2 ft., no scribing found.

(continued over)

John M. Powell
 Frank Jones & W. Penley
 June, 1968
 C. S. File No. 54/59