

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 1 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21081

Glenn S. Baughman
L.S. #536
For: U.S. Forest
Service
May 1978
M 70 - 15

Section corner for 19 and 30; and 24, 25 of T30-2. 182
Found - 1968 Brass cap properly marked set by Baughman & Ackaret.
8" Chinquapin bears S.36°W., 23.5 ft. Ren. #108
6" W. Fir bears S.23°E., 46.0 ft. down.
26" D. Fir bears N.56°E., 22.4 ft.
9" Maple bears N.20°W., 6.2 ft.
New BT - 10" D. Fir bears S.52°E., 69.4 ft. scribed "T30S R1W S30 BT".

1/4 Corner for Secs. 30; and Sec. 25 of T30-2. 183
Found - 1968 Brass cap properly marked set ny Baughman & Ackaret.
48" Cedar stump bears N.12°E., 22.5 ft. Ren. #107
No BT in SW 1/4.
New BT's- 8" D. Fir bears S.9°W., 34.2 ft. scribed 1/4 S25BT.
9" D. Fir bears N.51°E., 51.0 ft. scribed 1/4 S30 BT. 5/78

1/4 Corner for Sec. 9 only. (North) 184
Set - 2 1/2" x 30" Galv. I.P. with brass cap. 183
BT's- 10" Hemlock, S. 67 1/2° W., 21.1 ft. scribed "1/4 S9 BT"
10" Hemlock, S.46°E., 16.7 ft. scribed "1/4 S9 BT".

1/4 Corner for Secs. 9 and 10. 185
Found - 1968 Doug. Co. Brass cap. Ren. #69
30" D. Fir, N.43°W., 14.1 ft. scribing visible.
42" D. Fir snag, West 13.2 ft. (Original)
28" D. Fir stump, S.76°E., 14.9 ft. healed face. (Original)
New BT - 12" D. Fir bears N.32°W., 44.7 ft. scribed "1/4 S9 BT".

1/4 Corner for SEcs. 8 and 9. 186
Found - 1968 Doug. Co. brass cap. Ren. #83
22" Yew stump, N.52°E., 51.6 ft.
10" Hemlock (down) N.74°W., 34.6 ft. scribing visible.
12" Maple, S.52°W., 24.4 ft. rotten (original)
New BT's-12" Yew, N.57°E., 104.0 ft. "1/4 S9 BT".
30" Incense Cedar, N.8°W., 148.3 ft. "1/4 S8 BT".

Center 1/4 Corner for Sec. 9 187
Set - 2 1/2" x 30" Galy. I.P. with brass cap.
BT's- 10" W. Oak, S. 67°W., 55.2 ft. scribed "C 1/4 S9 BT"
19" P. Pine, N. 62 1/2°W., 94.4 ft. scribed "C 1/4 S9 BT". 6/16/78

1/4 Corner for Sec. 10 only. (North) 188
Set - 2 1/2" x 30" Galv. I.P. with brass cap. Ren. #241
New BT's- 17" Pacific Yew, S.50 1/2°E., 42.3 ft. scribed "1/4 S10 BT"
7" Grand Fir, S.28 1/2°W., 16.5 ft. scribed "1/4 S10 BT".
Note - Corner is 150' East of Creek, S.22 1/2°W., 15.6 ft. 7/7/78

Center 1/4 Corner for Sec. 2 189
Found - Alum. Cap #4287 S.26°50'15"W., 2.71 ft. Ren. #112
14" D. Fir, N.73°E., 11.6 ft. with visible scribing.
10" D. Fir, S.3°W., 15.1 ft. with visible scribing
Set - 2 1/2" x 30" Galv. Iron pipe with brass cap.

1/4 Corner for Secs. 1 and 2 190
Found - 8" I. Cedar, S.53°W., 10.7 ft. Ren. #118
14" D. Fir, N.52°E., 27.4 ft.
Alum. Cap R.E. 4287 N.04°09'55"W., 3.28 ft.
Set - 2 1/2" x 30" Galv. I.P. with brass cap at proportionate distance.

David K. Bateman
For: U. S. Forest Service
June 16, 1978
M 72 - 25

David K. Bateman
Timberland Services
For: U.S. Forest
Service
July 7, 1978
M 72 - 36

David K. Bateman
R.L.S. #1068
For: U.S. Forest Serv.
Aug. 31, 1978
M 73 - 24

FD. 7/16/86
R. Geisler
C.S. 63/34

RE-RENEWED, SEE CORNER NO. #231

RE-RENEWED, SEE CORNER NO. #241

RE-RENEWED, SEE CORNER NO. #232

CORRECTIONS MADE
9/15/78 PER BATEMAN'S
INSTRUCTIONS - D.R.

1978 Ren. #242 for corrected