

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30

T. S.

R 1

R. W. W. M.

FOKE-CHAPMAN CO. EUGENE, ORE. 97401

Lloyd R. Moffit LS944  
For: U.S.F.S.  
May, 1985  
C.S. 63/8

Center 1/4 corner for Section 12.  
Found - 3" bronze cap on a 2 1/2" iron pipe. Ren. #174  
10" dead fir bears N.59°W., 5.9 ft. scribe visible.  
10" fir (down) bears N.63°E., 3.0 ft. scribe visible.  
New BTs - 10" fir bears N.18°E., 28.9 ft. scribed C 1/4 S12 BT.  
11" fir bears N.86°E., 34.1 ft. scribed C 1/4 S12 BT.

228

FD. OK  
4/86  
R. GEISLER  
CS 63/34  
5/85

1/4 Corner for sections 27 and 34.  
(Original post not found)

229

Found - Iron pipe and brass cap set at proportionate position (M 69 - 4) firmly set in mound of stone. Ren. #162  
10" fir with partially healed double blaze bears N. 61 1/2° W., 80.4 ft. (Rec. N.64°W., 80.7 ft. M69-4) from the found monument.  
9" fir now an 11" D. fir with partially healed double blaze bears S.45°W., 127.9 ft. (Rec. S.42°42'W., 128.4 ft. M69-4) from the found monument.  
Also found (not noted on M69-4) original 8" diam. fir now a partially decayed fir stump approx 18" diam. 24" high. Stump has previously opened blaze with scribing visible "/4S". We open lower blaze and find scribing "BT". We count 110 growth rings from blaze to the bark of decayed stump. Record bearing and distance to original corner is N.88°W., 33.0 ft. See photos in C.S. File 62/29.

Set - At record bearing and distance from the found original BT as noted, we SET a 1" x 30" galv. iron pipe with brass cap attached marked "Douglas County Surveyor T30S 1/4 S27 S34 R 1 W 1985". Monument is set in stone mound approx 2 ft. across base and 2 ft. high.

The proportioned monument per M69-4 bears N.36 1/2°W., 22.9 ft.  
New Ties to BTs marked from M 69 - 4:  
(NW 10" fir) 10" fir with partially healed blaze bears N.56°W., 101.6 ft.  
(SW 9" W. fir) 11" D. fir with partially healed blaze bears S.55 1/2°W., 126.6 ft.

New BTs - 30" D. fir double blazed and scribed "1/4 S27 CS BT" bears N.14°W., 27.5 ft.  
8" madrone bark scribed "1/4 S34 CS BT" bears S.1 1/2°W., 28.1 ft.

9/20/85

230

Section corner for Secs. 35 and 36 only of T.29-1  
Found - 3/4" Iron pipe with 2 1/2" alum. cap exposed 14". Corner re-monumented by R.E. 4287 in 1967. Ren. #116  
New BT - Marked a 10" cedar BT which bears N.50°W., 71.9 ft. from the corner, scribed T29S RLW S35 BT.

1/4 Corner for Sections 9 and 10  
Found - 2 1/2" brass cap on 1" iron pipe exposed 16". Corner re-monumented in 1968 by County. Ren. #185  
New BT - Marked a new 8" oak BT which bears S.56°E., 97.7 ft. from the corner scribed 1/4 S10 BT.

231

Center 1/4 Corner for Section 2  
Found - 2" iron pipe with a 2 1/2" brass cap exposed 7" in small rock mound. Corner set in 1978 by L.S. 1068. Ren. #189  
New BT - Marked a 14" fir BT which bears S.15°E., 16.4 ft. from the corner scribed C 1/4 S2 BT.

232

Section corner for Sections 16, 15, 21 and 22.  
Found - A 2 1/2" brass cap on 1" Iron pipe exposed 8". Corner re-monumented in 1968 by the County. Ren. #46  
New BT - Marked a 9" Fir BT which bears N.73°E., 8.5 ft. scribed T30S RLW S15 BT.

233

Larry E. Monrean, Deputy  
Douglas County Surveyors Office  
S. J. Flause, witness  
Sept. 20, 1985  
C.S. 62/29

FD. OK 6/91  
C.S. 63/78  
FD. OK 9/92  
SHAWNER R.M. 3-76

M132-9

FDOK Shoner 7/1979  
CS 65/23-15

Lloyd R. Moffit L.S. 944  
For: U.S. Forest Service  
Dec. 1985  
C.S. 63/30

FD. OK 7/86  
R. GEISLER  
CS 63/34