

Douglas County Surveyor's Record of
Government Corners Renewed

30 T.S. 2 R. W. W. M.

Ben B. Irving Deputy County Surveyor
Witnesses
N. E. Richardson
Loren Weber
August 2, 1940.
V. 16-E. 55

SECTION CORNER SOUTH BOUNDARY OF SECTION 31 15
Rock in a mound of stone. Original bearing trees
A 6" Alder N.70 $\frac{1}{2}$ °W., 24 lks. marked visible but not legible.
A 10" Dogwood N.17°E., 35 lks. dead but scribe marks clear.
Marked new B.T.s
A 10" Hemlock bears N.33°W., 29.7 ft. marked
S.30 C.S.B.T.
A 10" Fir bears N.62°E., 41.0 ft. marked
S.30 C.S.B.T.

NOTE:
Corner on North Boundary of Section 31 as described in Government field notes and in good condition. 9-24-40

SECTION CORNER OF SECTIONS 22, 23, 26 and 27. 16
Location identified from original bearing tree
A 24" Fir S.28°E., 44 lks., chopped out, scribe marks partially legible.
A 60" Pine down and burned. Checks original bearing and distance.
Drove 1 $\frac{1}{2}$ " x 1 $\frac{1}{2}$ " x 60' angle Iron 50" in ground for corner and surrounded with a mound.
A Fir 20" diam. bears S.60°W., 19 lks. marked
T.30S., R.2W., S.27 C.S.B.T.
A Fir 8" diam. bears S.27°E., 53 lks. marked
T.30S., R.2W., S.26 C.S.B.T.
A Fir 22" diam. bears N.12°W. ← 37 lks. marked
T.30S., R.2W., S.22 C.S.B.T. S.B. N.7°W. - 24.4'
A Fir 24" diam. bears N.15°E. ← 38 lks. marked
T.30S., R.2W., S.23 C.S.B.T. S.B. N.20°E. - 25.1'

Cor. FOUND 7/59
SEE NOTE IN C.S. FILE 16/55

CORNER BETWEEN SECTIONS 22 and 27. 17
Location identified from one original B.T. scribed S.
Drove 1" x 36" Iron Pipe 36" in ground with 2" x 4" Oak Stake alongside for corner, from which
A Cedar 26" diam. bears S.25°W., 13.5 ft. marked
S.27 C.S.B.T.
A Fir 6" diam. bears North 5.7 ft. marked
S.22 C.S.B.T.

SECTION CORNER BETWEEN 22 and 23. 18
Location identified one original B.T. down and rotten but scribe marks legible. Set a Stone 4" x 7" x 16" marked X for corner, from which
Fir 16" diam. bears N.39°E., 47.3 ft. marked
S.23 C.S.B.T. OBLITERATED - REN. No. 183
Fir 16" diam. bears S.31°W., 39.0 ft. marked
S.22 C.S.B.T. SEE CORNER NO. 72

SECTION CORNER BETWEEN 13 and 24 T.30-R.2 and 18 and 19 T.30-R.1. 19
Location identified from original B.T.s a 24" Fir N.56 $\frac{1}{2}$ °E., 31 lks. partially visible and a 12" Fir S.79 $\frac{1}{2}$ °W. chopped out B.T. which is very plain. Set a stone 6" x 8" x 18" for corner, from which
Fir 20" diam. bears S.53 $\frac{1}{2}$ °E., 14.8 ft. marked T.30S.
R.1 W., S.19 C.S.B.T.
Fir 18" diam. bears S.79 $\frac{1}{2}$ °W., 19.4 ft. marked T.30S.
R.2W., S.24 C.S.B.T. Original B.T.
Fir 24" diam. bears N.56 $\frac{1}{2}$ °E., 20.0 ft. marked T.30S.
R.1W., S.18 C.S.B.T.
Fir 24" diam. bears N.62 $\frac{1}{2}$ °W., 48.2 ft. marked T.30S.
R.2W., S.13 C.S.B.T.

RENEWED SEE CORNER NO. 104